



U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



On-Scene / Vehicle to Vehicle / Front to Right Side Dynamic Science, Inc. / Case Number: DS9610 1992 Mercury Sable LS

1996

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Technical Report Documentation Page 1. Report No. 2. Government Accession No. 3. Recipient Catalog No. DS9610 4. Title and Subtitle 5. Report Date 1997 In-Depth Accident Investigation 6. Performing Organization Report No. 7. Author(s) 8. Performing Organization Report No. Dynamic Science, Inc. 9. Performing Organization name and Address 10. Work Unit No. (TRAIS) Dynamic Science, Inc. 530 College Parkway, Ste. K 11. Contract or Grant no. Annapolis, MD 21401 DTNH22-94-D-27058 12. Sponsoring Agency Name and Address 13. Type of report and period Covered [Report Month, Year] U.S. Dept. of Transportation (NRD-32) National Highway Traffic Safety Administration 14. Sponsoring Agency Code 400 7th Street, SW Washington, DC 20590 15. Suppiementai Notes This case was initiated in response to a reported collision in which the right side passenger's air bag deployment caused fatal injuries to the 7 year old right front passenger. This was conducted as an on-scene investigation. This collision occurred in the evening hours on Vehicle 1 was a 1992 Mercury Sable LS 4-door, driven by a 68-year-old male and the right front seat was occupied by a 7 year old male. Vehicle 2 was a 1993 Pontiac Grand Am (SE) 2-door driven by a 28-year-old male. The roadway is an asphalt, two lane, two way, winding desert roadway with no traffic controls. Vehicle 1 was traveling in an easterly direction, and Vehicle 2 was traveling in a westerly direction. Due to the heavy rain, the driver of Vehicle 1 had begun to slow down. The driver of Vehicle 1 saw Vehicle 2 come across the center double yellow line, but did not have time to take evasive action. Vehicle 2 was traveling too fast for the weather conditions. The driver of Vehicle 2 lost control of the vehicle and it entered the eastbound travel lane, directly in front of Vehicle 1. The left front of Vehicle 1 struck the right front quarter panel of Vehicle 2. At impact, the forces exceeded the threshold of the supplemental restraint systems in Vehicle 1, and both air bags deployed. After impact, Vehicle 2 rotated counterclockwise and the right side of Vehicle 2 side-slapped the left side of Vehicle 1. Vehicle 1 moved forward in an easterly direction and ran off the road and came to final rest heading north-east on the dirt shoulder. After the secondary impact, Vehicle 2 rotated counterclockwise approximately 120 degrees, and came to final rest, heading southwest, across the westbound travel lane. The air bag in the right front side contacted the right front occupant and caused fatal injuries to him. 16. Abstract 17. Key Words 18. Distribution Statement Air bag, deployment, child, fatality, collision

Form DOT F 1700.7 (8_72)

19. Security Classif. (of this report)

Reproduction of this form and completed page is authorized

20. Security Classif. (of this page)

21. No of pages

22 Price

TECHNICAL SUMMARY

This case was initiated in response to a reported collision in which the right side passenger's air bag deployment caused fatal injuries to the 7 year old right front passenger. This was conducted as an on-scene investigation. This collision occurred in the evening hours on 1996, in DSI was notified on 1996 and the source of the case is unknown.

The roadway is an asphalt, two lane, two way, winding desert roadway with no traffic controls. Vehicle 1 was about to enter a right curve, and Vehicle 2 was exiting a left curve in the roadway. There was a slight uphill grade for Vehicle 1, and a slight downhill grade for Vehicle 2. It had just begun to rain heavily, and lightning was reported in the area. The posted speed limit was 89 km/h (55 MPH).

Vehicle 1 was a 1992 Mercury Sable LS 4-door, driven by a 68 year old male (178 cm / 70 in, 100 kg / 220 lb) and the right front seat was occupied by a 7 year old male (137 cm / 54 in, 26 kg / 57 lb). Vehicle 2 was a 1993 Pontiac Grand Am SE 2-door, driven by a 28 year old male (185 cm / 73 in, 73 kg / 160 lb).

Vehicle 1 was traveling in an easterly direction, and Vehicle 2 was traveling in a westerly direction. Due to the heavy rain, the driver of Vehicle 1 had begun to slow down. The driver of Vehicle 1 saw Vehicle 2 come across the center double yellow line, but did not have time to take evasive action. Vehicle 2 was traveling too fast for the weather conditions. The driver of Vehicle 2 lost control of the vehicle and it entered the eastbound travel lane, directly in front of Vehicle 1. The left front of Vehicle 1 struck the right front quarter panel of Vehicle 2.

At impact, the forces exceeded the threshold of the supplemental restraint systems in Vehicle 1, and both air bags deployed.

After impact, Vehicle 2 rotated counterclockwise and the right side of Vehicle 2 side-slapped the left side of Vehicle 1. Vehicle 1 moved forward in an easterly direction and ran off the road and came to final rest heading north-east on the dirt shoulder. After the secondary impact, Vehicle 2 rotated counterclockwise approximately 120 degrees, and came to final rest, heading southwest, across the westbound travel lane.

The driver of Vehicle 1 was wearing the available lap/shoulder restraint. The evidence of usage was that the seat belt webbing had been stretched and curled. Also there were blood stains on the lap belt portion of the restraint and seat belt webbing transfer on the D-ring. The driver sustained injuries consisting of lacerations to the back of his head and left arm. The driver does not remember having lacerations or bleeding, but there were blood stains on the driver's air bag, lap belt and the seat. The lacerations to the back of the head may have been caused by the plastic cover across the top of the window frame. It had been displaced laterally towards the driver. The driver also sustained three fractured ribs on his right side which were caused by loading on the lap/shoulder restraint. He had a fractured metatarsal on his right foot that was caused when the toe pan intruded and contacted the brake and accelerator pedals. The fractured left hip presumably resulted from the side slap with Vehicle 2. The driver had abrasions to his chest, and left lower abdomen from contact with the lap/shoulder restraint and the air bag. The driver was transported to an area hospital via ground ambulance and he was hospitalized for approximately a month. Due to his hip replacement, he was in rehabilitation for approximately another month.

The 7 year old right front occupant of Vehicle 1 was wearing the available lap/shoulder restraint. The inspection




Figure 1. D-ring on right front shoulder belt.

of Vehicle 1 revealed loading on the seat belt webbing, as well as seat belt webbing transfer marks on the D-ring (see Figure 1). The plastic cover on the lower portion of the seat belt retracting mechanism had been broken off indicating heavy loading on the seat belt (see Figure 2). The driver of Vehicle 1 stated that the child was seated with his back in contact with the seat back, and that the lap/shoulder restraint was worn properly. After the collision, the child was slumped over, still belted in a seated position and unconscious. He was not in the back seat of the vehicle as noted in several of the medical records. The driver of Vehicle 1 further stated that there were no noticeable contusions, abrasions, or redness about the face of the child.



An off duty paramedic arrived on scene shortly after the collision, and performed CPR for some 15 minutes. When rescue personnel arrived on scene the 7-year-old was unconscious, pale, cyanotic, and in full cardiac arrest. He arrived at the ER in the same condition. Medical records noted no evidence of neck or skull fractures. There were multiple abrasions and contusions (AIS-1) primarily over the right lower quadrant. There was trauma to the upper chest and right clavicle. The trauma was primarily seat belt contusions and abrasions.

Figure 2. Right front passenger seat, damage to the plastic molding on the lower portion of the seat belt retracting mechanism.

The 7 year old sustained internal massive brain injuries (AIS-5). The autopsy report attributes death to multiple injuries due to blunt force trauma. It states that death is attributed to massive head injury, chest trauma (bilateral pulmonary contusions, AIS-3), and anoxic encephalopathy, brain death. One of the treating physicians indicated that the child "sustained massive whiplash type injuries to his head and neck which caused cerebral edema which resulted in his death." The cerebral edema and pulmonary contusions are attributed to contact with the air bag.

Initially he was transported via helicopter to an area hospital. One day later he was transported via helicopter to a pediatric intensive care unit of another hospital. He was treated there and expired seven days later on 08/20/96 at 1000 hours.

The traffic collision report indicates that the driver of Vehicle 2 was wearing the available lap and shoulder restraint. He sustained injuries consisting of a laceration on the back of his head, and contusions to his leg and center portion of his chest. He was transported to a local hospital via ground ambulance, where he stayed overnight and was released.

Vehicle 1 sustained total damage to the left front of the vehicle as a result of the first impact with Vehicle 2. A CDC of 11FDEW2 was assigned to the damage pattern (see Figure 3), with a maximum crush of 26 cm (10.2 in) at C₂. The missing vehicle portion of WinSmash computed a longitudinal Delta V of -36.6 km/h (22.7 mph) for Vehicle 1. Vehicle 1 was towed from the scene due to its damage to a local tow vard. and was then picked up by the attorney representing occupants of Vehicle 1. Vehicle 1 was then towed to the attorney's office where it was outdoors



Figure 3. Damage to Vehicle 1 from impact #1.

prior to being inspected. Vehicle 1 was inspected more than thirty days after the collision.

Police photographs indicate that Vehicle 2 sustained major damage to its front end, right front quarter panel, right side, right rear quarter panel, and right rear bumper areas as a result of impact with Vehicle 1. A CDC of 02RYEW3 was assigned to the damage pattern for the first impact. The missing vehicle portion of WinSmash computed a Delta V of 46.2 km/h (28.7 mph) for Vehicle 2. Vehicle 2 was towed from the scene due to its damage to a local tow yard, and then sold at a local salvage auction.

DYNAMIC SCIENCE, INC. ACCIDENT INVESTIGATION CASE NUMBER: DS9610

TABLE OF CONTENTS

Accident Data	1
Ambience	1
Roadway	2
Vehicles	3
Vehicle Damage	4
Vehicle Velocity Estimates	4
Collision Sequence	5
Rescue Activities	5
Driver and Other Occupants	0
Injuries	2
Abbreviations	4
Collision Measurements	5
Scene Diagram 16-1	7
Photo Index	8

ACCIDENT DATA:	
Location:	
Area/Type:	Desert/Rural
Date/Time:	1996 / 1813 hours
Accident Type:	Vehicle to Vehicle / Front to Right Front Side; Secondary impact side slap V1's left side vs. V2's right rear corner
Injury Severity:	
Vehicle 1:	Driver, AIS-2
	RF Occupant, AIS-5
Vehicle 2:	Driver, AIS-1
AMBIENCE:	
Viewing Conditions:	Bad visibility due to heavy rain
Cloud Cover:	Heavy Clouds
Precipitation:	100%, Heavy Rain
Road Surface:	Wet

ROADWAY:

VEHICLE 1 VEHICLE 2

Type: Two-lane Two-lane

Width: 7 M (22.9 ft) 7 M (22.9 ft)

Traffic Density: Moderate Moderate

Median: Painted double yellow Painted double yellow

lines lines

Edge: Painted white edge line, Painted white edge line,

and dirt shoulder and dirt shoulder

Surface: Asphalt Asphalt

Reported Defects: None None

Co-efficient of Friction (est.): 0.75 0.75

Vertical Alignment: Slight uphill Slight downhill

Horizontal Alignment: Straight Exiting left curve

Traffic Controls:

VEHICLE 1 VEHICLE 2

Signals: None None

Signs: None applicable None applicable

Speed Limit: 89 km/h (55 mph) 89 km/h (55 mph)

Towed due to damage

VEHICLES:

Tow Status:

VEHICLE 1 VEHICLE 2 Description: 1992 Mercury Sable LS 1993 Pontiac Grand Am 4-door SE 2-door **Odometer:** 100,728 kilometers Unknown 62,591 miles **Engine:** L6 / 3.8L EFI L4 / 2.3 L EFI **Vehicle Modifications:** None None **Tire Condition:** Good Good **Manual Restraints:** Three-point manual Three-point manual lap/shoulder restraints at lap/shoulder at LR, and LF, RF, LR, and RR RR seating positions. seating positions. Twopoint manual lap restraint at CF, and CR seating positions. **Automatic Restraints:** Driver's and mid-Three-point passive door mounted passenger's air mounted lap/shoulder bags restraints at LF, RF. **Reported Defects:** None None Cargo: None None Windshield Damage: Cracked by impact Cracked by impact forces. forces. Fleet: No No

Towed due to damage

VEHICLE DAMAGE: Impact #1, Highest Delta-V

VEHICLE 1 VEHICLE 2

Object Struck: Vehicle 2 Vehicle 1

Event Number: 01

CDC: 11FDEW2 02RYEW3 estimated from

photographs

Maximum Crush: 26.0 cm (10.2 in) Zone 3, estimated from

photographs

VEHICLE VELOCITY ESTIMATES:

Summary of Results Using Damage

Vehicle 1 Speed Change

(Damage)

Total: 39.0 km/h
Longitudinal: -36.6 km/h
Latitudinal: 13.3 km/h
PDOF: -20°

Energy Dissipated: 52,119 Joules
Barrier Equivalent Speed: 27.2 km/h
Moment Arm of Principle Force: 61.0 cm (CW)
Change in Angular Velocity: 1.8 deg/seconds

Used d0 and d1 values estimated from the vehicle size (modified for offset impact).

Vehicle 2 Speed Change

(ROLDMISS)

Total: 46.2 km/h
Longitudinal: -35.4 km/h
Latitudinal: -29.7 km/h

PDOF: 40°

Energy Dissipated: 186,284 Joules
Barrier Equivalent Speed: 54.9 km/h
Moment Arm of Principle Force: 66.7 cm (CW)
Change in Angular Velocity: 2.4 de/seconds

Used d0 and d1 values estimated from the vehicle size.

Delta-V's calculated using Oldmiss of WinSmash. Offset impact was checked since it was deemed appropriate in this case. The crush profile used in this case was estimated from measuring above the bumper level. The C-values used in the WinSmash program would result in a borderline reconstruction.

COLLISION SEQUENCE:

Pre-Crash: This two vehicl

This two vehicle collision occurred in 1996 at 1813 hours. The collision occurred on a two-lane, undivided, winding desert road. The east/west roadway consists of an eastbound and a westbound travel lane. This roadway is 7 M (22.9 ft) wide with an asphalt surface. The eastbound travel lane had a slight uphill grade, and the westbound travel lane had a slight downhill grade.

Crash: The driver of Vehicle 1 saw Vehicle 2 come across the center double yellow line, but did not have time to take evasive action. The driver of Vehicle 2 lost control of the vehicle and it entered the eastbound travel lane, directly in front of Vehicle 1. The left front of Vehicle 1 struck the right front quarter panel of Vehicle 2. Both air bags in Vehicle 1 deployed at this point. A WinSmash run determined that Vehicle 1 sustained a -36.6 km/h (22.7 mph) longitudinal velocity change. Vehicl1 continued generally forward while Vehicle 2 was rotated counterclockwise, and there was a second impact, a "side slap" between the left side of Vehicle 1 and the right rear side of Vehicle 2.

Post Crash: Vehicle 1 moved forward in an easterly direction and ran off the road and came to final rest heading northeast on the dirt shoulder. After the secondary impact, Vehicle 2 rotated counterclockwise approximately 120 degrees, and came to final rest heading south-west across the westbound travel lane.

The driver of Vehicle 1 noted that there was smoke still coming out of the driver's air bag. There was an odor of gun powder and he thought that the air bag was going to catch fire.

RESCUE ACTIVITIES:

Rescue activities

Event	Event Time
Accident	1813
Rescue dispatched	1838
Helicopter dispatched	1838
Rescue arrived	1843
Helicopter arrived	1858
Helicopter left scene	1903
Helicopter arrived at hospital	1 <mark>908</mark>
Time of Death	1000, on 8/_/96

The right front occupant of Vehicle 1 was treated initially at the scene by an off duty paramedic who performed CPR for 15 minutes. R/F occupant was then taken to an area hospital via helicopter. The next day, he was transported via helicopter to an pediatric intensive care unit of another hospital. The drivers of Vehicle 1 and Vehicle 2 were transported via ground ambulance to an area hospital. The driver of Vehicle 1 was hospitalized for approximately a month. The driver of Vehicle 2 was hospitalized overnight and then released.

Occupant

Kinematics:

Driver, Vehicle 1 - The driver was seated on a split bench in a normal, upright seated position. At impact, it appears that the driver had his right foot on the accelerator pedal and his left foot on the floor. Both hands were on the steering wheel. He was properly restrained by the available lap/shoulder restraint. During the on-site inspection, it appeared that the left front split bench seat had been adjusted just rearward of the mid-point seat track position. The adjustable seat back recline appeared to have been in a normal upright position. The seat back recline angle was measured at 10 degrees.

At impact, the driver braced. He was projected forward and to the left. His torso loaded the lap/shoulder restraint and his left arm, and face came into contact with the deploying air bag. The watch on his left arm was damaged due to contact with the air bag. It was somehow knocked off his arm, and it can be seen in photo 015. He was wearing glasses and the frames were bent by the contact with the air bag. He does not remember if they were knocked off, but no injuries occurred. He sustained injuries consisting of lacerations to the back of his head and arm. He does not remember having lacerations or bleeding, but there were blood stains on the driver's air bag, lap belt and seat. The laceration to the back of the head may have been caused by the plastic cover across the top window frame. It had been displaced laterally towards the driver. He also sustained three fractured ribs on his right side which were caused by loading on the lap/shoulder restraint. He had a fractured metatarsal on his right foot that was caused when the toe pan intruded and contacted the brake and accelerator pedals. The side slap impact resulted in a fractured left hip. He had abrasions to his chest, and left lower side from loading on the lap/shoulder restraint and air bag. He was transported to an area hospital via ground ambulance and he was hospitalized for approximately a month. Due to his hip replacement, he was in rehabilitation for approximately another month.

Occupant

Kinematics: RF Occupant, Vehicle 1 - The driver stated that the right front occupant was seated in an upright normal position with his back up against the right front seat back, and that the lap/shoulder restraint was worn in a normal fashion. The right front split bench seat had been adjusted just rearward of the mid-point seat track position. The adjustable seat back recline was reclined rearward, and the angle was measured at 33 degrees. The inspection of the right front lap/shoulder restraint, and injuries are consistent with him wearing the lap/shoulder restraint. The belt showed curling and stretching from loading. The D-ring was abraded by the seat belt webbing, and the plastic molding around the lower seat belt retracting mechanism was broken due to heavy loading (see photos 99-105). There was no pre-impact braking.

> At impact with Vehicle 2, the right front occupant began to move forward closer to the air bag, and loaded heavily on the lap/shoulder restraint. The right front air bag deployed and contacted his chest area. The driver stated that there were no noticeable contusions, abrasions, or redness about the child's face. As the air bag continued its unfolding sequence, it "snapped" and accelerated the child's head rearward. One of the treating physicians indicated that the child "sustained massive whiplash type injuries to his head and neck which caused cerebral edema which resulted in his death."

> As the head was accelerated rearward, the brain struck the front of the skull causing massive brain edema, subdural hemorrhage, ventricular hemorrhage, and subarachnoid hemorrhage. This led to anoxic encephalopathy, and then brain death. The child also sustained bilateral pulmonary contusions to the upper lobe, and a cardiac contusion as a result of contact with the air bag. He had multiple contusions and abrasions about his chest and lower abdomen attributed to the seat belt webbing.

> After the collision the child was slumped over, still belted in a seated position and unconscious. He was not in the back seat of the vehicle as noted in several of the medical records. An off duty paramedic arrived on scene shortly after the collision, and performed CPR for some 15 minutes. When rescue personnel arrived on scene the 7-year-old was unconscious, pale, cyanotic, and in full cardiac arrest. He arrived at the ER in the same condition, and he never regained consciousness. He expired seven days later.




Figure 4. Measurements of right front seat position and air bag.

Air bag System:

Vehicle 1 was equipped with two air bags, one in the steering wheel hub and one on the right front passenger side. The driver's air bag had a 58.5 cm (23 in) diameter. There were two symmetrical module cover flaps. The upper cover measured 20.5 (8.1 in) x 16.5 cm (6.5 in). There were two air vent ports at the 11 and 1 o'clock positions. The lower cover measured 20.5 (8.1 in) x 7.9 cm (3.1 in).

The right front passenger's air bag was a mid-mounted configuration. The air bag measured 81.5 cm (32.1 in) x 40 cm (15.7 in). There were two symmetrical module cover flaps. The upper flap cover measured 31.3 cm (12.3 in) x 5.5 cm (2.2 in), and the lower flap cover measured 31.3 cm (12.3 in) x 5.5 cm (2.2 in). There were two air vent ports on the left side (inboard) of the air bag, at the 10 and 8 o'clock positions.

The driver of Vehicle 1 noted that there was smoke still coming out of the driver's air bag. There was an odor of gun powder and he thought that the air bag was going to catch fire.

Scene Clearance:

Both vehicle were towed from the scene due to damage and were placed in police storage. Vehicle 1 was then taken to the office of the attorney representing the occupants, and was stored outdoors for several months prior to the vehicle inspection. Vehicle 2 was then taken to a auction salvage lot, were it was sold.

Safety Standards:

There were no violations of Federal Motor Vehicle Safety Standards and Regulations found during the inspection of Vehicle 1.

DRIVER AND OTHER OCCUPANTS:

VEHICLE 1

DRIVER OCCUPANT 2

Age/Sex: 68/Male 7/Male

Seated Position: Left front Right front

Seat Type: Split Bench Split Bench

Height: 178 cm (70 in) 137 cm (54 in), per autopsy

report

Weight: 100 kg (220 lbs) 26 kg (57 lbs), per autopsy report

Additional Measurements:

Erect Sitting Height NA 65.8 cm (25.9 in)¹

Buttock-knee Length NA 39.1 cm (15.4 in)¹

Occupation: Retired Not employed

Pre-existing Medical Unknown Significant history of wheezing

Condition: episodes, and had an unspecified

head injury at age 5²

Alcohol/Drug Involvement: None NA

Driving Experience: ≈52 years NA

Body Posture: Normal, upright Normal, upright

Hand Position: Both on steering wheel, NA

Foot Position: Right foot on accelerator NA

Restraint Usage: Lap/shoulder belt used Lap/shoulder belt used

Additional Occupants: None None

¹Anthropometry of Infants, Children, and Youths to Age 18 for Product Safety Design

²As noted on Hospital records

DRIVER AND OTHER OCCUPANTS (con't):

VEHICLE 2

DRIVER

Age/Sex: 28/Male

Seated Position: Left front

Seat Type: Bucket with folding back

Height: 185 cm (73 in)

Weight: 73 kg (160 lbs)

Occupation: Unknown

Pre-existing Medical

Condition:

Unknown

Alcohol Involvement: None

Driving Experience: ≈ 5 years

Body Posture: Unknown

Hand Position: Unknown

Foot Position: Unknown

Restraint Usage: Lap/shoulder restraints used

traffic collision report

Additional Occupants: None

INJURIES:

Vehicle 1

	<u>INJURY</u>	OIC CODE	<u>ICD-9</u>	SOURCE
DRIVER:	Fractured left hip	852600.2,2	820.8	Left side door
	3 fractured ribs on the right side	450220.2,1	807.03	Seat belt
	Fractured right metatarsal	852200.2,1	825.20	Foot pedal
	Abrasions across chest	490202.1,4	911.0	Seat belt webbing/Air bag
	Abrasion to lower left side of abdomen	590202.1,8	911.0	Seat belt webbing
	Laceration to back of head	190600.1,3	873.0	Window frame plastic covering
	Laceration to left arm	790600.1,2	880.03	Air bag
R/F OCCUPANT:	Massive brain edema	140674.5,9	348.5	Air bag
	Loss of consciousness/Unconscious on admission or initial observation at scene. Length of consciousness > 24 hours.	160818.5, 0	854.05	Air bag
	Subdural hemorrhage	140650.4,9	852.25	Air bag
	Ventricular hemorrhage	140678.4,9	852.25	Air bag
	Bilateral pulmonary contusion to upper lobe	441410.4,3	518.4	Air bag
	Cardiac contusion	441002.3,4	861.01	Air bag
	Subarachnoid hemorrhage	140684.3,9	852.05	Air bag
	Multiple abrasions over the right lower abdomen	590202.1,8	911.0	Seat belt webbing

Multiple contusions over the right lower abdomen	590402.1,8	922.2	Seat belt webbing
Contusions over chest in the seat belt position	490402.1,4	922.1	Seat belt webbing

INJURIES:

Vehicle 2

	<u>INJURY</u>	OIC CODE	<u>ICD-9</u>	SOURCE
DRIVER:	Laceration to back of head	190600.1, 3	873.0	Unknown
	Contusion to leg	890402.1,9	924.5	Unknown
	Contusion to chest	490402.1,4	922.1	Seat belt webbing

Abbreviations Used In Scene And Photographic Documentation

ft Feet in Inches

AIS Abbreviated Injury Scale

BLF Begin Left Front
BLR Begin Left Rear
BRF Begin Right Front
BRR Begin Right Rear
CBE Cab Behind Engine
CCW Counterclockwise

CDC Collision Deformation Classification

CG Center of Gravity

CM Centimeter

COE Cab Over Engine

CW Clockwise

E, EB East, Eastbound **ELF End Left Front** ELR End Left Rear **End Right Front ERF ERR** End Right Rear **FRP Final Rest Position** Ι Interstate Highway IP Intermediate Point

KG Kilogram

KPH Kilometers Per Hour

LF Left Front
LR Left Rear
M Meter

N, NB North, Northbound

NE Northeast NW Northwest

PDOF Principal Direction of Force

POI Point of Impact
R Radius of Curvature

RF Right Front
RL Reference Line
RP Reference Point
RR Right Rear

S, SB South, Southbound

SE Southeast SW Southwest


Time or Elapsed Time (in seconds)

V1 Vehicle Number 1 W, WB West, Westbound

COLLISION MEASUREMENTS Taken from the Police Accident Report

Reference Point: East Curb Line of North/South roadway	Reference Line: South Fog Line		
ITEM	Distance and Direction from RP	Distance and Direction from RL	
Area of Impact #1 Front of Vehicle 1 and right side of Vehicle 2	66.4 m (218') East	2.3 m (7'7") North	
Point of rest for Vehicle 1			
R/F tire	69.8 m (229') East	3.4 m (11'2") South	
R/R tire	67.4 m (221') East	4.9 m (16') South	
L/F tire	69.6 m (226'8") East	2.2 m (7'2") South	
L/R tire	66.4 m (218') East	3.4 m (11'3") South	
Point of rest for Vehicle 2			
R/F tire	67.9 m (222'11") East	6 m (19'7") North	
R/R tire	70.1 m (230') East	At the North fog line	
L/F tire	68.9 m (226') East	3.3 m (13'10") North	
L/R tire	70.6 m (231'8") East	6 m (19'9") North	

Scene Diagram page 1



Scene Diagram page 2




PHOTO INDEX

Case No. DS9610

РНОТО NO.	VEHICLE NO.	DIRECTION OF PICTURE	SUBJECT MATTER
			The following photographs were taken by the police at the scene, and at the tow yard of both vehicles.
001-005	1		Exterior of vehicle at final rest.
006-010	1		Interior of vehicle, driver's position.
011-015	1		Interior of vehicle, at right front position.
019-033	2		Exterior of vehicle, both at final rest and the tow yard.
034-039	2		Interior of vehicle. **Note photo 038, speedometer locked at 128.7 km/m (80 mph).
			The following photographs were taken by the investigator.
040-042	1	East	Direction of travel towards impact area.
048	1	East	Impact area.
043	1	East	Final rest area.
045	1	West	Opposite direction of travel from final rest area.
046-047	2	West	Direction of travel towards impact area.
048	2	South-West	Impact area #1.
049	2	West	Counterclockwise rotation.
050-051	2	South-West	Final rest area. Tires marked per police measurements.
052	2	North-East	Opposite direction from final rest.
053	2	West	Opposite direction of travel.
054-072	1	NA	Exterior damage.
073-079	1	NA	Exterior damage with crush measuring stands at bumper mounting brackets, and radiator supportrail.

080-097	1	NA	Interior looking at driver's area.
098-113	1	NA	Interior looking at right front area.
114-120	1	NA	Interior looking at driver's area and roof.
121-123	1	NA	Interior looking at right front area.
124-126	1	NA	Interior rear seats.
































































































































DSI96AB10-062


















































































































BESTAVAILABLE





















ACCIDENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

1.	Primary	Sampling	Unit	Number
----	----------------	----------	------	--------

2. Case Number - Stratum Die 9 6 1 4

IDENTIFICATION

3. Number of General Vehicle Forms Submitted

<u> 02</u>

4. Date of Accident (Month, Day, Year)

5. Time of Accident

1813

Code reported military time of accident.

NOTE: Midnight = 2400 Unknown = 9999

SPECIAL STUDIES - INDICATORS

Check (/) each special study (SS15-SS18 below) that has been completed; code 1 for the checked special studies and 0 for the special studies not checked.

6. ___ SS15 Administrative Use

\$

0_

7. ___ SS16 Pedestrian Crash Data Study
(Data for this special study available
in a separate file.)

8. ___ SS17 Impact Fires

ф

9. ___ SS18 Unsafe Driver Actions

Ф

10. ___ SS19 ____

<u>\$</u>

NUMBER OF EVENTS

11. Number of Recorded Events in This Accident

02

Code the number of events which occurred in this accident.

ACCIDENT EVENTS

For each event that occurred in the accident, code the lowest numbered vehicle in the left columns and the other involved vehicle or object in the right columnss.

						
Accident Event Sequence Number	Vehicle Number	Class Of Vehicle	General Area of Damage	Vehicle Number or Object Contacted	Class Of Vehicle	General Area of Damage
12. <u>0</u> <u>1</u>	13. <u>φ</u> <u> </u>	14. <u>Ø 3</u>	15. <u>F</u>	16. <u>¢</u> <u>2</u>	17. <u>\$\phi\$</u> 2	18. <u></u>
19. <u>0</u> <u>2</u>	20. <u> </u>	21. <u>\$\phi\$</u> 3	22. <u>L</u>	23. 0 2	24. <u>\$\phi\$</u> 2	25. <u>R</u>
26. <u>0</u> <u>3</u>	27	28	29	30	31	32
33. <u>0 4</u>	34	35	36	37	38	39
40. <u>0</u> <u>5</u>	41	42	43	44	45	46

IF GREATER THAN FIVE EVENTS, CONTINUE CODING ON THE ACCIDENT EVENT SUPPLEMENT

	CODES F	OR CI	LASS OF VE	HICLE	
(01) Subcomp. (02) Compact (03) Intermedia (04) Full size (105) Largest (107) Unknown (14) Compact (15) Large utili (16) Utility sta (19) Unknown (20) Minivan (107) Large van (21) Large van (24) Van Based (28) Other van (29) Unknown	tor vehicle act/mini (wheelbase < 254 cm) (wheelbase ≥ 254 but < 265 cm) ate (wheelbase ≥ 265 but < 278 cm) wheelbase ≥ 278 but < 291 cm) wheelbase ≥ 291 cm) passenger car size utility vehicle ty vehicle (≤ 4,500 kgs GVWR) tion wagon (≤ 4,500 kgs GVWR) utility type (≤ 4,500 kgs GVWR) d school bus (≤ 4,500 kgs GVWR) type (≤ 4,500 kgs GVWR) van type (≤ 4,500 kgs GVWR) pickup truck (≤ 4,500 kgs GVWR)		(38) (39) (45) (48) (49) (50) (58) (59) (60) (67) (68) (78) (79) (80) (90)	Large pickup truck (\$\(\pm\) 4,50 Other pickup truck (\$\(\pm\) 4,50 Unknown pickup truck type Other light truck (\$\(\pm\) 4,500 Unknown light truck type (Unknown light vehicle type School bus (excludes van b Other bus (> 4,500 kgs G Unknown bus type Truck (> 4,500 kgs GVWF Tractor without trailer Tractor-trailer(s) Unknown medium/heavy tr Unknown light/medium/hea Motored cycle Other vehicle Unknown	O kgs GVWR) e (≤ 4,500 kgs GVWR kgs GVWR) ≤ 4,500 kgs GVWR) e pased)(> 4,500 kgs GVWI VWR) R)
CDC ADDITOAT	CODES FOR GENER				
CDS APPLICAE AND OTHER VEHICLES	BLE (0) Not a motor vehicle (N) Noncollision (F) Front	(L)	Right side Left side Back		(T) Top (U) Undercarriage (9) Unknown
TDC APPLICABLE VEHICLES	(0) Not a motor vehicle(N) Noncollision(F) Front(R) Right side	(B)	(rear of tr	nit with cargo area ailer or straight truck) (T) r of tractor)	(C) Rear of cab (V) Front of cargo area Top (U) Undercarriage (9) Unknown
(32) Rollove (33) Fire or (34) Jackkr (35) Other	orn — rollover (excludes end-over-end) er — end-over-end explosion nife intraunit damage (specify):	UME	(57) (58) (59) (60) (61) (62) (63) (64) (68)	Fence Wall Building Ditch or culvert Ground Fire hydrant Curb Bridge Other fixed object (specify	y):
(39) Noncol Collision With F (41) Tree (3) (42) Tree (3) (43) Shrubb (44) Emban	lision — details unknown ixed Object 10 cm in diameter) 10 cm in diameter) ery or bush kment		Collisio (70) (71) (72) (73)	Unknown fixed object on with Nonfixed Object Passenger car, light truck, not in-transport Medium/heavy truck or bu Pedestrian Cyclist or cycle Other nonmotorist or conv	s not in-transport
Nonbreakaway (50) Pole or (51) Pole or (52) Pole or (53) Pole or (54) Concre (55) Impact (56) Other t	post (\$ 10 cm in diameter) post (> 10 cm but \$ 30 cm in diamete post (> 30 cm in diameter) post (diameter unknown) te traffic barrier	r)	(75) (76) (77) (78) (79) (88)	Vehicle occupant Animal Train Trailer, disconnected in tra Object fell from vehicle in- Other nonfixed object (specific disconnected) Unknown nonfixed object Other event (specify):	ansport transport
,0,00011			(99)	Unknown event or object	

GENERAL VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 2. Case Number - Stratum 3. Vehicle Number VEHICLE IDENTIFICATION 4. Vehicle Model Year Code the last two digits of the model year (99) Unknown 5. Vehicle Make (specify): MERCOR	12. Speed Limit (000) No statutory limit Code posted or statutory speed limit in kmph (999) Unknown 55 mph x 1.6093 = 489 kmph 13. Police Reported Alcohol Presence For Driver (0) No alcohol present (1) Yes alcohol present (7) Not reported (8) No driver present (9) Unknown
Applicable codes are found in your NASS Data Collection, Coding and Editing Manual. (99) Unknown 6. Vehicle Model (specify): SABLE Applicable codes are found in your NASS Data Collection, Coding and Editing Manual. (999) Unknown	14. Alcohol Test Result For Driver Code actual value (decimal implied before first digit—0.xx) (95) Test refused (96) None given (97) AC test performed, results unknown (98) No driver present (99) Unknown Source:
7. Body Type Note: Applicable codes may be found on the back of this page.	15. Police Reported Other Drug Presence For Driver (0) No other drug(s) present (1) Yes other drug(s) present (7) Not reported
8. Vehicle Identification Number \[\limits_{\text{M}} \overline{\text{L}} \frac{\text{M}}{5} \frac{\text{J}}{4} \frac{\text{J}}{5} \limits_{\text{V}} \frac{\text{J}}{2} \frac{J}{2} \frac{\text{J}}{2} \frac{\text{J}}{2} \frac{\text{J}}{2} \	(8) No driver present (9) Unknown 16. Other Drug Specimen Test Result For Driver (0) No specimen test given (1) Drug(s) not found in specimen (2) Drug(s) found in specimen, (specify):
9. Vehicle Special Use (This Trip) (0) No special use (1) Taxi (2) Vehicle used as school bus (3) Vehicle used as other bus (4) Military (5) Police (6) Ambulance (7) Fire truck or car (8) Other (specify): (9) Unknown	(3) Specimen test given, results unknown or not obtained (8) No driver present (9) Unknown if specimen test given 17. Driver's Zip Code (00001) Driver not a resident of U.S. or territories Code actual 5-digit zip code (99998) No driver present
OFFICIAL RECORDS	(99999) Unknown
10. Police Reported Vehicle Disposition (0) Not towed due to vehicle damage (1) Towed due to vehicle damage (9) Unknown 11. Police Reported Travel Speed Code to the nearest kmph (NOTE: 000 means less than 0.5 kmph) (160) 159.5 kmph and above (999) Unknown	18. Driver's Race/Ethnic Origin (1) White (non-Hispanic) (2) Black (non-Hispanic) (3) White (Hispanic) (4) Black (Hispanic) (5) American Indian, Eskimo or Aleut (6) Asian or Pacific Islander (7) Other (specify): (8) No driver present (9) Unknown

CODES FOR BODY TYPE

CDS APPLICABLE VEHICLES

Automobiles

- (01) Convertible (excludes sun-roof, t-bar)
- (02) 2-door sedan, hardtop, coupe
- (03) 3-door/2-door hatchback
- (04) 4-door sedan, hardtop
- (05) 5-door/4-door hatchback
- (06) Station wagon (excluding van and truck based)
- (07) Hatchback, number of doors unknown
- (08) Other automobile type (specify):
- (09) Unknown automobile type

Automobile Derivatives

- (10) Auto based pickup (includes El Camino, Caballero, Ranchero, Brat, and Rabbit pickup)
- (11) Auto based panel (cargo station wagon, auto based ambulance/hearse)
- (12) Large limousine more than four side doors or stretched chassis
- (13) Three-wheel automobile or automobile derivative

Utility Vehicles (≤ 4,536 kgs GVWR)

- (14) Compact utility (Jeep CJ-2 ĆJ-7, Scrambler, Golden Eagle, Renegade, Laredo, Wrangler, Cherokee [84 and after], Dispatcher, Raider, Bronco II, Bronco [76 and before], Explorer, S-10 Blazer, Geo Tracker, Bravada, S-15 Jimmy, Thing, Pathfinder, Trooper, Trooper II, Rodeo, Amigo, Navajo, 4-Runner, Montero, Passport, Samurai, Sidekick, Rocky)
- (15) Large utility (includes Jeep Cherokee [83 and before], Ramcharger, Trailduster, Bronco-fullsize [78 and after], fullsize Blazer, fullsize Jimmy, Hummer, Landcruiser, Rover, Scout, Yukon)
- (16) Utility station wagon (Chevy Suburban, GMC Suburban, Travelall, Grand Wagoneer, includes suburban limousine)
- (19) Utility, unknown body type

Van Based Light Trucks (≤ 4,536 kgs GVWR)

- (20) Minivan (Town and Country, Caravan, Grand Caravan, Voyager, Grand Voyager, Mini-Ram, Vista, Aerostar, Windstar, Villager, Lumina APV, Trans Sport, Silhouette, Astro, Safari, Toyota Van, Toyota Minivan, Previa, Nissan Minivan, Quest, Mitsubishi Minivan, Expo Wagon, Vanagon/Camper.)
- (21) Large van (B150-B350, Sportsman, Royal, Maxiwagon, Ram, Tradesman, Voyager [83 and before], E150-E350, Econoline, Clubwagon, Chateau, G10-G30, Chevy Van, Beauville, Sport Van, G15-G35, Rally Van, Vandura.)
- (22) Step van or walk-in van (≤ 4,536 kgs GVWR)
- (23) Van based motorhome (s 4,536 kgs GVWR)
- (24) Van based school bus (< 4,536 kgs GVWR)
- (25) Van based other bus (≤ 4,536 kgs GVWR)
- (28) Other van type (Hi-Cube Van, Kary) (specify):
- (29) Unknown van type

Light Conventional Trucks (Pickup style cab, ≤ 4.536 kgs GVWR)

- (30) Compact pickup (D50, Colt P/U, Ram 50, Dakota, Arrow Pickup [foreign], Ranger, Courier, S-10, T-10, LUV, S-15, T-15, Sonoma, Datsun/Nissan Pickup, P'up, Mazda Pickup, Toyota Pickup, Mitsubishi Pickup)
- (31) Large Pickup (Jeep Pickup, Comanche, Ram Pickup, D100-D350, W100-W350, F100-F350, C10-C35, K10-K35, R10-R35, V10-V35, Silverado, Sierra, R100-R500, T100)
- (32) Pickup with slide-in camper
- (33) Convertible pickup
- (39) Unknown pickup style light conventional truck type

Other Light Trucks (≤ 4,536 kgs GVWR)

- (40) Cab chassis based (includes rescue vehicles, light stake, dump, and tow truck)
- (41) Truck based panel
- (42) Light truck based motorhome (chassis mounted)
- (45) Other light conventional truck type
- (48) Unknown light truck type
- (49) Unknown light vehicle type (automobile, utility, van, or light truck)

OTHER VEHICLES

Buses (Excludes Van Based)

- (50) School bus (designed to carry students, not cross country or transit)
- (58) Other bus type (e.g., transit, intercity, bus based motorhome) (specify):
- (59) Unknown bus type

Medium/Heavy Trucks (> 4,536 kgs GVWR)

- (60) Step van (> 4,536 kgs GVWR)
- (61) Single unit straight truck (4,536 kgs < GVWR ≤ 8,845 kgs)
- (62) Single unit straight truck (8,845 kgs < GVWR ≤ 11,793 kgs)
- (63) Single unit straight truck (> 11,793 kgs GVWR)
- (64) Single unit straight truck, GVWR unknown
- (65) Medium/heavy truck based motorhome
- (67) Truck-tractor with no cargo trailer
- (68) Truck-tractor pulling one trailer
- (69) Truck-tractor pulling two or more trailers
- (70) Truck-tractor (unknown if pulling trailer)
- (78) Unknown medium/heavy truck type
- (79) Unknown truck type (light/medium/heavy)

Motored Cycles (Does Not Include All-Terrain Vehicles/Cycles)

- (80) Motorcycle
- (81) Moped (motorized bicycle)
- (82) Three-wheel motorcycle or moped
- (88) Other motored cycle (minibike, motorscooter) (specify):_____
- (89) Unknown motored cycle type

Other Vehicles

- (90) ATV (All-Terrain Vehicle) and ATC (All-Terrain Cycle)
- (91) Snowmobile
- (92) Farm equipment other than trucks
- (93) Construction equipment other than trucks
- (97) Other vehicle type
- (99) Unknown body type

	PRECRASH ENVIRONMENTAL DATA			
		25	. Roadway Surface Condition	2
19.	Relation To Interchange Or Junction		(1) Dry	
	(0) Non-interchange area and non-junction	18	(2) Wet	
	(1) Interchange area related		(3) Snow or slush	
	• • • • • • • • • • • • • • • • • • • •	P	(4) Ice	
	Non-Interchange junctions		(5) Sand, dirt, or oil	
	(2) Intersection related		(8) Other (specify):	
	(3) Driveway, alley access related		(9) Unknown	
	(4) Other junction (specify)			
	() Caret janetion (opcomy)	1 20	Links On allsi	1
	(5) Unknown type of junction	20	Light Conditions	
	(e) Similariti typa of Junation		(1) Daylight	
	(9) Unknown		(2) Dark	
	(c) officiality	1	(3) Dark, but lighted	
			(4) Dawn	
20	Trafficway Flow	ı	(5) Dusk	
	(0) Not physically divided (two way traffic)		(9) Unknown	
	(1) Divided trafficway-median strip without positive			
	barrier barried trainic way-median strip without positive	1		j
	(2) Divided trafficway-median strip with positive	27	. Atmospheric Conditions	1_
		1	(0) No adverse atmospheric-related driving	
	barrier		conditions	
	(3) One way traffic		(1) Rain	
	(9) Unknown		(2) Sleet/hail	
		1	(3) Snow	
21.	Number Of Travel Lanes Z		(4) Fog	
	(1) One		(5) Rain and fog	
	(2) Two	i	(6) Sleet and fog	
	(3) Three	ı	(7) Other (e.g., smog, smoke, blowing sand or	
	(4) Four		dust, etc.) (specify):	
	(5) Five	1		
	(6) Six		(9) Unknown	
	(7) Seven or more			
	(9) Unknown	28.	. Traffic Control Device	Ď
	, o, o,		(0) No traffic control(s)	
			(1) Traffic control signal (not RR crossing)	
	Roadway Alignment 2	1	5 • • • • • • • • • • • • • • • • • • •	
	(1) Straight	1	Regulatory	
	(2) Curve right		(2) Stop sign	
	(3) Curve left		(3) Yield sign	
	(9) Unknown	Î	(4) School zone sign	
		1	(5) Other regulatory sign (specify):	
23	Roadway Profile	j	o way top conju	
	(1) Level	ı	(6) Warning sign (not RR crossing)	
	(1) Level (2) Uphill grade (>2%)	1	(7) Unknown sign	
	(3) Hill crest		(8) Miscellaneous/other controls including RR	
	(4) Downhill grade (>2%)		controls (specify):	
	(5) Sag		control (opening)	
	(9) Unknown		(9) Unknown	
	(5) OHKHOWII	Ī		
	_			
24 . l	Roadway Surface Type 2	29.	Traffic Control Device Functioning	do 1
(1) Concrete		(0) No traffic control device	-
(2) Bituminous (asphalt)]	(1) Traffic control device not functioning	
	3) Brick or block		(specify):	
(4) Slag, gravel, or stone		•	
(5) Dirt		(2) Traffic control device functioning properly	
	8) Other (specify):	l	(9) Unknown	
(9) Unknown			

	PF	RECRASH DRIVER RELATED DATA		S VEHICLE TRAVELLING
30.	Drive	er's Distraction/Inattention To Driving	(10)	Over the iane line on left side of travel lane Over the lane line on right side of travel lane
-	(Prio	r To Recognition Of Critical Event)	1 712	Off the edge of the road on the left side
	(00)	No driver present	1 (13)	Off the edge of the road on the right side
	(01)	Attentive or not distracted	1 (14)	End departure
	(02)	Looked but did not see	1 (15)	Turning left at intersection
		Distractions		Turning right at Intersection
	(03)	By other occupant(s), (specify):		Crossing over (passing through) intersection
	(,	=, -===================================	(18)	This vehicle decelerating
	(04)	By moving object in vehicle (specify):	(19)	Unknown travel direction
			1	
	(05)	While talking or listening to ceilular phone (specify	OTH	IER MOTOR VEHICLE IN LANE
		location and type of phone):	(50)	Other vehicle stopped
	(00)	AA/L-U	(51)	Traveling In same direction with lower steady
	(00)	While dialing cellular phone (specify location and		speed
		type of phone):		Traveling In same direction while decelerating
	(07)	While adjusting climate controls	(53)	Traveling in same direction with higher speed
	(08)	While adjusting radio, cassette, CD (specify):		Traveling in opposite direction
	(00)	virino adjusting radio, cassette, OD (specity).		In crossover
	(09)	While using other device/controls integral to		Backing
	()	vehicle (specify):	(59)	Unknown travel direction of other motor vehicle in
	(10)	While using or reaching for device/object brought		iane
	` ′	into vehicle (specify):		
	(11)	Sleepy or feli asleep		IER MOTOR VEHICLE ENCROACHING INTO
	(12)	Distracted by outside person, object, or event	LAN	
		(specify):	(60)	From adjacent iane (same direction)—over left
	(13)	Eating or drinking	l	iane line
	(14)	Smoking related	(61)	From adjacent lane (same direction)—over right
	(97)	Distracted/inattentive, details unknown		lane line
	(98)	Other, distraction (specify):	(62)	From opposite direction—over left lane line
	(00)		(63)	From opposite direction—over right lane line
		Unknown 4 14	(64)	From parking lane
31.	Pre-E	Event Movement (Prior to	(65)	From crossing street, turning into same direction
	Reco	gnition of Critical Event)	(66)	From crossing street, across path
	(00)	No driver present	(67)	From crossing street, turning into opposite
		Going straight		direction
	(02)	Decelerating in traffic lane	(68)	From crossing street, intended path not known
	(03)	Accelerating in traffic lane	(70)	From driveway, turning into same direction
	(04)	Starting in traffic lane	(71)	From driveway, across path
	(05)	Stopped in traffic lane	(72)	From driveway, turning into opposite direction
	(00)	Passing or overtaking another vehicle	(73)	From driveway, intended path not known
	(07)	Disabled or parked in travel lane	(74)	From entrance to limited access highway
	(00)	Leaving a parking position	(78)	Encroachment by other vehicle—details unknown
	(10)	Entering a parking position Turning right		•
	711	Turning left	PED	ESTRIAN, PEDALCYCLIST, OR OTHER
		Making a U-turn		MOTORIST
		Backing up (other than for parking position)	(80)	Pedestrian in roadway
	(14)	Negotiating a curve	(81)	Pedestrian approaching roadway
		Changing ianes	(82)	Pedestrian—unknown location
		Merging	(83)	Pedalcyclist or other nonmotorist in roadway
	(17)	Successful avoidance maneuver to a previous		·
		critical event	(specify):	
	(97)	Other (specify):	(84)	Pedaicyclist or other nonmotorist approaching
	(99)	Unknown	\	roadway, (specify):
32.	Critic	al Precrash Event	(85)	Pedaicyclist or other nonmotorist—unknown
				location
	(01)	VEHICLE LOSS OF CONTROL DUE TO:	(specify):	
		Biow out or flat tire Stalled engine		
	(02)	Disabling vehicle failure (e.g., who all fall att		ECT OR ANIMAL
	(00)	Disabling vehicle failure (e.g., wheel fell off) (specify):		Animal in roadway
	(04)	Non-disabling vehicle problem (e.g., hood flew up)	(88)	Animal approaching roadway
		(specify):		Animal—unknown location
	(05)	Poor road conditions (puddie, pot hole, ice, etc.)	(90)	Object in roadway
		(specify):	(91)	Object approaching roadway
	(06)	Traveling too fast for conditions	(92)	Object—unknown location
	(08)	Other cause of control loss (specify):	(98)	Other critical precrash event (specify):
	(09)	Unknown cause of control loss	(99)	Unknown

33. Attempted Avoidance Maneuver (00) No driver present (01) No avoidance maneuver (02) Braking (no lockup) (03) Braking (lockup) (04) Braking (lockup unknown) (05) Releasing brakes (06) Steering left (07) Steering right (08) Braking and steering left (09) Braking and steering right (10) Accelerating (11) Accelerating and steering left	35. Pre-Impact Location (0) No driver present (1) Stayed in original travel lane (2) Stayed on roadway but left original travel lane (3) Stayed on roadway, not known if left original travel lane (4) Departed roadway (5) Remained off roadway (6) Returned to roadway (7) Entered roadway (9) Unknown
(12) Accelerating and steering right (98) Other action (specify):	36. Accident Type (Note: Applicable codes on back of this
(99) Unknown	page)
(99) Unknown	(00) No impact
24 Bro Impost Cashillan	Code the number of the diagram that best
34. Pre-Impact Stability (0) No driver present	describes the accident circumstance
(1) Tracking	(98) Other accident type (specify):
(2) Skidding longitudinally—rotation less than 30 degrees	(99) Unknown
(3) Skidding laterally—clockwise rotation	
(4) Skidding laterally—counterclockwise rotation	
(7) Other vehicle loss-of-control (specify):	
(9) Precrash stability unknown	
STOP HERE IE GV07 D	DES NOT FOUND 04 40

STOP HERE IF GV07 DOES NOT EQUAL 01 - 49

Category	Configur- ation	ACCIDENT TYPES (includes intent)	
J 6	A. Right Roadside Departure	DRIVE OFF CONTROL/ TRACTION LOSS WITH VEH. PED. ANIM. OTHER	05 CS SPECIFICS UNKNOWN
l Single driver	B. Left Roadside Departure	DRIVE OFF CONTROL/ AVOID COLLISION SPECIFIC ROAD TRACTION LOSS WITH VEH. PED. ANIM. OTHER	10 CS SPECIFICS UNKNOWN
	C. Forward Impact	PARKED VEHICLE STA. OBJECT PEDESTRIAN/ END SPECIFIC OTHER	16 CS SPECIFICS UNKNOWN
ficway	D. Rear-End	20 22 24 26 28 30 (EACH• STOPPED SLOWER 25,26,27 DECEL 29,30,31 SPECIFIC OTHER	- /
II Same Trafficway Same Direction	E. Forward Impact	CONTROL/ TRACTION LOSS 37 AVOID COLLISION AVOID COLLISION OTH TRACTION LOSS WITH VEHICLE WITH OBJECT	H• 42) (EACH• 43) CIFICS SPECIFICS ER UNKNOWN
	F. Sideswipe/ Angle	46 45 45 47 (EACH• 48) SPECIFICS OTHER SPEC	(EACH • 49) CIFICS UNKNOWN
ay cflon	G. Head-On	(EACH • 52) (EACH • 53) SPECIFICS OTHER SPECIFICS UNKNOWN	
Same Trafficway Opposite Direction	H. Forward Impact	55 57 59 61 SPI	CH+ 62) (EACH+ 63) ECIFICS SPECIFICS HER UNKNOWN
=	I. Sideswipe/ Angle	(EACH • 66) (EACH • 67) SPECIFICS OTHER SPECIFICS UNKNOWN	
N Change Trafficway Vehicle Turing	J. Turn Across Path		H• 74) (EACH• 75) EIFICS SPECIFICS EN UNKNOWN
	K. Turn Into Path	77 79 76 78 80 81 82 (EAC) TURN INTO SAME DIRECTION TURN INTO OPPOSITE DIRECTION OTHER	
v Intersecting Paths (Vehice Damage)	L. Straight Paths	00	(EACH+ 91) SPECIFICS UNKNOWN
VI. Miscel- Igneous	M. Backing Etc.	92 93 OTHER VEHICLE OR OBJECT 98 Other Accident Type 99 Unknown Accident Type 00 No impact	

	OCCUPANT RELATED	44. Vehicle Cargo Weight Code weight to pearest
37.	Driver Presence in Vehicle (0) Driver not present (1) Driver present (9) Unknown	Code weight to nearest 10 kilograms. (000) Less than 5 kilograms (454) 4,536 kilograms or more (999) Unknown
38.	Number of Occupants This Vehicle (00-96) Code actual number of occupants for this vehicle (97) 97 or more	Source: INSPECTION ROLLOVER DATA
	(99) Unknown	45. Rollover (00) No rollover (no overturning)
39.	Number of Occupant Forms Submitted AIR BAG RELATED	Rollover (primarily about the longitudinal axis) (01-16) Code the number of quarter turns
40.	Is this an AOPS Vehicle? (0) No (includes unknown) (1) Yes - researcher determined (2) VIN determined air bag system (3) VIN determined automatic (passive) belts (4) VIN determined air bag and automatic (passive) belts	(17) Rollover, 17 or more quarter turns (specify): (98) Rolloverend-over-end (i.e., primarily about the lateral axis) (99) Rollover (overturn), details unknown 46. Rollover Initiation Type (00) No rollover
41.	Air Bag(s) Deployment, First Seat Frontal (0) Not equipped or not available (1) No air bags deployed Single Air Bag Vehicle (2) Driver air bag deployed (3) Driver air bag, unknown if deployed	(01) Trip-over (02) Flip-over (03) Turn-over (04) Climb-over (05) Fall-over (06) Bounce-over (07) Collision with another vehicle
42.	Multiple Air Bag Vehicle (4) Driver side only deployed (5) Passenger side only deployed (6) Driver and passenger side deployed (7) Driver and passenger side unknown if deployed (8) Air bag(s) deployed, details unknown (9) Unknown Air Bag(s) Deployment, Other Than First Seat Frontal (0) Not equipped with an "other" air bag	(08) Other rollover initiation type specify): (98) Rolloverend-over-end (99) Unknown rollover initiation type 47. Location of Rollover Initiation (0) No rollover (1) On roadway (2) On shoulder—paved (3) On shoulder—unpaved (4) On roadside or divided trafficway median (8) Rolloverend-over-end (9) Unknown
	 Deployed during accident (as a result of impact) Deployed inadvertently just prior to accident Deployed, details unknown Deployed as a result of a noncollision event 	48. Rollover Initiation Object Contacted (Note: Applicable codes on back of page) 49. Location on Vehicle Where Initial Principal
	during accident sequence (e.g., fire, explosion, electrical) (5) Unknown if deployed (7) Nondeployed (9) Unknown Specify type of "other" air bag present:	Tripping Force Is Applied (0) No rollover (1) Wheels/tires (2) Side plane (3) End plane (4) Undercarriage (5) Other location on vehicle (specify):
		(6) Non-contact rollover forces (specify):
	VEHICLE WEIGHT ITEMS	(8) Rolloverend-over-end (9) Unknown
43	Vehicle Curb Weight Code weight to nearest 10 kilograms. (045) Less than 454 kilograms (612) 6,124 kilograms or more (999) Unknown 3,148 lbs X.4536 = 1,428 kgs Source:	50. Direction of Initial Roll (0) No rollover (1) Roll right - primarily about the longitudinal axis (2) Roll left - primarily about the longitudinal axis (8) Rolloverend-over-end (9) Unknown roll direction

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

(00) No rollover (01-30) — Vehicle Number	(57) Fence (58) Wall
Noncollision	(59) Building (60) Ditch or culvert
(31) Turn-over — fall-over	(61) Ground
(32) No rollover impact initiation (end-over-end)	(62) Fire hydrant
(34) Jackknife	(63) Curb
(O I) GOCKIIIE	(64) Bridge
Collision With Fixed Object	
(41) Tree (≤ 10 cm in diameter)	(68) Other fixed object (specify):
(42) Tree (> 10 cm in diameter)	(60) Helmon Fred - Head
(43) Shrubbery or bush	(69) Unknown fixed object
(44) Embankment	Calliation with Northwest Obtace
(44) Linbankinent	Collision with Nonfixed Object
IAE) Proglement male on mark form diameters	(70) Passenger car, light truck, van, or other
(45) Breakaway pole or post (any diameter)	vehicle not in-transport
Nanhandraus Dala a Dani	(71) Medium/heavy truck or bus not in-transport
Nonbreakaway Pole or Post	(76) Animal
(50) Pole or post (≤ 10 cm in diameter)	(77) Train
(51) Pole or post (> 10 cm but ≤ 30 cm in	(78) Trailer, disconnected in transport
diameter)	(79) Object fell from vehicle in-transport
(52) Pole or post (> 30 cm in diameter) (53) Pole or post (diameter unknown)	(88) Other nonfixed object (specify):
	(89) Unknown nonfixed object
(54) Concrete traffic barrier	(ee, ee.
(55) Impact attenuator	(98) Other event (specify):
(56) Other traffic barrier (includes guardrail)	(a) a mile at an a lapton y /
(specify):	(99) Unknown event or object

OVERRIDE/UNDERRIDE (THIS VEHICLE)	ACCIDENT RECONSTRUCTION PROGRAMS
51. Front Override/Underride (this Vehicle)	HIGHEST DELTA V
52. Rear Override/Underride (this Vehicle) (0) No override/underride, or not an end-to-end impact between two CDS applicable vehicles, and no medium/heavy truck or bus underride	58. Basis for Total (Resultant) Delta V (highest) (00) No vehicle inspection
Override (see specific CDC) [Between 2 CDS applicable vehicles (Bodytype, GV07=1-49)] (1) 1st CDC (2) 2nd CDC (3) Other not automated CDC (specify):	Delta V Calculated (01) Reconstruction program-damage only routine (02) Reconstruction program-damage and trajectory routine (03) Missing vehicle algorithm
Underride (see specific CDC) (Between 2 CDS applicable vehicles (Bodytype, GV07 = 1-49)) (4) 1st CDC (5) 2nd CDC (6) Other not automated CDC (specify):	Delta V Not Calculated (04) At least one vehicle (which may be this vehicle) is beyond the scope of an acceptable reconstruction program, regardless of collision conditions.
(7) Medium/heavy truck or bus override (of any configuration) (9) Unknown	All vehicles within scope (CDC applicable) of reconstuction program but one of the collision conditions is beyond the scope of the reconstruction program or other acceptable
HEADING ANGLE AT IMPACT FOR HIGHEST DELTA V	reconstruction technique, regardless of adequacy of damage data.
Values: (000)-(359) Code actual value (996) Non-horizontal impact (997) Noncollision (998) Impact with object (999) Unknown 53. Heading Angle For This Vehicle 4 9 4 54. Heading Angle For Other Vehicle	 (05) Rollover (06) Other non-horizontal forces (07) Sideswipe type damage (08) Severe override (09) Yielding object (10) Overlapping damage (11) All vehicle and collision conditions are within scope of one of the acceptable reconstruction
RECONSTRUCTION DATA	programs, but there is insufficient data available, (specify):
55.Towed Trailing Unit (0) No towed unit (1) Yes—towed trailing unit (9) Unknown	
56. Documentation of Trajectory Data for This Vehicle (0) No (1) Yes	(98) Other, (specify):
57. Post Collision Condition of Tree or Pole (For Highest Delta V) (0) Not collision (for highest delta V) with tree or pole (1) Not damaged (2) Cracked/sheared (3) Tilted < 45 degrees (4) Tilted ≥ 45 degrees (5) Uprooted tree (6) Separated pole from base (7) Pole replaced (8) Other (specify):	
(9) Unknown	

COMPUTER GENERAT	ED CRASH SEVERITY
59. Total Delta V Highest	63. Impact Speed Highest 9 9 8
39.0 Nearest kmph (highest)	Nearest kmph (highest)
Nearest kmph (secondary)	Nearest kmph (secondary)
(NOTE: 000 means less than 0.5 kmph) (160) 159.5 kmph and above (999) Unknown Highest	(NOTE: 000 means less than 0.5 kmph) (160) 159.5 kmph and above (998) Trajectory algorithm not run (999) Unknown
60. Longitudinal Component of Delta V + 3 7	DELTA V CONFIDENCE LEVEL
Nearest kmph (highest) Nearest kmph (secondary) (NOTE:000 means greater than -0.5 kmph and less than +0.5 kmph) (±160) ±159.5 kmph and above (999) Unknown	64. Confidence In Reconstruction Program Results (For Highest Delta V) (0) No reconstruction (1) Collision fits model — results appear reasonable (2) Collision fits model — results appear high (3) Collision fits model — results appear low (4) Borderline reconstruction — results appear reasonable
61. Lateral Component of Delta V - Highest - 1 3	OTHER SPEED ESTIMATE
$\frac{-\omega}{13.3}$ Nearest kmph (highest)	Highest 65. Barrier Equivalent Speed
Nearest kmph (secondary) (NOTE:000 means greater than -0.5 kmph and less than +0.5 kmph)	ウ <u>2 3</u> <u>シ7・2</u> Nearest kmph (highest)
(±160) ±159.5 kmph and above (_999) Unknown	Nearest kmph (secondary) (NOTE: 000 means
Highest 62. Energy Absorption	less than 0.5 kmph) (160) 159.5 kmph and above (999) Unknown
/ Nearest 100 joules (secondary)	
(NOTE: 0000 means less than 50 joules) (9997) 999,650 joules or more (9999) Unknown	

ESTIMATED DELTA V **INSPECTION TYPE** 66. Estimated Highest Delta V (Researcher 67. Type of Vehicle Inspection Determined) (0) No inspection (0) Reconstruction Delta V coded (1) Vehicle fully repaired-no damage evident (2) Partial inspection (specify): Estimated Delta V (1) Less than 10 kmph (3) Complete inspection (2) \geq 10 kmph but < 25 kmph (3) \geq 25 kmph but < 40 kmph (4) \geq 40 kmph but < 55 kmph **DELTA V EVENT NUMBER** (5) \geq 55 kmph Other estimates of damage severity 68. Delta V Event Number (6) Minor Code the accident event sequence (7) Moderate number that resulted in the Delta V that (8) Severe has been coded above for this vehicle (99) Unknown (9) Unknown


*** IF THE CDS APPLICABLE VEHICLE WAS NOT INSPECTED (I.E., GV67 = 0), ***

DO NOT COMPLETE THE EXTERIOR AND INTERIOR VEHICLE FORMS

*** IF GV07 DOES NOT EQUAL 01-49, DO NOT COMPLETE ***

THE EXTERIOR VEHICLE, INTERIOR VEHICLE,

OCCUPANT ASSESSMENT, AND OCCUPANT INJURY FORMS.



EXTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM

CRASHWORTHINESS DATA SYSTEM 1. Primary Sampling Unit Number 3. Vehicle Number D59614 2. Case Number - Stratum VEHICLE IDENTIFICATION VIN 1 MELM 5345N6 XXXXXXX Model Year $\frac{9}{2}$ Vehicle Make (specify): MERCURY Vehicle Model (specify): SABLE CL LOCATOR Locate the end of the damage with respect to the vehicle's damaged center point or bumper corner for end impacts or an undamaged axle for side impacts. Specific Impact No. Location of Direct Damage Location of Field L Location of Max Crush ABOVE FRAME LAVEL REAR AXLE

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.


Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

Specific		Direct Damage				<u> </u>	Tome.			T	
Impact Number	Plane of Impact C-Measurements	Width (CDC)	Max Crush	Field L	C ₁	C ₂	C ₃	C₄	C ₅	C ₆	₫D
фl	Bunfer	117	41,5	117	41.5	13.7					
	BRACKETS									·	
	FREE SPACE		31.5		31.5	31.5					
	STAND ADJ.		T15.0		T15.0	+15.0					
	CRUSH		25.¢		25.0						-14.1
φ2	SiLL	119.0	Zine 2	154							-102.
d)	RADIATOR				1.2						
ψı		115		132	1 .	1	397	1	ł		
	FRES SPACE					;	29.5		1		
	STAND ADJ.				+15	715	+15	[†] 15	+15	+15	
	Chusit				23.6	26.1	25.2	21.9	9	\$	

VEHICLE DAMAGE SKETCH TIRE-WHEEL DAMAGE **ORIGINAL SPECIFICATIONS** WHEEL STEER ANGLES a. Rotation physically b. Tire (For locked front wheels or restricted deflated 269.2 Wheelbase cm displaced rear axles only) RF ± Overall Length cm RF / Maximum Width cm RR LR Φ Φ **Curb Weight** kg Within ± 5 degrees Average Track cm (1) Yes (2) No (8) NA (9) Unk. **DRIVE WHEELS** Front Overhang cm TYPE OF TRANSMISSION ØFWD □RWD □4WD Rear Overhang cm ☐ Manual ☐ Automatic Undeformed End Width 145.db cm **Approximate** END SHIFT ≥ 10 CM Engine Size: cyl./displ. 1/6 Cargo Weight kg ☐ Yes ☐ No

MEASUREMENTS IN CENTIMETERS



NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

			CDC	WORKSH	43	Τ					
			CODES FOR	OBJECT CO	NTA	ACTED					
(01-30)	- Vehicle Nu	mber		(5	7)	Fence					
				(5	8)	Wall					
Noncoll	ision					Building					
(31)	(31) Overturn - rollover (excludes end-over-end					Ditch or	culvert				
	(32) Rollover—end-over-end					Ground	Cuivert				
	(33) Fire or explosion					Fire hydrant					
	Jackknife	IOH					rant				
						Curb					
(35)	Other intrauni	t damage (specif	y):			Bridge					
(00)		·		(6	8)	Other fix	ed object (s	specify):			
	Noncollision in										
(38)	Other noncolli	ision (specify):		(6	9)	Unknow	n fixed obje	ct			
(39)	Noncollision -	- details unknow	'n	Collis	sior	with No	nfixed Obje	ct			
								truck, van, o	or other		
Collision	n With Fixed O	bject		•	-		ot in-transp				
	Tree (≤ 10 cm			17	1)			or bus not i	in-transport		
	Tree (> 10 cr					Pedestria		. J. Dus Hot I	dansport		
	Shrubbery or I					Cyclist o					
	Embankment	54311						r conveyanc	е		
(45)	Brooksway na	ala ar paat (am. d	!								
(45)	Dieakaway po	ole or post (any d	iameter)			Vehicle of	occupant				
Manhara		D				Animal					
	akaway Pole or					Train					
		10 cm in diame		(7)	8)	Trailer, d	lisconnected	l in transpor	t		
(51)		> 10 cm but ≤ 3	0 cm in					cle in-transp	ort		
	diameter)			(8)	8)	Other no	nfixed object	ct (specify):			
		> 30 cm in diam									
(53)	Pole or post (c	diameter unknow	n)	(8	9)	Unknow	n nonfixed o	bject			
	Concrete traff			(9)	8)	Other ev	ent (specify):			
	Impact attenu		1 10								
(50)	(specify):	earrier (includes g	uardrail)	(9	9)	Unknowr	n event or o	bject			
***************************************									ī		
		DEFORMA	TION CLASS	SIFICATION B	ΥE	VENT NU	JMBER				
A ! -l A						(4)	(5)				
Accident		(1) (2)				specific	Specific	(6)			
Event Sequence	Object	Direction	Incremental	(3)		ngitudinal	Vertical or	Type of	(7)		
Number	Contacted	of Force	Value of	Deformation		Lateral	Lateral	Damage	Deformation		
Number	Contacted	(degrees)	Shift	Location		ocation	Location	Distribution	Extent		
41	A 2	- 7 M	4.4	=		0		.)	<u>.</u>		
41	42	<u> </u>	$\phi \phi$	<u>r</u>		<u>U</u>	٤_	w	$\mathcal{\underline{\Phi}}_{}$		
	- —										
12	カユ	~ 9 h	d b	L		2	یع	ريز	カっ		
4-	· + -		4				Z	$\mathcal{L}_{\mathcal{L}}$	<u>42</u>		
	·										
	· 										
											

		COLLISION	DEFORMA	TION CLAS	SIFICATIO	N	
HIGHEST I	DELTA "V"						
Accident Event Sequence Number	Object Contacted 5. ϕ \neq	(1) (2) Direction of Force 6	(3) Deformation Location 7. <u>F</u>	(4) Longitudinal or Lateral Location 8.	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent 11. ϕ
Second Hig	ghest Delta "V"						~ ~~ ~ .
12. <u>\$</u> 2	13. <u>\$\phi\$</u> 2	14. ϕ 9	15. <u>L</u>	16. <u>Z</u>	17. <u>E</u>	18. <u> </u>	19. <u>\$\phi_2</u>
		CRUS	H PROFILE	IN CENTIM	ETERS		
			nage described below. (ALL M				
HIGHEST D	ELTA "V"						
20. L	21. 	C ₂	C ₃		C ₅	C _e	22. ±D
145	ф <u>24</u>	φ 24	<u> 0 25 </u>	122 ¢	<u>\$9</u> \$;	\$\$ `	\$1 <u>4</u>
Second Hig	hest Delta "V"						
23. L	24. C,		C ₃		<u>C₅</u>	C ₆ 2	± D
(Coded impact i (250) (998) (999) (77. Direct D (For high	med End Width when highest se an end plane code to the nea 250 centimeters No highest seve Unknown camage Width hest severity im Code to the nea 250 centimeters	everity impact.) irest centimeter s or more rity end plane in pact) rest centimeter	mpact	(650) (650) (999) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650) (650)	Wheelbase Code to the neadentimeter S50 centimeter Unknown	s or more 2.54 = Width	2 6 9 _ centimeters (F

			FUEL SYSTEM
30.	Are CDCs Documented but Not Coded on The Automated File? (0) No (1) Yes	<u>\$</u>	35. Location of Fuel Tank-1 Filler Cap 36. Location of Fuel Tank-2 Filler Cap (0) No fuel tank (1) On back plane (2) Aft of center of the rear wheels (rear axle) on left side plane
31.	Researcher's Assessment of Vehicle Disposition (0) Not towed due to vehicle damage (1) Towed due to vehicle damage (9) Unknown	<u>L</u>	 (3) Aft of center of the rear wheels (rear axle) on right side plane (4) Forward of center of the rear wheels (rear axle) on left side plane (5) Forward of center of the rear wheels (rear axle) on right side plane (6) Over the center of the rear wheels (rear axle)
32.	Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? (0) No post manufacturer modifications (1) Yes - post manufacturer modifications (specify):	<u> </u>	on left side plane (7) Over the center of the rear wheels (rear axle) on right side plane (8) Other (specify): (9) Unknown 37. Type of Fuel Tank-1
	(Include photograph of CERTIFICATION PLACARD in case report) (9) Unknown if vehicle is modified		38. Type of Fuel Tank-2 (0) No fuel tank (electrical vehicle) (1) Metallic (2) Non-metallic (9) Unknown
	FIRE OCCURRENCE		39. Location of Fuel Tank-1
34.	Fire Occurrence (0) No fire Yes, fire occurred (1) Minor (2) Major (9) Unknown Origin of Fire (0) No fire (1) Vehicle exterior (front, side, back, top) (2) Exhaust system (3) Fuel tank (and other fuel retention system parts) (4) Engine compartment (5) Cargo/trunk compartment (6) Instrument panel (7) Passenger compartment area (8) Other location (specify):	 	40. Location of Fuel Tank-2 (0) No fuel tank (1) Aft of center of the rear wheels (rear axle) centered (2) Aft of center of the rear wheels (rear axle) left side (3) Aft of center of the rear wheels (rear axle) right side (4) Forward of center of the rear wheels (rear axle) centered (5) Forward of center of the rear wheels (rear axle) left side (6) Forward of center of the rear wheels (rear axle) right side (7) Over center of the rear wheels (rear axle) right side (8) Other (specify): (9) Unknown 41. Damage to Fuel Tank-1 42. Damage to Fuel Tank-2 (0) No fuel tank (1) No damage to fuel tank (2) Deformed, no seam failure
	(9) Unknown		(2) Deformed, no seam failure (3) Deformed, with a seam failure (4) Punctured (5) Lacerated (ripped) (6) Abraded (scraped) (7) Filler neck separation from the fuel tank (8) Other damage (specify): (9) Unknown

			·		
43.	Leakage Location of Fuel System-1	1		his Vehicle Equipped With More Than	1
44.	Leakage Location of Fuel System-2	ıb	1	Fuel Tanks? No (one or two tanks only)	
	(0) No fuel tank	4	(0)	140 (one of two tanks offly)	
	(1) No fuel leakage		Yes	- More Than Two Tanks	
			1	Yes no damage to any tank or filler	
	Primary Area Of Leakage		'''	cap and no fuel system leakage	
	(2) Tank		(2)	Yes no damage to any tank or filler	
	(3) Filler neck		, ,	cap but there is fuel system leakage	
	(4) Cap			(specify leakage location):	
	(5) Lines/pump/filter				
	(6) Vent/emission recovery		(3)	Yes damage to an additional tank or	
	(8) Other (specify):			filler cap and there is fuel system leakage	
	(9) Unknown		-	(specify the following):	
				Type of tank	
46	Eval Type 1	h 1		lank location	
40.	Fuel Type-1	4-	ĺ	Filler cap location	_
46	Fuel Type-2	44		rank damade	
₩.	ruer rype-2	44		Location of leakage	_
	Single Fuel Type		(9)	Type of fuelUnknown if more than two tanks	-
	(00) No fuel tank		(3)	Chichewit it more than two tanks	
	(01) Gasoline				
	(02) Diesel				
	(03) CNG (Compressed Natural Gas)			COMMENTS	
	(04) LPG (Liquid Petroleum Gas) also				
	known as Propane				
	(05) LNG (Liquid Natural Gas)				
	(06) Methanol (M100 or M85)				
	(07) Ethanol (E100 or E85)				
	(08) Other (Hydrogen or others) (specify):				
	Electric Powered or Electric/Solar				
	Powered Vehicles				
	(10) Lead Acid Battery	İ			
	(11) Nickel-Iron Battery				
	(12) Nickel-Cadmium Battery	i			
	(13) Sodium Metal Chloride Battery	ļ			
	(14) Sodium Sulfur Battery	i			
	(18) Other (Specify):		***		
	(98) Other Hybrid (specify):				
	(99) Unknown fuel type		-		
	1007 Chikhowh luel type				
		Ì			
	*** STOD: IE THE ODS AT			LE MAC NOT TOMED ***	

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED ***

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.

INTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM ATA SYSTEM

contact and not holed by occupant contact

occupant contact

(7) Glazing removed prior to accident (8) Glazing disintegrated by occupant contact (9) Unknown if contacted by occupant


(6) Glazing out-of-place by occupant contact and holed by

Administration	CRASHWORTHINESS DATA SYST
1. Primary pampling Unit Number	GLAZING
	Type of Window/Windshield Glazing
2. Case Number - Stratum DS 961 \$\psi\$	15. WS 16. LF 1 17. RF 1 18. LR 4 19. RR 4
3. Vehicle Number	20. BL <u>4</u> 21. Roof <u>d</u> >22. Other <u>4</u>
INTEGRITY	(0) No glazing
4. Passenger Compartment Integrity (00) No integrity loss Yes, Integrity Was Lost Through (01) Windshield (02) Door (side) (03) Door/hatch (back door) (04) Roof (05) Roof glass (06) Side window (07) Rear window (backlight) (08) Roof and roof glass (09) Windshield and door (side) (10) Windshield and roof (11) Side and rear window (side window and backlight) (12) Windshield and side window (13) Door and side window (98) Other combination of above (specify):	(1) AS-1 — Laminated (2) AS-2 — Tempered (3) AS-3 — Tempered-tinted (original) (4) AS-2 — Tempered-with after market tint (5) AS-3 — Tempered-tinted (with additional after market tint) (6) AS-14 — Glass/Plastic (7) Glazing removed prior to accident (8) Other (specify): (9) Unknown Window Precrash Glazing Status 23. WS / 24. LF / 25. RF / 26. LR / 27. RR / 28. BL / 29. Roof / 30. Other / (0) No glazing (1) Fixed (2) Closed (3) Partially opened (4) Fully opened (7) Glazing removed prior to accident (9) Unknown
Door, Tailgate or Hatch Opening	Glazing Damage from Impact Forces
5. LF <u>/</u> 6. RF <u>/</u> 7. LR <u>/</u> 8. RR <u>/</u> 9. TG/H <u></u>	31. WS <u>2</u> 32. LF <u>/</u> 33. RF <u>/</u> 34. LR <u>/</u> 35. RR <u>/</u>
(0) No door/gate/hatch (1) Door/gate/hatch remained closed and operational (2) Door/gate/hatch came open during collision (3) Door/gate/hatch jammed shut (8) Other (specify):	36. BL / 37. Roof 38. Other / (0) No glazing (1) No glazing damage from impact forces (2) Glazing in place and cracked from impact forces (3) Glazing in place and holed from impact forces (4) Glazing out-of-place (cracked or not) and not holed from impact forces (5) Glazing out-of-place and holed from impact forces
Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then code Ø	(6) Glazing disintegrated from impact forces(7) Glazing removed prior to accident(9) Unknown if damaged
10. LF ϕ 11. RF ψ 12. LR ϕ 13. RR ϕ 14. TG/H ϕ	Glazing Damage from Occupant Contact
(0) No door/gate/hatch or door not opened	39. WS <u>/</u> 40. LF <u>/</u> 41. RF <u>/</u> 42. LR <u>/</u> 43. RR <u>/</u>
Door, Tailgate or Hatch Came Open During Collision (1) Door operational (no damage) (2) Latch/striker failure due to damage (3) Hinge failure due to damage (4) Door structure failure due to damage (5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage (6) Latch/striker and binge failure due to damage	44. BL 45. Roof 46. Other (0) No glazing (1) No occupant contact to glazing (2) Glazing contacted by occupant but no glazing damage (3) Glazing in place and cracked by occupant contact (4) Glazing in place and holed by occupant contact (5) Glazing out-of-place (cracked or not) by occupant

(9) Unknown

(8) Other failure (specify):

(6) Latch/striker and hinge failure due to damage




LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are COMPARISON INTRUDE VALUE — VALUE	ED INTRUSION	DOMINANT CRUSH DIRECTION
	φ5	69.5 - 60.6	= 9.5	2
11	18	22 \$ - 25 \$	= 3.p	1
13	φ4		= //>	3
13	b4	_	= 2.5	2_
11	27	_	= 1\$	3
		_	=	
		· -	=	
		_	=	
		_	=	
		_	=	
		_	=	
		_	=	
		_	=	
		_	=	
			=	

OCCUPANT AREA INTRUSION Note: If no intrusions, leave variables IV47-IV86 blank. INTRUDING COMPONENT **Dominant** Interior Components Intruding Location of Magnitude Crush (01) Steering assembly Intrusion Direction Component of Intrusion (02) Instrument panel left (03) Instrument panel center (04) Instrument panel right 48. Z 7 49. Z 50. (05) Toe pan (06) A (A1/A2)-pillar (07) B-pillar (08) C-pillar <u>1</u> 52. φ 5 53. 2 54. 2 (09) D-pillar (10) Side panel - forward of the A1/A2-pillar (11) Door panel (side) (12) Side panel - rear of the B-pillar (13) Roof (or convertible top) (14) Roof side rail (15) Windshield (16) Windshield header 4th 59. 60. 61. 62. (17) Window frame (18) Floor pan (includes sill) (19) Backlight header (20) Front seat back 5th 63.___ 64.__ 65. 66. (21) Second seat back (22) Third seat back (23) Fourth seat back (24) Fifth seat back 6th 67. 68. 70._ 69. (25) Seat cushion (26) Back door/panel (e.g., tailgate) (27) Other interior component (specify): L- WINDOW FRAME PLASTIC COVER 7th 71.___ 72. 73. **Exterior Components** (30) Hood 8th 75.___ 76.__ 77.__ (31) Outside surface of this vehicle (specify): 78. (32) Other exterior object in the environment (specify): 9th 79.___ 80.__ 81.__ (33) Unknown exterior object 82. (97) Catastrophic (98) Intrusion of unlisted component(s) (specify): 10th 83.___ 84.__ 85. ___ 86. (99) Unknown LOCATION OF INTRUSION MAGNITUDE OF INTRUSION (1) ≥ 3 centimeters but < 8 centimeters Front Seat Fourth Seat (2) ≥ 8 centimeters but < 15 centimeters (11) Left (41) Left (3) ≥ 15 centimeters but < 30 centimeters (12) Middle (42) Middle (4) ≥ 30 centimeters but < 46 centimeters (13) Right (43) Right (5) ≥ 46 centimeters but < 61 centimeters (6) ≥ 61 centimeters Second Seat (97) Catastrophic (7) Catastrophic (21) Left (98) Other enclosed (9) Unknown (22) Middle area (specify) (23) Right (99) Unknown **DOMINANT CRUSH DIRECTION** Third Seat (1) Vertical (31) Left (32) Middle (2) Longitudinal (3) Lateral (33) Right (7) Catastrophic

(9) Unknown

	(All Meas	rements Are in Centime	iters)	
COMPARISON VALUE	- 0	DAMAGE VALUE	=	DEFORMATION
	Z		=	
	_		=	
			=	
			=	
	•			

STEERING COLUMN	INSTRUMENT PANEL
87. Steering Column Type	92. Odometer Reading / / / / ,000
(1) Fixed column (2) Tilt column (3) Telescoping column (4) Tilt and telescoping column (8) Other column type (specify):	kilometers Code to the nearest 1,000 kilometers (000) No odometer (001) Less than 1,500 kilometers (500) 499,500 kilometers or more (999) Unknown L. 2. 591 miles x 1.6093 = 144 728 kilometers
88. Tilt Steering Column Adjustment (0) No tilt steering column (1) Full up (2) Between full up and center (3) Center (4) Between center and full down (5) Full down (9) Unknown	Source: VEHICLE INSPECTION 93. Instrument Panel Damage from Occupant Contact? (0) No (1) Yes (9) Unknown 94. Type of Knee Bolster Covering
89. Telescoping Steering Column Adjustment (0) No telescoping steering column (1) Full back (2) Between full back and midpoint (3) Midpoint (4) Between midpoint and full forward (5) Full forward (9) Unknown	(0) No knee bolster (1) Padded (2) Rigid plastic (8) Other (specify): (9) Unknown 95. Knee Bolsters Deformed from Occupant Contact? (0) No knee bolster (1) No deformation (2) Yes - deformation (9) Unknown
90. Steering Rim/Spoke Deformation Code actual measured deformation to the nearest centimeter (00) No steering rim deformation (01-14) Actual measured value in centimeters (15) 15 centimeters or more (98) Observed deformation cannot be measured (99) Unknown	96. Did Glove Compartment Door Open During Collision(s)? (0) No glove compartment door (1) No - door did not open (2) Yes - door opened (9) Unknown
91. Location of Steering Rim/Spoke Deformation (00) No steering rim deformation Quarter Sections (01) Section A (02) Section B (03) Section C (04) Section D Half Sections (05) Upper half of rim/spoke (06) Lower half of rim/spoke (07) Left half of rim/spoke (08) Right half of rim/spoke (09) Complete steering wheel collapse (10) Undetermined location (99) Unknown	97. Adaptive (Assistive) Driving Equipment (0) No adaptive driving equipment (1) Adaptive driving equipment installed (Check all that apply.) [] Hand controls for braking/acceleration [] Steering control devices (attached to OEM steering wheel [] Low effort power steering (unit or device) [] Replacement steering wheel (i.e., reduced diameter) [] Joy-stick steering controls [] Wheelchair tie-downs [] Modification to seat belts (specify): [] Additional or relocated switches (specify): [] Raised roof [] Wall-mounted head rest (used behind wheelchair) [] Other adaptive device (specify): (9) Unknown



POINTS OF OCCUPANT CONTACT					
Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
Α	170	i	_	Deployed	2
В	DID		L-KNEZ	DENTED BOLSTER	2
С	\$11'		R-KNEE	DENTED BOLSTER	2.
D	254	1		MOVED - JAMMED	3
E	254	1		MEYED - JAMMED TO PLEHT	3
F	Ø\$3	1	-	SCURF - INDENTATION	3
G	245			SCOFF - INDENTATION	3
Н	180	2	FACE, CHEST		1
l	110	2		Missing VINT	9
J	Ø19			COIN TRAY KNOCKED DOWN	9
K	dil		_	HEATER MODULE Missing	9
L	\$59	1	HEAD	INJURY PLASTIC COVER INTRUSIO) Z
М			J)	
N					

FRONT CODES FOR INTERIOR COMPONENTS REAR (001) Windshield (301) Backlight (rear window) (002) Mirror LEFT SIDE INTERIOR (302) Backlight storage rack, (003) Sunvisor (051) Left side interior surface, (151) Seat, back support door, etc. (004) Steering wheel rim excluding hardware or (152) Belt restraint (303) Other rear object (specify): (005) Steering wheel hub/spoke armrests webbing/buckle (006) Steering wheel (combination (052) Left side hardware or Belt restraint B-pillar or door of codes 004 and 005) armrest frame attachment point ADAPTIVE (ASSISTIVE) DRIVING (007) Steering (053) Left A (A1/A2)-pillar (154) Other restraint system EQUIPMENT column, transmission (054) Left B-pillar component (specify): (401) Hand controls for selector lever, other (055) Other left pillar (specify): braking/acceleration attachment (155) Head restraint system (402) Steering control devices (008) Cellular telephone or CB (056) Left side window glass (160) Other occupants (specify): (attached to OEM steering radio (057) Left side window frame wheel) (009) Add on equipment(e.g., (058) Left side window sill (161) Interior loose objects (403) Steering knob attached to tapedeck, air conditioner) (059) Left side window glass (162) Child safety seat (specify): steering wheel (010) Left instrument panel and including one or more of the (405) Replacement steering wheel below following: frame, window (163) Other interior object (i.e., reduced diameter) (011) Center instrument panel and sill, A (A1/A2)-pillar, B-(specify): (406)Joy stick steering controls below pillar, or roof side rail. (407) Wheelchair tie-downs (012) Right instrument panel and (060) Other left side object AIR BAG (408) Modification to seat belts. below (specify): (170) Air bag-driver side (013) Glove compartment door (175) Air bag compartment (specify): (014) Knee bolster RIGHT SIDE cover-driver side (409) Additional or relocated (015) Windshield including one or (101) Right side interior surface, (180) Air bag-passenger side switches, (specify): more of the following: front excluding hardware or (185) Air bag compartment header, A (A1/A2)-pillar. armrests cover-passenger side instrument panel, mirror, or (102) Right side hardware or (190) Other air bag (specify) (410) Raised roof steering assembly (driver armrest (411) Wall mounted head rest side only) (103) Right A (A1/A2)-pillar (used behind wheel chair) (016) Windshield including one or (104) Right B-pillar (195) Other air bag compartment (412) Other adaptive device more of the following: front (105) Other right pillar (specify): cover (specify) (specify): header, A (A1/A2)-pillar. instrument panel, or mirror (106) Right side window glass (passenger side only) (107) Right side window frame (017) Windshield reinforced by (108) Right side window sill ROOF extenor object, (specify): (109) Right side window glass (201) Front header including one or more of the (202) Rear header (019) Other front object (specify): following: frame, window sill, A (A1/A2)-pillar, B-(203) Roof left side rail (204) Roof right side rail pillar, or roof side rail. (205) Roof or convertible top (110) Other right side object (specify): VENT **FLOOR** (251) Floor (including toe pan) (252) Floor or console mounted transmission lever, including CONFIDENCE LEVEL OF CONTACT

console

(253) Parking brake handle

parking brake

(254) Foot controls including

POINT

Certain

Probable

Possible

Unknown

(1)

(2)

(3)

(9)

BEST AVAILABLE MANUAL RESTRAINTS NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form. If a child safety seat is present, encode the data on the back of this page 11. If the vehicle has automatic restraints available, encode the appropriate data on page 6. Left Center Right 3 A-Availability 40ADING CURL CURLING, Wilbony CURLING LOADING B-Evidence of usage SCRATCHED LATCH TRAIN! DRING C-Used in this crash? かゆ R **D-Proper Use** S E-Failure Modes F-Anchorage Adjustment A-Availability 3 PLATES B-Evidence of usage SCRATCHED LATCH SECO C-Used in this crash? \$ B JY X ÐΦ **D-Proper Use** W ŇD **E-Failure Modes** Φ 0 D F-Anchorage Adjustment A-Availability B-Evidence of usage 0 T C-Used in this crash? H **D-Proper Use** Ε E-Failure Modes R F-Anchorage Adjustment A-Manual (Active) Belt System Availability D-Proper Use of Manual (Active) Belts F-Shoulder Belt Upper Anchorage Adjustment (0) None available None used or not available (0) No shoulder belt (1) Belt removed/destroyed (1) Belt used properly No upper anchorage adjustment for (1) (2) Shoulder belt (2) Belt used properly with child safety shoulder belt (3) Lap belt (4) Lap and shoulder belt Adjustable shoulder Belt Upper (5) Belt available - type unknown Belt Used Improperly Anchorage Shoulder belt worn under arm (3) (2)In full up position Integral Belt Partially Destroyed Shoulder belt worn behind back or (4)(3) In mid position (6) Shoulder belt (lap belt seat (4)In full down position destroyed/removed) (5)Belt worn around more than one (5)Position unknown (7) Lap belt (shoulder belt person Unknown if position has adjustable (9) destroyed/removed) (6) Lap belt worn on abdomen upper anchorage adjustment (8) Other belt (specify): (7)Lap belt or lap and shoulder belt used improperly with child safety seat (specify): (9) Unknown (8) Other improper use of manual belt system (specify): B/C-Manual (Active) Belt System Use (00) None used, not available, or belt Unknown removed/destroyed (01) Inoperable (specify): E-Manual (Active) Belt Failure Modes During (02)Shoulder belt Accident (03)Lap belt (0) No manual belt used or not available (04)Lap and shoulder belt (1) No manual belt failure(s) (05) Belt used - type unknown (2) Torn webbing (stretched webbing (80)Other belt used (specify): not included) (3) Broken buckle or latchplate (12)Shoulder belt used with child safety (4) Upper anchorage separated (5) Other anchorage separated (13)Lap belt used with child safety seat (specify): Lap and shoulder belt used with (14)(6) Broken retractor child safety seat (7)Combination of above (specify): Belt used with child safety seat -(15) type unknown (8) Other manual belt failure (specify): Other belt used with child safety (18)

seat (specify):

Unknown if belt used

(9)

Unknown

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

Ain BAGS				
		Frontal Air BagsLeft Front	Frontal Air Bags-Right Front	OtherAir Bag
F	Availability/Function	1	/	Φ
R	Deployment	1	1	\$
5 T	Failure	,	/	27

Air Bag System Availability/Function

- (0) Not equipped/not available
- (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):
- (3) Air bag not reinstalled
- (9) Unknown

Air Bag System Deployment (This Occupant Position)

- (0) Not equipped/not available
- (1) Deployed during accident (as a result of impact)
- (2) Deployed inadvertently just prior to accident
- (3) Deployed, accident sequence undetermined
- (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (5) Unknown if deployed
- (7) Nondeployed
- (9) Unknown

Are There Indications of Air Bag System Failure? (This Occupant Position)

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (9) Unknown

AUTOMATIC BELTS

		Left	Right
	A-Availability/Function	φ	Ф
F	B-Use	φ	ψ
R	C-Type	Φ	4
5 T	D-Proper Use	ψ	4
	E-Failure Modes	\$	Ø

A-Automatic (Passive) Belt System Availability/Function

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

B-Automatic (Passive) Belt System Use

- (O) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative)
- (3) Automatic belt use unknown
- (9) Unknown

C-Automatic (Passive) Belt System Type

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

D-Proper Use of Automatic (Passive) Belt System

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):

- (8) Other improper use of automatic belt system (specify):
- (9) Unknown

E-Automatic (Passive) Belt Failure Modes During Accident

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):
- (6) Broken retractor
- (7) Combination of above (specify):
- (8) Other automatic belt failure (specify):
- (9) Unknown

FIRST SEAT FRONTAL AIR BAGS

NOTES: Encode the applicable data *for the driver and first seat passenger* in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger	
A-Type of air bag?	/		
B-Flaps open at tear points?	2	~_	
C-Flaps damaged?	1	(
D-Air bag damaged?	41	<i>Φ</i> I	
E-Source of air bag damage	φl	ΦI	
F-Air bag tethered?	2.2	7	
G-Air bag have vent ports?	22	2,2	
H-Other occupant contact air bag?			
I-Occupant wearing eyewear?	2	1	

A-Type of Air Bag

- (0) Not equipped/not available
- (1) Original manufacturer installed system
- (2) Retrofitted air bag
- (3) Replacement air bag
- (8) Unknown type of air bag
- (9) Unknown

B-Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?

- (0) Not equipped/not available
- (1) No
- (2) Yes
- (3) Deployed, unknown if flap(s) opened at designated tear points
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

C-Were Air Bag Module Cover Flap(s) Damaged?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if air bag module cover flap(s) damaged
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

D-Was There Damage To The Air Bag?

- (00) Not equipped/not available
- (01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured
- (03) Cut
- (04) Torn
- (05) Holed
- (06) Burned
- (07) Abraded
- (88) Other damage (specify):
- (95) Damaged, details unknown
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

E-Source of Air Bag Damage

- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify):
- (03) Object carried by occupant, (specify):
- (04) Adaptive/assistive controls, (specify):
- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (88) Other damage source (specify):
- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

F-Was The Air Bag Tethered?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps):
- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

G-Did The Air Bag Have Vent Ports?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports):
- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

H-Was the Air Bag in this Occupant's Position Contacted by Another Occupant?


- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if other occupant contact to air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

I-Was This Occupant Wearing Eye-wear?


- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)



DRIVER AIR BAG SKETCHES (Cont'd)

3. DRIVER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

> width (W_U) _____ width (W_L) ____ height (H)


4. DRIVER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

Upper Flap

b. Lower Flap


width (W_U) $2\psi.5$ width (W_L) $2\psi.5$

height (H_u) /6 5 height (H_L) 7.9



- 5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE
- 6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS


7. SKETCH LOCATION OF CIRCULAR AIR BAG VENT **PORTS** 2,5 cm




PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)





2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)




PASSENGER AIR BAG SKETCHES (Cont'd)

3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

width (W) _____

height (H)




4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

b. Lower Flap

width (W_0) 3j, 3 width (W_L) 3j. 3

height (H_u) 5.5 height (H_L) 5.5



5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS 65cm DIAMETER

"OTHER" AIR BAG DAMAGE AND CONTACT SKETCHES
1. SKETCH DAMAGE AND CONTACT EVIDENCE ON "OTHER" AIR BAG (Front)
2. SKETCH DAMAGE AND CONTACT EVIDENCE ON "OTHER" AIR BAG (Back)

"OTHER" AIR BAG SKETCHES (Cont'd)
3. SKETCH AIR BAG MODULE FLAP AND SIZE OR OPENING FOR AIRBAG
4. SKETCH AIR BAG VENT PORTS

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found on the next page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
	A-Head Restraint Type/Damage	3	ψ	3
	B-Seat Type	Ø6	06	ФЬ
_	C-Seat Orientation)	j
<u>.</u>	D-Seat Track Position	5	5	5
R S	E-Seat Back Incline Pre/Post Impact	100 14	<i>\$1</i>	Q3 33 ⁻⁵
T	F-Seat Performance	1)	1
	A-Head Restraint Type/Damage	,	ψ	1
h H	B-Seat Type	Φ3	43	ψ3
	C-Seat Orientation	1)
S E	D-Seat Track Position	1	1	i
CO	E-Seat Back Incline Pre/Post Impact	ψ1	(b)	ıbl
N	F-Seat Performance	1	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1
	A-Head Restraint Type/Damage	_	/	/
	B-Seat Type			
_	C-Seat Orientation			
H	D-Seat Track Position			
R	E-Seat Back Incline Pre/Post Impact			
D	F-Seat Performance	/		
	A-Head Restraint Type/Damage			-
	B-Seat Type			
0	C-Seat Orientation			
T H	D-Seat Track Position			
E	E-Seat Back Incline Pre/Post Impact			
R	F-Seat Performance			

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE (I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

HEAD RESTRAINTS/SEAT EVALUATION

A-Head Restraint Type/Damage by Occupant at This Occupant Position

- (0) No head restraints
- (1) Integral no damage(2) Integral damaged during accident
- (3) Adjustable no damage
- (4) Adjustable damaged during accident
- (5) Add-on no damage
- (6) Add-on damaged during accident
- Other Specify):
- (9) Unknown

B-Seat Type (this Occupant Position)

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09)Box mounted seat (i.e., van type)
- (10) Other seat type (specify):
- (99) Unknown

C-Seat Orientation (this Occupant Position)

- (0)Occupant not seated or no seat
- Forward facing seat (1)
- (2)Rear facing seat
- (3) Side facing seat (inward)
- Side facing seat (outward) (4)
- (8) Other (specify):
- (9)Unknown

D-Seat Track Adjusted Position Prior To Impact

- (0)Occupant not seated or no
- (1) Non-adjustable seat track

Adjustable Seat Track

- (2)Seat at forward most track position
- (3)Seat between forward most and middle track positions
- Seat at middle track position
- (5)Seat between middle and rear most track positions
- (6)Seat at rear most track position
- (9)Unknown

E-Seat Back Incline Prior and Post **Impact**

- (00)Occupant not seated or no seat
- (01)Not adjustable

Upright prior to impact

- (11) Moved to completely rearward position
- (12)Moved to rearward midrange position
- (13)Moved to slightly rearward position
- (14)Retained pre-impact position
- (15)Moved to slightly forward position
- (16)Moved to forward midrange position
- (17)Moved to completely forward position

Slightly reclined prior to impact

- Moved to completely rearward position
- (22)Moved to rearward midrange position
- (23)Retained pre-impact postion
- (24)Moved to upright position
- (25)Moved to slightly forward position
- (26)Moved to forward midrange position
- (27)Moved to completely forward position

Completely reclined prior to impact

- Retained pre-impact position
- (32)Moved to rearward midrange position
- (33)Moved to slightly rearward position
- (34)Moved to upright position
- (35) Moved to slightly forward position
- Moved to forward midrange (36)position
- (37)Moved to completely forward position
- (99) Unknown

34 33 35 36 32 37 31

14 13

12

22

21

11

15

25

26

27

16

17

F-Seat Performance (this Occupant Position)

- (0)Occupant not seated or no seat
- (1)No seat performance failure(s)
- (2) Seat adjusters failed
- (3)Seat back folding locks or "seat back" failed (specify):
- (4)Seat tracks/anchors failed
- (5)Deformed by impact of occupant
- (6)Deformed by passenger compartment intrusion (specify):
- (7)Combination of above (specify):
- (8)Other (specify):
- (9) Unknown

Coding diagrams for Seat Back Incline Position Prior and Post Impact

the occupant's number using the codes listed bel	cupant's number in the first row and complete the column below. Complete a column for each child safety seat present.
Occupant Number	
1. Type of Child Safety Seat	
2. Child Safety Seat Orientation	16
3. Child Safety Seat Harness Usage	NOW
4. Child Safety Seat Shield Usage	
5. Child Safety Seat Tether Usage	
6. Child Safety Seat Make/Model	
Specify Below 1. Type of Child Safety Seat	v for Each Child Safety Seat
(0) No child safety seat	3. Child Safety Seat Harness Usage
(1) Infant seat (2) Toddler seat	4. Child Safety Seat Shield Usage
(3) Convertible seat	
(4) Booster seat	5. Child Safety Seat Tether Usage
(7) Other type child safety seat (specify):	Note: Options Below Are Used for Variables 3-5
(8) Unknown child safety seat type	(00) No child safety seat
(9) Unknown if child safety seat used	Not Designed with Harness/Shield/Tether (01) After market harness/shield/tether
2. Child Safety Seat Orientation	added, not used
(00) No child safety seat	(02) After market harness/shield/tether used
Designed for Rear Facing for	(03) Child safety seat used, but no after marke harness/shield/tether added
This Age/Weight	(09) Unknown if harness/shield/tether
(01) Rear facing	added or used
(02) Forward facing	5
(08) Other orientation (specify):	Designed With Harness/Shield/Tether
(09) Unknown orientation	(11) Harness/shield/tether not used (12) Harness/shield/tether used (19) Unknown if harness/shield/tether used
Designed for Forward Facing for This	
Age/Weight (11) Rear facing	Unknown If Designed With Harness/Shield/Tethe
(12) Forward facing	(21) Harness/shield/tether not used (22) Harness/shield/tether used
(18) Other orientation (specify):	(29) Unknown if harness/shield/tether used
(19) Unknown orientation	(99) Unknown if child safety seat used
Unknown Design or Orientation For This	6. Child Safety Seat Make/Model
Age/Weight, or Unknown Age/Weight	(Specify make/model and occupant number)
(21) Rear facing	
(22) Forward facing (28) Other orientation (specify):	
(29) Unknown orientation	
(99) Unknown if child safety seat used	

EJECTION	/ENTRAPM	ENT DATA
----------	----------	-----------------

e vehicle. Code the appropriate data on the Occupant Assessment Form. EJECTION No [] Yes [] Describe indications of ejection and body parts involved in partial ejection(s):						
escribe indications of ejection and	body parts in	voived in partia	i ejection(s	;):		
		· · · · · · · · · · · · · · · · · · ·				
	w					
	· · · · · · · · · · · · · · · · · · ·					
Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						
ction 1) Complete ejection	(7) Roof	f er area (e.g., ba	ck of		gral structure er medium (spe	cify):
(2) Partial ejection		up, etc.) (specif				
(3) Ejection, Unknown degree (9) Unknown	(9) Unki	nown		(9) Unk	nown	
ontine A					tatus (Immedia	tely Pric
oction Area (1) Windshield	Ejection M	ledium r/hatch/tailgate		to impact) (1) Ope		
(2) Left front	(2) Nont	fixed roof struct	ture	(2) Clos		
(3) Right front	(3) Fixed	(3) Fixed glazing			gral structure	
(4) Left rear (5) Right rear	(4) Nont	fixed glazing (sp	pecify):	(9) Unk	nown	
(6) Rear						
TRAPMENT No. 1 Yes [1				-	
scribe entrapment mechanism:						
						
mponent(s):						

OCCUPANT ASSESSMENT FORM

Form Approved O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number		OCCUPANT'S SEATING	
	1614	10. Occupant's Seat Position	11
		Front Seat	
3. Vehicle Number	<u> </u>	(11) Left side	
4. Occupant Number	Å 1	(12) Middle (13) Right side	
	<u>φ</u>	(14) Other (specify):	
OCCUPANT'S CHARACTERIS	STICS	(15) On or in the lap of another occupant	
5. Occupant's Age	68	Second Seat	
Code actual age at time of accident.		(21) Left side	
(00) Less than one year old (specify by	month):	(22) Middle	
_		(23) Right side	
(97) 97 years and older		(24) Other (specify):	
(99) Unknown		(25) On or in the lap of another occupant	-
		Third Seat	
	1	(31) Left side	
6. Occupant's Sex	1	(32) Middle	
(1) Male		(33) Right side	
(2) Female-not reported pregnant		(34) Other (specify):	
(3) Female-pregnant-1st trimester(1st-3	Brd month)	(35) On or in the lap of another occupant	
(4) Female-pregnant-2nd trimester(4th-	6th month)		
(5) Female-pregnant-3rd trimester(7th-9(6) Female-pregnant-term unknown	9th month)	Fourth Seat	
(9) Unknown		(41) Left side	
(O) OHKHOWII		(42) Middle	
		(43) Right side	
		(44) Other (specify):	
7. Occupant's Height Code actual height to the nearest	178	(45) On or in the lap of another occupant (97) In or on unenclosed area	
centimeter.		(98) Other seat (specify):	
(999) Unknown		(99) Unknown	
7 \$\psi\$ inches X 2.54 = centimeters	S		
8. Occupant's Weight	1 40	11. Occupant's Posture	A
Code actual weight to the nearest	-44	(0) Normal posture	4
kilogram.		·	
(999) Unknown		Abnormal posture	
7 2 1		(1) Kneeling or standing on seat(2) Lying on or across seat	
22⊈ pounds X .4536 = kilogr	rams	(3) Eying on or across seat (3) (3) (3) (4) (3) (4) (4) (5)	004
	j	(4) Sitting sideways or turned to talk with an	sal notha
Occupant's Role		Occupant or to look out a rear window	
(1) Driver	1	(5) Sitting on a console	
(2) Passenger (9) Unknown		(6) Lying back in a reclined seat position (7) Bracing with fact or bands as	
107 OHKHUWII		(7) Bracing with feet or hands on a surface in of seat	n froi
		(8) Other abnormal posture (specify):	
		(9) Unknown	
orm 433A (1/96) This report is authorized by	P.L. 89-563, Till	e 1, Section 106, 108, and 112. While you are not remind to	AILABL

EJEQ	CTION/E	NTRAPMENT	raye
12. Ejection (0) No ejection (1) Complete ejection (2) Partial ejection (3) Ejection, unknown degree (9) Unknown	\$	15. Medium Status (Immediately Prior To Impact) (0) No ejection (1) Open (2) Closed (3) Integral structure (9) Unknown	Þ
13. Ejection Area (0) No ejection (1) Windshield (2) Left front (3) Right front (4) Left rear (5) Right rear (6) Rear (7) Roof	Þ	16. Entrapment (0) Not entrapped/exit not inhibited (1) Entrapped/pinned - mechanically restrained (2) Could not exit vehicle due to jammed doors fire, etc. (specify):	<u>\$</u>
(8) Other area (e.g., back of pickup, etc.) (specify): (9) Unknown		Occupant Mobility (0) Occupant fatal before removed from vehicle (1) Removed from vehicle while unconscious or not oriented to time or place	<u>4</u>
14. Ejection Medium (0) No ejection (1) Door/hatch/tailgate (2) Nonfixed roof structure (3) Fixed glazing (4) Nonfixed glazing (specify): (5) Integral structure (8) Other medium (specify): (9) Unknown	<u>\$</u>	(2) Removed from vehicle due to perceived serinjuries (3) Exited vehicle with some assistance (4) Exited vehicle under own power (5) Occupant fully ejected (8) Removed from vehicle for other reasons (specify): (9) Unknown	ious

		BELT SYSTE	M FUNCTION	
18.	Manual (Active) Belt System Avail. (0) None available (1) Belt removed/destroyed (2) Shoulder belt (3) Lap belt (4) Lap and shoulder belt (5) Belt available—type unknown	lability <u>4</u>	Manual Shoulder Belt Upper Anchorage Adjustment (0) No manual shoulder belt (1) No upper anchorage adjustment for manual shoulder belt Adjustable shoulder Belt Upper Anchorage	<u></u>
	Integral Belt Partially Destroyed (6) Shoulder belt (lap belt destroyed) (7) Lap belt (shoulder belt destroyed) (8) Other belt (specify): (9) Unknown	ved/removed)	 (2) In full up position (3) In mid position (4) In full down position (5) Position unknown (9) Unknown if position has adjustable upper anchorage adjustment 	L
19.		+4'	23. Automatic (Passive) Belt System Availability/ Function	Φ
lυ.	 Manual (Active) Belt System Use (00) None used, not available, or removed/destroyed (01) Inoperative (specify): 	belt 4 1	(0) Not equipped/not available (1) 2 point automatic belts (2) 3 point automatic belts (3) Automatic belts - type unknown	
	(02) Shoulder belt (03) Lap belt (04) Lap and shoulder belt (05) Belt used—type unknown		Non-functional (4) Automatic belts destroyed or rendered inoperative (9) Unknown	L
	(08) Other belt used (specify):(12) Shoulder belt used with child(13) Lap belt used with child safet	tv seat	24. Automatic (Passive) Belt System Use (0) Not equipped/not available/destroyed or rendered inoperative (1) Automatic belt in use (2) Automatic belt not in use (manually)	Ψ_
	 (14) Lap and shoulder belt used w safety seat (15) Belt used with child safety se (18) Other belt used with child safety se (specify): 	vith child eat-type unknown	(2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): (3) Automatic belt use unknown (9) Unknown	
20.	(99) Unknown if belt used Proper Use of Manual (Active) Belt. (0) None used or not available	ts	25. Automatic (Passive) Belt System Type (0) Not equipped/not available (1) Non-motorized system	\$
	(1) None used or not available(1) Belt used properly(2) Belt used properly with child s	rafaty seat	(2) Motorized system (9) Unknown 26 Proper Use of Automatic (Pageing)	h
	Belt Used Improperly (3) Shoulder belt worn under arm (4) Shoulder belt worn behind bac (5) Belt worn around more than or	ck or seat	26. Proper Use of Automatic (Passive) Belt System (0) Not equipped/not available/not used (1) Automatic belt used properly (2) Automatic belt used properly with child safety seat	4
	(6) Lap belt worn on abdomen(7) Lap belt or lap and shoulder be improperly with child safety se	elt used eat (specify):	Automatic Belt Used Improperly (3) Automatic shoulder belt worn under arm (4) Automatic shoulder belt worn behind back (5) Automatic belt worn around more than	
	(8) Other improper use of manual (specify):	belt system	one person (6) Lap portion of automatic belt worn on abdomen	
	(9) Unknown		(7) Automatic lap and shoulder belt or	
	Manual (Active) Belt Failure Modes During Accident (0) No manual belt used or not available failure (1)		automatic shoulder belt used improperly with child safety seat (specify): (8) Other improper use of automatic belt system.	
	(1) No manual belt failure(s)(2) Torn webbing (stretched webb included)	ing not	(8) Other improper use of automatic belt system (specify):(9) Unknown	•
	 (3) Broken buckle or latchplate (4) Upper anchorage separated (5) Other anchorage separated (sp 	pecify):	27. Automatic (Passive) Belt Failure Modes During Accident (0) Not equipped/not available/not in use	ф
	(6) Broken retractor(7) Combination of above (specify)		 (1) No automatic belt failure(s) (2) Torn webbing (stretched webbing not included) (3) Broken buckle or latchplate 	i)
	(8) Other manual belt failure (spec	ify):	(5) Other anchorage separated (specify):	
	(9) Unknown		(6) Broken retractor(7) Combination of above (specify):(8) Other automatic belt failure (specify):	
			(9) Unknown .	

POLICE REPORTED RESTRAINT USE	AIR BAG SYSTEM FUNCTION
28. Police Reported Belt Use (0) None used (1) Police did not indicate belt use (2) Shoulder belt (3) Lap belt (4) Lap and shoulder belt (5) Belt used, type not specified (6) Child safety seat (7) Automatic belt (8) Other type belt, (specify):	30. Frontal Air Bag System Availability/Function (This Occupant Position) (0) Not equipped/not available (1) Air bag Non-functional (2) Air bag disconnected (specify): (3) Air bag not reinstalled (9) Unknown 31. Frontal Air Bag System Deployment (This Occupant Position)
29. Police Reported Air Bag Availability/Function (0) No air bag available (1) Police did not indicate air bag availability/function (2) Deployed (3) Not deployed (4) Unknown if deployed (9) Police indicated "unknown"	 (0) Not equipped/not available (1) Deployed during accident (as a result of impact) (2) Deployed inadvertently just prior to accident (3) Deployed, details unknown (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical) (5) Unknown if deployed (7) Nondeployed (9) Unknown 32. Other Than First Seat Frontal Air Bag
Check the Primary Source Used In Determining Belt Use. Vehicle inspection Official injury data Driver/occupant interview Other (specify): Unknown if belt used	Availability/Function (This Occupant Position) (0) Not equipped/not available (1) Air bag Non-functional (2) Air bag disconnected (specify): (3) Air bag not reinstalled (9) Unknown Specify type of "other" air bag present: 33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) (0) Not equipped with an "other" air bag (1) Deployed during accident (as a result of impact) (2) Deployed inadvertently just prior to accident (3) Deployed, details unknown (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical) (5) Unknown if deployed (7) Nondeployed
	(9) Unknown 34. Are There Indications of Air Bag System Failure? (This Occupant Position) (0) Not equipped/not available (1) No (2) Yes (specify): (9) Unknown

	FIRST SEAT FRONTAL AIR	BAG SYSTEM EVALUATION
35.	Had Vehicle Been in Previous Accident(s)? (0) Not equipped/not available (1) No previous accidents Yes (2) Previous accident(s) without deployment(s) (3) One previous accident with deployment (4) More than one previous accident with at least one deployment (8) Previous accidents, unknown deployment status (9) Unknown	40. Longitudinal Component of Delta V For Air Bag Deployment Impact (_000) Not equipped/not available Code the value of the delta V for the impact that initiated the air bag deployment (_996) Deployment, unknown longitudinal Delta V (_997) Not deployed (_998) Unknown if deployed (_999) Unknown
36.	Type of Air Bag (0) Not equipped/not available (1) Original manufacturer installed system (2) Retrofitted air bag (3) Replacement air bag (8) Unknown type of air bag (9) Unknown	41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? (0) Not equipped/not available (1) No (2) Yes (3) Deployed, unknown if flap(s) opened at designated tear points (7) Not deployed (8) Unknown if deployed
37.	Had Any Prior Maintenance/Service Been Performed On This Air Bag System? (0) Not equipped/not available (1) No prior maintenance (2) Yes, prior maintenance (specify): (9) Unknown	(9) Unknown 42. Were Air Bag Module Cover Flap(s) Damaged? (0) Not equipped/not available (1) No (2) Yes (specify): (3) Deployed, unknown if air bag module cover flap(s) damaged
38.	Air Bag Deployment Accident Event Sequence Number (00) Not equipped/not available Code the accident event sequence number that initiated the air bag deployment (96) Deployed, unknown event (97) Not deployed (98) Unknown if deployed (99) Unknown	(7) Not deployed (8) Unknown if deployed (9) Unknown 43. Was There Damage To The Air Bag? (00) Not equipped/not available (01) Not damaged Yes - Air Bag Damage (02) Ruptured (03) Cut (04) Torn
39.	CDC For Air Bag Deployment Impact (0) Not equipped/not available (1) Highest delta V (2) Second highest delta V (3) Other non-coded delta V (specify): (6) Deployed, unknown event (7) Not deployed (8) Unknown if deployed (9) Unknown	(05) Holed (06) Burned (07) Abraded (88) Other damage (specify): (95) Damaged, details unknown (96) Deployed, unknown if damaged (97) Not deployed (98) Unknown if deployed (99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTE	IVI	HEAD RESTRAINT AND SEAT EVALUATION
44. Source of Air Bag Damage (00) Not equipped/not available (01) Not damaged (02) Object worn by occupant, (specify): (03) Object carried by occupant, (specify): (04) Adaptive/assistive controls, (specify): (05) Fire in vehicle (06) Thermal burns (07) Rescue or emergency efforts (88) Other damage source (specify):	<u> </u>	49. Head Restraint Type/Damage by Occupant at This Occupant Position (0) No head restraints (1) Integral—no damage (2) Integral—damaged during accident (3) Adjustable—no damage (4) Adjustable—damaged during accident (5) Add-on—no damage (6) Add-on—damaged during accident (8) Other (specify):
(95) Damaged, unknown source (96) Deployed, unknown if damaged (97) Not deployed (98) Unknown if deployed (99) Unknown 45. Was The Air Bag Tethered? (0) Not equipped/not available (1) No (2) Yes (specify number of tether straps):	2	50. Seat Type (this Occupant Position) (00) Occupant not seated or no seat (01) Bucket (02) Bucket with folding back (03) Bench (04) Bench with separate back cushions (05) Bench with folding back(s) (06) Split bench with separate back cushions (07) Split bench with folding back(s) (08) Pedestal (i.e., column supported) (09) Box mounted seat (i.e., van type) (10) Other seat type (specify):
 (3) Deployed, unknown if tethered (7) Not deployed (8) Unknown if deployed (9) Unknown 46. Did The Air Bag Have Vent Ports? (0) Not equipped/not available (1) No (2) Yes (specify number of vent ports): 	<u>\bullet</u>	(99) Unknown 51. Seat Orientation (this Occupant Position) (0) Occupant not seated or no seat (1) Forward facing seat (2) Rear facing seat (3) Side facing seat (inward) (4) Side facing seat (outward) (8) Other (specify):
 (3) Deployed, unknown if vent ports present (7) Not deployed (8) Unknown if deployed (9) Unknown 47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? (0) Not equipped/not available (1) No (2) Yes (specify): 	<u> </u>	(9) Unknown 52. Seat Track Adjusted Position Prior To Impact (0) Occupant not seated or no seat (1) Non-adjustable seat track Adjustable Seat Track (2) Seat at forward most track position (3) Seat between forward most and middle track positions
 (3) Deployed, unknown if other occupant contair bag (7) Not deployed (8) Unknown if deployed (9) Unknown 48. Was This Occupant Wearing Eye-wear? (0) Not air bag equipped/air bag not available (1) No (2) Eyeglasses/sunglasses (3) Contact lenses (4) Deployed, unknown if eyewear worn (7) Not deployed (8) Unknown if deployed (9) Unknown 	act to	 (4) Seat at middle track position (5) Seat between middle and rear most track positions (6) Seat at rear most track position (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION continued

- 53. Seat Back Incline Prior and Post Impact
 - (00) Occupant not seated or no seat
 - (01) Not adjustable

Upright prior to impact

- (11) Moved to completely rearward position
- (12) Moved to rearward midrange position
- (13) Moved to slightly rearward position
- (14) Retained pre-impact position
- (15) Moved to slightly forward position
- (16) Moved to forward midrange position
- (17) Moved to completely forward position


Slightly reclined prior to impact


- (21) Moved to completely rearward position
- (22) Moved to rearward midrange position
- (23) Retained pre-impact position
- (24) Moved to upright position
- (25) Moved to slightly forward position
- (26) Moved to forward midrange position
- (27) Moved to completely forward position

Completely reclined prior to impact

- (31) Retained pre-impact position
- (32) Moved to rearward midrange position
- (33) Moved to slightly rearward position
- (34) Moved to upright position
- (35) Moved to slightly forward position
- (36) Moved to forward midrange position
- (37) Moved to completely forward position
- (99) Unknown
- 54. Seat Performance (this Occupant Position)
 - (0) Occupant not seated or no seat
 - (1) No seat performance failure(s)
 - (2) Seat adjusters failed
 - (3) Seat back folding locks or "seat back" failed (specify):
 - (4) Seat track/anchors failed
 - (5) Deformed by impact of occupant
 - (6) Deformed by passenger compartment intrusion, (specify):
 - (7) Combination of above (specify):
 - (8) Other (specify):
 - (9) Unknown







CHILD SAF	FETY SEAT
CHILD SAF 55. Child Safety Seat Make/Model (000) No child safety seat Applicable codes are found in your NASS CDS Data Collection, Coding and Editing (950) Built-in child safety seat (997) Other make/model (specify): (998) Unknown make/model (999) Unknown if child safety seat used 56. Type of Child Safety Seat (0) No child safety seat (1) Infant seat (2) Toddler seat (3) Convertible seat (4) Booster seat - with shield (5) Booster seat - without shield (7) Other type child safety seat (specify):	58. Child Safety Seat Harness Usage 59. Child Safety Seat Shield Usage 60. Child Safety Seat Tether Usage Note: Options below applicable to Variables OA58-OA60. (00) No child safety seat Not Designed With Harness/Shield/Tether (01) After market harness/shield/tether added, not used (02) After market harness/shield/tether used (03) Child safety seat used, but no after market harness/shield/tether added (09) Unknown if harness/shield/tether added or used
(9) Unknown if child safety seat used 57. Child Safety Seat Orientation (00) No child safety seat Designed for Rear Facing for This Age/Weight (01) Rear facing (02) Forward facing (08) Other orientation (specify):	Designed With Harness/Shield/Tether (11) Harness/shield/tether not used (12) Harness/shield/tether used (19) Unknown if harness/shield/tether used Unknown If Designed With Harness/Shield/Tether (21) Harness/shield/tether not used (22) Harness/shield/tether used (29) Unknown if harness/shield/tether used
Designed For Forward Facing for This Age/Weight (11) Rear facing (12) Forward facing (18) Other orientation (specify): (19) Unknown orientation Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight (21) Rear facing (22) Forward facing (28) Other orientation (specify): (29) Unknown orientation (99) Unknown if child safety seat used	(99) Unknown if child safety seat used

	· dgo
INJURY CONSEQUENCES	
61. Injury Severity (Police Rating)	3 63. Type Of Medical Facility (for Initial Treatment) 2
 (0) O - No injury (1) C - Possible injury (2) B - Nonincapacitating injury (3) A - Incapacitating injury (4) K - Killed (5) U - Injury, severity unknown (6) Died prior to accident (9) Unknown 	(0) Not treated at a medical facility (1) Trauma center (2) Hospital (3) Medical clinic (4) Physician's office (5) Treatment later at medical facility (8) Other (specify):
62. Treatment - Mortality (0) No treatment (1) Fatal (2) Fatal - ruled disease (specify):	64. Hospital Stay (00) Not Hospitalized Code the number of days (up through 60) that the occupant stayed in hospital. (61) 61 days or more
Nonfatal	(99) Unknown
 (3) Hospitalization (4) Transported and released (5) Treatment at scene - nontransported (6) Treatment later (7) Treatment - other (specify): 	65. Working Days Lost Code the number of days (up through 60) that the occupant lost from work due to the accident (00) No working days lost
(8) Transported to a medical facility-unknown is treated(9) Unknown	f (61) 61 days or more (62) Fatally injured (97) Not working prior to accident (99) Unknown
EMERGENCY F	RESPONSE INFORMATION
EMS Notification (1) Not notified ROAD	EMS Type VEHICLE (01) Fire department ROAD VEHICLE

EMS Notification	2	EMS Type	(D)
(1) Not notified	ROAD VEHICLE	(01) Fire department	ROAD VEHIC
(2) Notified	~	(O2) Rescue squad	99
(9) Unknown	AIR VEHICLE	(03) Police department	AIR VEHICL
		(04) Trauma unit	
	1033	(05) Disaster unit	
EMS NotificationTime		(06) Ambulance service unit	
(9999) Unknown	ROAD VEHICLE	(07) Hospital	
	1836	(08) Mortuaries/funeral homes	
	AIR VEHICLE	(98) Other, specifiy:	
	0 1 2	(99) Unknown	
EMS Arrival Time	1 0 4 3		
(9998) EMS cancelled or did	ROAD VEHICLE		aa
not arrive	LB 53	EMS Care (on scene or during transport)	97
(9999) Unknown	AIR VEHICLE	(01) No care administered	ROAD VEHIC
		(O2) First aid	99
	999	(03) Resuscitation	AIR VEHIC
EMS Departure Time To	-((/ /	(04) CPR	
Treatment Facility	ROAD VEHICLE	(05) Emergency cardiac care	
(9997) EMS arrived, provided	9991	(06) Life support system monitoring (block	od pressure,
treatment, but did not	AIR VEHICLE	pulse rate, respiration, EKG)	-
transport		(07) Emergency burn care	
(9998) EMS arrived, but was		(08) Combination of above, specify:	
not used		(98) Other, specify:	
(9999) Unknown		(99) Unknown	
	1.909		
EMS Arrival Time At	9171		
Treatment Facility	ROAD VEHICLE		
(9999) Unknown	9999		

STOP WORK HERE VARIABLES 66-74 TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES		TRAUMA DATA
66. Time to Death Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day 31, 2 days = 32, n days = 30 + n up through 30 days = 60) (00) Not fatal (96) Fatal - ruled disease (99) Unknown	<u>Ф</u> ф =	71. Glasgow Coma Scale (GCS) Score (at Medical Facility) (00) Not injured (01) Injured - not treated at medical facility (02) No GCS Score at medical facility (03-15) Code the actual value of the initial GCS Score recorded at medical facility. (97) Injured, details unknown (99) Unknown if injured
67. 1st Medically Reported Cause of Death 68. 2nd Medically Reported Cause of Death 69. 3rd Medically Reported Cause of Death Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death (00) Not fatal or no additional causes (96) Mode of death given but specific injuries are not linked to cause of death. (specify): (97) Other result (includes fatal ruled disease) (specify):	\$ \$ \$ \$ \$ \$ \$	72. Was the Occupant Given Blood? (1) No - blood not given (2) Yes - blood given (specify units): (9) Unknown if blood given 73. Arterial Blood Gases (ABG) – HCO ₃ (00) Not injured (01) Injured, ABGs not measured or reported (02-50) Code the actual value of the HCO ₃ (96) ABGs reported, HCO ₃ unknown (97) Injured, details unknown (99) Unknown if injured
70. Number of Recorded Injuries for This Occupant Code the actual number of injuries recorded for this occupant. (00) No recorded injuries (97) Injured, details unknown (99) Unknown if injured	ф <u>1</u>	74. Primary Source of Belt Use Determination (0) Not equipped/not available/destroyed or rendered inoperative (1) Vehicle inspection (2) Official injury data (3) Driver/occupant interview (8) Other (specify): (9) Unknown if belt used

Administration

OCCUPANT INJURY FORM

BEST AVAILABLE

Form Approved O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number

2. Case Number - Stratum

3. Vehicle Number

4. Occupant Number

4. Occupant Number

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	A.I.S 90 Source Type of Specific							Injury	Occupant			
	of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Source Confidence Level	Direct/ Indirect Injury	Area Intrusion Number	ICD-9
1st	5.7	6 <u> </u>	75	8 <u>26</u>	क्रिके	10. 2	11 7212	254	13.2	14.2	15 <u>\$2</u>	<u>826</u> 8
2nd	16. 2	17.4	18 🗲	19. <u>#2</u>	20 Z 🕹	21 7	2223	<u>15a</u>	24	25	26. <u>P</u> P	<u>B07.</u> 43
3rd	27.7	28. 🕰	29 💆	30. <u>22</u>	эг <u>ФФ</u>	32 <u>Z</u>	33. <u> </u> 34.	254	. 35_2	36. <u>L</u>	37. <u>4</u> 2	825,20
4th	38. 7	39.4	40 9 .	n 4 2	42.42	43 1	44. <u>4</u> 45.	<u>/5</u> 3	46. <u>1</u>	47	18. 夕华	<u>911.4</u>
5th	49	50. <u>5</u>	51 9 5	242	53. <u>d/ ン</u>	54. 🛴	55. <u>6</u> .56.	152	57	58. <u>L</u> 5	_{१९} क्ष	911:p
6th	60. <u>9</u>	61	62. <u>9</u> 6	3. (1 66	<u>фФ</u>	65. <u>l</u>	66. <u>3</u> 67	<u> 4 6 b</u>	68. 2	69	<u>。本</u> 上	<u>β73.</u> φ
7th	71_9	72	739 7	4 <u>66</u>	75. P. P.	76. <u>1</u>	77. <u>Z</u> 78.	LZ#	79. <u> </u>	80. <u>/</u> 8	1 <u>4</u> 0	<u>884</u> ,43
8th	82	83	84: 8	5	86,	87	8889		90	91 9	2	
9th	93	94	95 96	51	97	98	99100.		101	102 10	з	-
10th	104	105	106 10	7:1	08	109	110111.		112	113 11	4	<u>- 1</u>

OCCUPANT INJURY CLASSIFICATION **Body Region Specific Anatomic** Level of Injury **Aspect** Structure Head Specific injuries are (2) (3) (4) (5) (6) (7) (8) Face Right assigned consecutive Neck Left Vessels, Nerves, Organs. two-digit numbers beginning Thorax Bilateral Bones, Joints are assigned with 02. Abdomen Central consecutive two digit Spine Anterior numbers beginning with 02. To the extent possible, within **Upper Extremity** (6) **Posterior** the organizational Lower Extremity Superior The exceptions to this rule framework of the AIS, 00 is (9) Unspecified (8) Inferior apply to: assigned to an injury NFS as Unknown to severity or where only one Whole region Whole Area injury is given in the Type of Anatomic Skin - Abrasion (02)dictionary for that anatomic Structure Skin - Contusion (04)structure. 99 is assigned to (06)Skin - Laceration any injury NFS as to lesion Whole Area (08)Skin - Avulsion or severity. (2) (3) Vessels (10)Amputation Nerves (20)Burn **Abbreviated Injury Scale** Organs (includes (30)Crush Muscles/ligaments) (40) Degloving Skeletal (includes (5) Minor Injury (50)Injury - NFS (2) (3) Moderate Injury joints) (90)Trauma, other than Serious Injury Head - LOC mechanical (4) (5) (6) Severe Injury **(9)** Skin Critical Injury Head - LOC Maximum (02) Length of LOC (untreatable) Injured, unknown (04)Level severity (06) of (08) Consciousness (10) Concussion Spine

(02)

(04)

(06)

Cervical

Thoracic


Lumbar

SOURCE OF INJURY DATA **INJURY SOURCE** DIRECT/INDIRECT INJURY CONFIDENCE LEVEL OFFICIAL RECORDS (1) Autopsy records with or (1) Certain without hospital/medical Direct contact injury (2) Probable (2) (3) records Indirect contact injury Possible (2) Hospital/medical records other Noncontact injury (9) Unknown than emergency room Injured, unknown source (e.g., discharge summary) (3) Emergency room records only (including associated X-rays or other lab reports) (4) Private physician, walk-in or emergency clinic UNOFFICIAL RECORDS (5) Lay coroner report (6) E.M.S. personnel (7) Interviewee (8) Other source (specify): (9) Police

INJURY SOURCES FRONT (102) Right side hardware or (183) Air bag-passenger side and (001) Windshield Wall mounted head rest (used object held (002) Mirror behind wheel chair) (103)Right A (A1/A2)-pillar Air bag-passenger side and (003)Sunvisor (412)Other adaptive device (104)Right B-pillar object in mouth (004)Steering wheel rim (specify):_ (105)Other right pillar (specify): (185)Air bag compartment (005) Steering wheel hub/spoke cover-passenger side Steering wheel (combination (006)(106)Right side window glass (186)Air bag compartment of codes 004 and 005) EXTERIOR of OCCUPANT'S Right side window frame (107)(007)cover-passenger side and Steering column, transmission VEHICLE (108)Right side window sill evewear (451) Hood selector lever, other (109)Right side window glass (187) Air bag compartment attachment (452)Outside hardware (e.g., including one or more of the cover-passenger side and Cellular telephone or CB radio outside mirror, antenna) (800)following: frame, window sill, jewelry Add on equipment (e.g., tape (009)(453)Other exterior surface or tires A (A1/A2)-pillar, B-pillar, or (188) Air bag compartment deck, air conditioner) (specify): roof side rail. cover-passenger side and (010) Left instrument panel and (110) Other right side object object held (454) Unknown exterior objects below (specify): (189) Air bag compartment (011) Center instrument panel and cover-passenger side and EXTERIOR OF OTHER MOTOR below object in mouth (012)**VEHICLE** Right instrument panel and INTERIOR (190) Other air bag (specify) (501) Front bumper below (151) Seat, back support (013)Glove compartment door (502)Hood edge (152) Belt restraint webbing/buckle (195) Other air bag compartment (503)(014) Knee bolster Other front of vehicle (153)Belt restraint B-pillar or door cover (specify) (015) Windshield including one or (specify): frame attachment point more of the following: front (154) Other restraint system (504)header, A (A1/A2)-pillar, Hood component (specify): ROOF (505)Hood ornament instrument panel, mirror, or (201) Front header (506)Windshield, roof rail, A-pillar steering assembly (driver side (155)Head restraint system (202)Rear header (507) only) Side surface (160) Other occupants (specify): (203)Roof left side rail (016) Windshield including one or (508)Side mirrors Roof right side rail (204)more of the following: front (509)Other side protrusions (161)Interior loose objects Roof or convertible top (205)header, A (A1/A2)-pillar, (specify): (162)Child safety seat (specify): Instrument panel, or mirror **FLOOR** (passenger side only) (510)Rear surface (163)Other interior object (specify): (251) Floor (including toe pan) (017) Windshield reinforced by (511)Undercarriage (252)Floor or console mounted (512) Tires and wheels exterior object (specify) transmission lever, including (513) Other exterior of other motor AIR BAG console (019) Other front object (specify): vehicle (specify): (170) Air bag-driver side (253)Parking brake handle (171) Air bag-driver side and (254) Foot controls including (514) Unknown exterior of other evewear parking brake LEFT SIDE motor vehicle (172) Air bag-driver side and jeweiry (051) Left side interior surface, (173) Air bag-driver side and object REAR OTHER VEHICLE OR OBJECT IN excluding hardware or held (301) Backlight (rear window) armrests THE ENVIRONMENT (174) Air bag-driver slde and object (302)Backlight storage rack. (052)(551) Ground Left side hardware or armrest in mouth door, etc. (053) Left A (A1/A2)-pillar (598)Other vehicle or object (175) Air bag compartment (303) Other rear object (specify): (054) Left B-pillar (specify): cover-driver side (055) Other left pillar (specify): (176) Air bag compartment Unknown vehicle or object (599)cover-driver side and eyewear ADAPTIVE (ASSISTIVE) DRIVING (056)Left side window glass (177) Air bag compartment EQUIPMENT (057)Left side window frame NONCONTACT INJURY cover-driver side and jewelry (401) Hand controls for (058) Left side window sill (601) Fire in vehicle (178)Air bag compartment braking/acceleration (059) Left side window glass (602)Flying glass cover-driver side and object (402)Steering control devices including one or more of the (603)Other noncontact Injury held (attached to OEM steering following: frame, window sill, (179) Air bag compartment wheel) A (A1/A2)-pillar, B-pillar, or (specify): cover-driver side and object in (403)Steering knob attached to (604)roof side rail. Air bag exhaust gases steering wheel Other left side object (697)Injured, unknown source (180) Air bag-passenger side (405)Replacement steering wheel (specify): (181) Air bag-passenger side and (i.e., reduced diameter) evewear (406)Joy stick steering controls (182) Air bag-passenger side and (407)Wheelchair tle-downs RIGHT SIDE ieweln Modification to seat belts, (408)(101) Right side interior surface, (specify): excluding hardware or Additional or relocated armrests switches, (specify): (410) Raised roof

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





	OFFICIAL INJURY DATA — SKELETAL INJURIES	BEST AVAILAB
Restrained?		
Yes	Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and unavailable.)	
	Interview	
Blood Alcohol Le mg/dl)	vel	
BAL =0	(60g)	
Blasgow Coma Cale Score		
SCSS =	3 fractured ribs on the	
nits of Blood	right side	
ven nits =	Seat Belt	
0	Fractured left hip	
terial Blood Gas	foot pedal intrusion	
H =		
CO ₂ =		
co,		
1.0		
	Fractured right	
	metatarsal	i

Foot pedal

OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number	OCCUPANT'S SEATING
2. Case Number - Stratum	10. Occupant's Seat Position 3
2. Case Number - Stratum 1)37616	Front Seat
3. Vehicle Number	(11) Left side (12) Middle
4. Occupant Number ϕ 2	(13) Right side
OCCUPANT'S CHARACTERISTICS	(14) Other (specify):
OCCUPANT S CHARACTERISTICS	(15) On or in the lap of another occupant
5. Occupant's Age Code actual age at time of accident. (00) Less than one year old (specify by month): (97) 97 years and older (99) Unknown	Second Seat (21) Left side (22) Middle (23) Right side (24) Other (specify): (25) On or in the lap of another occupant Third Seat (31) Left side
6. Occupant's Sex	(32) Middle
(1) Male	(33) Right side
(2) Female-not reported pregnant (3) Female-pregnant-1st trimester(1st-3rd month)	(34) Other (specify):(35) On or in the lap of another occupant
(4) Female-pregnant-2nd trimester(4th-6th month)	(30) On or in the rap of another occupant
(5) Female-pregnant-3rd trimester(7th-9th month)	Fourth Seat
(6) Female-pregnant-term unknown (9) Unknown	(41) Left side (42) Middle
(5) UNKNOWN	(43) Right side
	(44) Other (specify):
7. Occupant's Height Code actual height to the nearest centimeter. (999) Unknown	(45) On or in the lap of another occupant(97) In or on unenclosed area(98) Other seat (specify):(99) Unknown
$ \frac{54}{4} \text{ inches } \times 2.54 = \underline{137} \text{ centimeters} $ 8. Occupant's Weight $ \underline{424} \text{ b} $	11. Occupant's Posture
Code actual weight to the nearest kilogram.	(0) Normal posture
(999) Unknown	Abnormal posture (1) Kneeling or standing on seat
<u>57</u> _ pounds X .4536 = <u>Ø Z 6</u> kilograms	(2) Lying on or across seat(3) Kneeling, standing or sitting in front of seat
9. Occupant's Role (1) Driver (2) Passenger (9) Unknown	 (4) Sitting sideways or turned to talk with another occupant or to look out a rear window (5) Sitting on a console (6) Lying back in a reclined seat position (7) Bracing with feet or hands on a surface in front of seat (8) Other abnormal posture (specify):
	(9) Unknown
	BEST AVAILABLE

	EJECTION/ENTRAPMENT							
12.	Ejection (0) No ejection (1) Complete ejection (2) Partial ejection (3) Ejection, unknown degree (9) Unknown	Ф	15. Medium Status (Immediately Prior To Impact) (0) No ejection (1) Open (2) Closed (3) Integral structure (9) Unknown					
13.	Ejection Area (0) No ejection (1) Windshield (2) Left front (3) Right front (4) Left rear (5) Right rear (6) Rear (7) Roof (8) Other area (e.g., back of pickup, etc.) (specify): (9) Unknown		16. Entrapment (0) Not entrapped/exit not inhibited (1) Entrapped/pinned - mechanically restrained (2) Could not exit vehicle due to jammed doors, fire, etc. (specify): (9) Unknown 17. Occupant Mobility (0) Occupant fatal before removed from vehicle (1) Removed from vehicle while unconscious or not oriented to time or place					
14.	Ejection Medium (0) No ejection (1) Door/hatch/tailgate (2) Nonfixed roof structure (3) Fixed glazing (4) Nonfixed glazing (specify): (5) Integral structure (8) Other medium (specify): (9) Unknown	<u>P</u>	 (2) Removed from vehicle due to perceived serious injuries (3) Exited vehicle with some assistance (4) Exited vehicle under own power (5) Occupant fully ejected (8) Removed from vehicle for other reasons (specify): (9) Unknown 					
	·							

	BELT SYSTE	M FUNCTION
18.	Manual (Active) Belt System Availability (0) None available (1) Belt removed/destroyed (2) Shoulder belt (3) Lap belt (4) Lap and shoulder belt (5) Belt available—type unknown	22. Manual Shoulder Belt Upper Anchorage Adjustment (0) No manual shoulder belt (1) No upper anchorage adjustment for manual shoulder belt Adjustable shoulder Belt Upper Anchorage (2) In full up position
	Integral Belt Partially Destroyed (6) Shoulder belt (lap belt destroyed/removed) (7) Lap belt (shoulder belt destroyed/removed) (8) Other belt (specify):	(2) In full up position (3) In mid position (4) In full down position (5) Position unknown (9) Unknown if position has adjustable upper anchorage adjustment
	(9) Unknown	23. Automatic (Passive) Belt System Availability/
19.	Manual (Active) Belt System Use (00) None used, not available, or belt removed/destroyed (01) Inoperative (specify):	Function (0) Not equipped/not available (1) 2 point automatic belts (2) 3 point automatic belts (3) Automatic belts - type unknown
	(02) Shoulder belt (03) Lap belt (04) Lap and shoulder belt (05) Belt used—type unknown (08) Other belt used (specify):	Non-functional (4) Automatic belts destroyed or rendered inoperative (9) Unknown 24. Automatic (Passive) Belt System Use
	 (12) Shoulder belt used with child safety seat (13) Lap belt used with child safety seat (14) Lap and shoulder belt used with child safety seat (15) Belt used with child safety seat—type unknown (18) Other belt used with child safety seat 	(0) Not equipped/not available/destroyed or rendered inoperative (1) Automatic belt in use (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): (3) Automatic belt use unknown (9) Unknown
20.	(specify): (99) Unknown if belt used Proper Use of Manual (Active) Belts (0) None used or not available	25. Automatic (Passive) Belt System Type (0) Not equipped/not available (1) Non-motorized system (2) Motorized system (9) Unknown
	 Belt used properly Belt used properly with child safety seat Belt Used Improperly Shoulder belt worn under arm Shoulder belt worn behind back or seat Belt worn around more than one person 	26. Proper Use of Automatic (Passive) Belt System (0) Not equipped/not available/not used (1) Automatic belt used properly (2) Automatic belt used properly with child safety seat
	 (6) Lap belt worn on abdomen (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): (8) Other improper use of manual belt system (specify): 	Automatic Belt Used Improperly (3) Automatic shoulder belt worn under arm (4) Automatic shoulder belt worn behind back (5) Automatic belt worn around more than one person (6) Lap portion of automatic belt worn
	(9) Unknown	on abdomen (7) Automatic lap and shoulder belt or
21.	Manual (Active) Belt Failure Modes During Accident (0) No manual belt used or not available (1) No manual belt failure(s) (2) Torn webbing (stretched webbing not included)	automatic shoulder belt used improperly with child safety seat (specify): (8) Other improper use of automatic belt system (specify):
	 (3) Broken buckle or latchplate (4) Upper anchorage separated (5) Other anchorage separated (specify): (6) Broken retractor (7) Combination of above (specify): (8) Other manual belt failure (specify): 	27. Automatic (Passive) Belt Failure Modes During Accident (0) Not equipped/not available/not in use (1) No automatic belt failure(s) (2) Torn webbing (stretched webbing not included) (3) Broken buckle or latchplate (4) Upper anchorage separated (5) Other anchorage separated (specify):
	(9) Unknown	(6) Broken retractor (7) Combination of above (specify): (8) Other automatic belt failure (specify): (9) Unknown
		(5) Challowin

POLICE REPORTED RESTRAINT USE	AIR BAG SYSTEM FUNCTION
28. Police Reported Belt Use (0) None used (1) Police did not indicate belt use (2) Shoulder belt (3) Lap belt (4) Lap and shoulder belt (5) Belt used, type not specified (6) Child safety seat (7) Automatic belt (8) Other type belt, (specify):	30. Frontal Air Bag System Availability/Function (This Occupant Position) (0) Not equipped/not available (1) Air bag Non-functional (2) Air bag disconnected (specify): (3) Air bag not reinstalled (9) Unknown
(9) Police indicated "unknown" 29. Police Reported Air Bag Availability/Function (0) No air bag available (1) Police did not indicate air bag availability/function (2) Deployed (3) Not deployed (4) Unknown if deployed (9) Police indicated "unknown"	31. Frontal Air Bag System Deployment (This Occupant Position) (0) Not equipped/not available (1) Deployed during accident (as a result of impact) (2) Deployed inadvertently just prior to accident (3) Deployed, details unknown (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical) (5) Unknown if deployed (7) Nondeployed (9) Unknown
Check the Primary Source Used In Determining Belt Use. Vehicle inspection Official injury data Driver/occupant interview Other (specify): Unknown if belt used	Availability/Function (This Occupant Position) (O) Not equipped/not available (1) Air bag Non-functional (2) Air bag disconnected (specify): (3) Air bag not reinstalled (9) Unknown Specify type of "other" air bag present:
	 33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) (0) Not equipped with an "other" air bag (1) Deployed during accident (as a result of impact) (2) Deployed inadvertently just prior to accident (3) Deployed, details unknown (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical) (5) Unknown if deployed (7) Nondeployed (9) Unknown
	34. Are There Indications of Air Bag System Failure? (This Occupant Position) (0) Not equipped/not available (1) No (2) Yes (specify): (9) Unknown

	FIRST SEAT FRONTAL AIR	BAG SYSTEM EVALUATION
35.	Had Vehicle Been in Previous Accident(s)? (0) Not equipped/not available (1) No previous accidents Yes (2) Previous accident(s) without deployment(s) (3) One previous accident with deployment (4) More than one previous accident with at least one deployment (8) Previous accidents, unknown deployment status (9) Unknown	40. Longitudinal Component of Delta V For Air Bag Deployment Impact (_000) Not equipped/not available Code the value of the delta V for the impact that initiated the air bag deployment (_996) Deployment, unknown longitudinal Delta V (_997) Not deployed (_998) Unknown if deployed (_999) Unknown
	Type of Air Bag (0) Not equipped/not available (1) Original manufacturer installed system (2) Retrofitted air bag (3) Replacement air bag (8) Unknown type of air bag (9) Unknown	41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? (0) Not equipped/not available (1) No (2) Yes (3) Deployed, unknown if flap(s) opened at designated tear points (7) Not deployed (8) Unknown if deployed (9) Unknown
37.	Had Any Prior Maintenance/Service Been Performed On This Air Bag System? (0) Not equipped/not available (1) No prior maintenance (2) Yes, prior maintenance (specify): (9) Unknown	42. Were Air Bag Module Cover Flap(s) Damaged? (0) Not equipped/not available (1) No (2) Yes (specify): (3) Deployed, unknown if air bag module cover flap(s) damaged (7) Not deployed
38.	Air Bag Deployment Accident Event Sequence Number (00) Not equipped/not available Code the accident event sequence number that initiated the air bag deployment (96) Deployed, unknown event (97) Not deployed (98) Unknown if deployed (99) Unknown	(8) Unknown if deployed (9) Unknown 43. Was There Damage To The Air Bag? (00) Not equipped/not available (01) Not damaged Yes - Air Bag Damage (02) Ruptured (03) Cut (04) Torn
	CDC For Air Bag Deployment Impact (0) Not equipped/not available (1) Highest delta V (2) Second highest delta V (3) Other non-coded delta V (specify): (6) Deployed, unknown event (7) Not deployed (8) Unknown if deployed (9) Unknown	(05) Holed (06) Burned (07) Abraded (88) Other damage (specify): (95) Damaged, details unknown (96) Deployed, unknown if damaged (97) Not deployed (98) Unknown if deployed (99) Unknown

	FIRST SEAT FRONTAL AIR BAG SYST	EM	HEAD RESTRAINT AND SEAT EVALUATION
44	Source of Air Bag Damage	88	49. Head Restraint Type/Damage by Occupant 3
	(00) Not equipped/not available		— at this Occupant Position
	(01) Not damaged		(0) No head restraints
	(02) Object worn by occupant, (specify):		(1) Integral—no damage
			(2) Integral—damaged during accident
	(03) Object carried by occupant, (specify):		(3) Adjustable—no damage (4) Adjustable—damaged during accident
			(5) Add-on—no damage
	(04) Adaptive/assistive controls, (specify):		(6) Add-on-damaged during accident
			(8) Other (specify):
	(05) Fire in vehicle		(o) Other (specify).
	(06) Thermal burns		(9) Unknown
	(07) Rescue or emergency efforts		(0, 0)
	(88) Other damage source (specify):	١.	50. Seat Type (this Occupant Position)
	MODULE GOVER & RUOF RA	16	(00) Occupant not seated or no seat
	(95) Damaged, unknown source		(01) Bucket
	(96) Deployed, unknown if damaged		(02) Bucket with folding back
	(97) Not deployed		(03) Bench
	(98) Unknown if deployed (99) Unknown		(04) Bench with separate back cushions
	(39) Olikilowii		(05) Bench with folding back(s)
		}	(06) Split bench with separate back cushions
45.	Was The Air Bag Tethered?		(07) Split bench with folding back(s)
	(0) Not equipped/not available		(08) Pedestal (i.e., column supported)
	(1) No		(09) Box mounted seat (i.e., van type)
	(2) Yes (specify number of tether straps):		(10) Other seat type (specify):
	(0)	_	(99) Unknown
	(3) Deployed, unknown if tethered		(99) Olikhown
	(7) Not deployed		51. Seat Orientation (this Occupant Position)
	(8) Unknown if deployed (9) Unknown		(0) Occupant not seated or no seat
	(9) Officiowif		(1) Forward facing seat
46.	Did The Air Bag Have Vent Ports?		(2) Rear facing seat
	(0) Not equipped/not available	11	(3) Side facing seat (inward)
	(1) No		(4) Side facing seat (outward)
	(2) Yes (specify number of vent ports):		(8) Other (specify):
	/0\ 0		
	(3) Deployed, unknown if vent ports present(7) Not deployed		(9) Unknown
	(8) Unknown if deployed		
	(9) Unknown		52. Seat Track Adjusted Position Prior To Impact
	(O) OTIKITO WIT	ì	(0) Occupant not seated or no seat
47.	Was the Air Bag in this Occupant's Position	- 1	(1) Non-adjustable seat track
	Contacted by Another Occupant?		Adjustable Seat Track
	(0) Not equipped/not available		(2) Seat at forward most track position
	(1) No		(3) Seat between forward most and middle track
	(2) Yes (specify):		positions
			(4) Seat at middle track position
	(3) Deployed, unknown if other occupant con	ntact to	(5) Seat between middle and rear most track
	air bag		positions
	(7) Not deployed		(6) Seat at rear most track position
	(8) Unknown if deployed		(9) Unknown
	(9) Unknown	,	
40	Was This Ossume (1)4/ 1 5	- 1	
	Was This Occupant Wearing Eye-wear?		-
	(0) Not air bag equipped/air bag not available) ·	
	(1) No (2) Evaglasses/sunglasses		
	(2) Eyeglasses/sunglasses (3) Contact lenses		
	(4) Deployed, unknown if eyewear worn		
	(7) Not deployed		
	(8) Unknown if deployed		
	(9) Unknown		
			i

HEAD RESTRAINT AND SEAT EVALUATION continued

- 53. Seat Back Incline Prior and Post Impact
 - (00) Occupant not seated or no seat
 - (01) Not adjustable

Upright prior to impact


- (11) Moved to completely rearward position
- (12) Moved to rearward midrange position
- (13) Moved to slightly rearward position
- (14) Retained pre-impact position
- (15) Moved to slightly forward position
- (16) Moved to forward midrange position
- (17) Moved to completely forward position


Slightly reclined prior to impact


- (21) Moved to completely rearward position
- (22) Moved to rearward midrange position
- (23) Retained pre-impact position
- (24) Moved to upright position
- (25) Moved to slightly forward position
- (26) Moved to forward midrange position
- (27) Moved to completely forward position

Completely reclined prior to impact

- (31) Retained pre-impact position
- (32) Moved to rearward midrange position
- (33) Moved to slightly rearward position
- (34) Moved to upright position
- (35) Moved to slightly forward position
- (36) Moved to forward midrange position
- (37) Moved to completely forward position
- (99) Unknown
- 54. Seat Performance (this Occupant Position)
 - (0) Occupant not seated or no seat
 - (1) No seat performance failure(s)
 - (2) Seat adjusters failed
 - (3) Seat back folding locks or "seat back" failed (specify):
 - (4) Seat track/anchors failed
 - (5) Deformed by impact of occupant
 - (6) Deformed by passenger compartment intrusion, (specify):
 - (7) Combination of above (specify):
 - (8) Other (specify):
 - (9) Unknown







CHILD SAFETY SEAT 000 55. Child Safety Seat Make/Model 58. Child Safety Seat Harness Usage (000) No child safety seat Applicable codes are found in your NASS CDS Data Collection, Coding and Editing 59. Child Safety Seat Shield Usage (950) Built-in child safety seat (997) Other make/model (specify): 60. Child Safety Seat Tether Usage (998) Unknown make/model (999) Unknown if child safety seat used Note: Options below applicable to Variables OA58-OA60. Φ 56. Type of Child Safety Seat (00) No child safety seat (0) No child safety seat (1) Infant seat Not Designed With Harness/Shield/Tether (2) Toddler seat (01) After market harness/shield/tether (3) Convertible seat added, not used (4) Booster seat - with shield (02) After market harness/shield/tether used (5) Booster seat - without shield (03) Child safety seat used, but no after market (7) Other type child safety seat (specify): harness/shield/tether added (09) Unknown if harness/shield/tether (8) Unknown child safety seat type added or used (9) Unknown if child safety seat used Designed With Harness/Shield/Tether (11) Harness/shield/tether not used 57. Child Safety Seat Orientation (12) Harness/shield/tether used (00) No child safety seat (19) Unknown if harness/shield/tether used Designed for Rear Facing for This Age/Weight Unknown If Designed With Harness/Shield/Tether (01) Rear facing (21) Harness/shield/tether not used (02) Forward facing (22) Harness/shield/tether used (08) Other orientation (specify): (29) Unknown if harness/shield/tether used (09) Unknown orientation (99) Unknown if child safety seat used Designed For Forward Facing for This Age/Weight (11) Rear facing (12) Forward facing (18) Other orientation (specify): (19) Unknown orientation Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight (21) Rear facing (22) Forward facing (28) Other orientation (specify): (29) Unknown orientation (99) Unknown if child safety seat used

INJURY CONSEQUENCES 61. Injury Severity (Police Rating) 63. Type Of Medical Facility (for Initial Treatment) 2 (0) Not treated at a medical facility (0) 0 - No injury (1) Trauma center (1) C - Possible injury (2) Hospital (2) B - Nonincapacitating injury (3) Medical clinic (3) A - Incapacitating injury (4) Physician's office (4) K - Killed (5) Treatment later at medical facility (5) U - Injury, severity unknown (8) Other (specify): (6) Died prior to accident (9) Unknown (9) Unknown 62. Treatment - Mortality 64. Hospital Stay (0) No treatment (00) Not Hospitalized (1) Fatal Code the number of days (up through 60) (2) Fatal - ruled disease (specify): that the occupant stayed in hospital. (61) 61 days or more (99) Unknown Nonfatal (3) Hospitalization 65. Working Days Lost (4) Transported and released Code the number of days (5) Treatment at scene - nontransported (up through 60) that the occupant (6) Treatment later lost from work due to the accident (7) Treatment - other (specify): (00) No working days lost (61) 61 days or more (8) Transported to a medical facility-unknown if (62) Fatally injured treated (97) Not working prior to accident (9) Unknown (99) Unknown **EMERGENCY RESPONSE INFORMATION**

EMS Notification (1) Not notified (2) Notified (9) Unknown	ROAD VEHICLE AIR VEHICLE	EMS Type (01) Fire department (02) Rescue squad (03) Police department
EMS NotificationTime (9999) Unknown	TO STORY SERVICE TO STO	(04) Trauma unit (05) Disaster unit (06) Ambulance service unit (07) Hospital (08) Mortuaries/funeral homes (98) Other, specifiy:
EMS Arrival Time (9998) EMS cancelled or did not arrive (9999) Unknown	T 8 + 3 ROAD VEHICLE AIR VEHICLE	EMS Care (on scene or during transport) (01) No care administered (02) First aid
EMS Departure Time To Treatment Facility (9997) EMS arrived, provided treatment, but did not transport (9998) EMS arrived, but was not used (9999) Unknown	9997 ROAD VEHICLE 1999 AIR VEHICLE	(03) Resuscitation (04) CPR (05) Emergency cardiac care (06) Life support system monitoring (blood pressure, pulse rate, respiration, EKG) (07) Emergency burn care (08) Combination of above, specify: (98) Other, specify:
EMS Arrival Time At Treatment Facility (9999) Unknown	POAD VEHICLE B	

STOP WORK HERE VARIABLES 66-74 TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES		TRAUMA DATA			
66. Time to Death Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day 31, 2 days = 32, n days = 30 + n up through 30 days = 60) (00) Not fatal (96) Fatal - ruled disease (99) Unknown	<u>37</u> =	71. Glasgow Coma Scale (GCS) Score (at Medical Facility) (00) Not injured (01) Injured - not treated at medical facility (02) No GCS Score at medical facility (03-15) Code the actual value of the initial GCS Score recorded at medical facility. (97) Injured, details unknown (99) Unknown if injured			
67. 1st Medically Reported Cause of Death 68. 2nd Medically Reported Cause of Death 69. 3rd Medically Reported Cause of Death Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death (00) Not fatal or no additional causes (96) Mode of death given but specific injuries are not linked to cause of death. (specify):	ψ <u>3</u> ψ <u>3</u>	72. Was the Occupant Given Blood? (1) No - blood not given (2) Yes - blood given (specify units): (9) Unknown if blood given 73. Arterial Blood Gases (ABG) – HCO ₃ (00) Not injured (01) Injured, ABGs not measured or reported (02-50) Code the actual value of the HCO ₃ (96) ABGs reported, HCO ₃ unknown (97) Injured, details unknown (99) Unknown if injured			
(97) Other result (includes fatal ruled disease) (specify):		BELT USE DETERMINATION			
70. Number of Recorded Injuries for This OccupantCode the actual number of injuries recorded for this occupant. (00) No recorded injuries (97) Injured, details unknown (99) Unknown if injured	49	74. Primary Source of Belt Use Determination (0) Not equipped/not available/destroyed or rendered inoperative (1) Vehicle inspection (2) Official injury data (3) Driver/occupant interview (8) Other (specify): (9) Unknown if belt used			

2. Case Number - Stratum

BEST AVAILABLE

Form Approved O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

OCCUPANT INJURY FORM

National Highway Traffic Safety
Administration

Primary Sampling Unit Number

3. Vehicle Number

01

D59610

4. Occupant Number

Ф2-

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source		Type of	A.I.S 9 Specific	0				Injury Source	Occupant Direct/	Area	
	of Injury Data	Body Region	Anatomic Structure	Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Confidence Level	Indirect Injury	Intrusion Number	ICD-9
1st	5. <u>L</u>	6	7 <u>4</u>	вфЬ	<u>. 74</u>	10.5	11. 9 12	L84	13. <u>l</u>	14.	15.4.0	3 <u>48</u> 5
2nd	16.2	17.L	18.4	19. <u>Ø6</u>	2054	21. <u>£</u>	292	<u> 18 </u>	24. 1	25. <u> </u>	26. <u>4</u> <u>1</u>	<u>852.25</u>
3rd	27	28. 1	29.生	30. <u>Ø</u> 6	31. <u>78</u>	32 <u>4</u>	33. <u>9</u> .34.	L84	35. <u>]</u>	36	37 <u>4</u> 4	8 <u>22.25</u>
					42. <u>/_</u>	43 <u>#</u>						518 <i>4</i>
					53. 少上					58. 1	59 <u>&</u> <u>V</u>	<u>Виь ф</u> І
					4B4							8 <u>52</u> 45
					75. <u>\$2</u>						в1. <u>ФФ</u>	
												922.2
9th	93	94.4	95. <u>9</u> 9	6. <u>#</u>	97. <u>02</u>	98	99. 4100.	L52	101. <u>1</u>	102 1	03. <u>WØ</u>	922.)
10th 1	104	105	106: 16	971	08	109	110111.		112	113 1	14	31 (80)

OCCUPANT INJURY CLASSIFICATION

Body Region Specific Anatomic Level of Injury **Aspect** Structure Head Specific injuries are (2) (3) Right Face assigned consecutive (2) (3) Left Neck Vessels, Nerves, Organs. two-digit numbers beginning (4) (5) (7) Bilateral Thorax Bones, Joints are assigned with 02. (4) Central Abdomen consecutive two digit (5) Spine Anterior numbers beginning with 02. To the extent possible, within (6) **Posterior Upper Extremity** the organizational (8) (7) Superior Lower Extremity The exceptions to this rule framework of the AIS, 00 is (8) (9) Inferior Unspecified apply to: assigned to an injury NFS as (9) Unknown to severity or where only one (0)Whole region Whole Area injury is given in the Type of Anatomic Skin - Abrasion (02)dictionary for that anatomic Structure (04)Skin - Contusion structure. 99 is assigned to (06) Skin - Laceration any injury NFS as to lesion Whole Area (80)Skin - Avulsion or severity. (2) (3) (4) Vessels (10) Amputation Nerves (20) Burn Abbreviated Injury Scale Organs (includes (30)Crush Muscles/ligaments) (40) Degloving Minor Injury (5)Skeletal (includes (50<u>)</u> Injury - NFS (2) (3) (4) Moderate Injury joints) Head - LOC (90) Trauma, other than Serious Injury mechanical Severe Injury Skin Critical Injury Head - LOC (6) Maximum (02) Length of LOC (untreatable) (7) Injured, unknown (04)Level severity (06)of (80) Consciousness (10) Concussion Spine (02)Cervical (04)Thoracic (06)Lumbar

DOUNCE OF INJUNY DATA	INJURY SOURCE CONFIDENCE LEVEL	DIRECT/INDIRECT INJURY
OFFICIAL RECORDS (1) Autopsy records with or without hospital/medical records (2) Hospital/medical records other than emergency room (e.g., discharge summary) (3) Emergency room records only (including associated X-rays or other lab reports) (4) Private physician, walk-in or emergency clinic UNOFFICIAL RECORDS (5) Lay coroner report (6) E.M.S. personnel (7) Interviewee (8) Other source (specify):	(1) Certain (2) Probable (3) Possible (9) Unknown	(1) Direct contact injury (2) Indirect contact injury (3) Noncontact injury (7) Injured, unknown source


SOURCE OF INJURY DATA

INJURY SOURCES FRONT (102) Right side hardware or (183) Air bag-passenger side and (411) Wall mounted head rest (used (001) Windshield armrest object held behind wheel chair) (002) Mirror (103)Right A (A1/A2)-pillar (184) Air bag-passenger side and (412) Other adaptive device (003)Sunvisor (104) Right B-pillar object in mouth (specify):_ (004)Steering wheel rim (105)Other right pillar (specify): (185) Air bag compartment (005) Steering wheel hub/spoke cover-passenger side (006) Steering wheel (combination (106)Right side window glass (186) Air bag compartment EXTERIOR of OCCUPANT'S of codes 004 and 005) (107)Right side window frame cover-passenger side and VEHICLE (007) Steering column, transmission Right side window sill (108)eyewear (451) Hood selector lever, other (109)Right side window glass (187) Air bag compartment (452) Outside hardware (e.g., attachment including one or more of the cover-passenger side and (008) outside mirror, antenna) Cellular telephone or CB radio following: frame, window sill, jewelry Other exterior surface or tires (009)Add on equipment (e.g., tape A (A1/A2)-pillar, B-pillar, or (1881) Air bag compartment (specify): deck, air conditioner) roof side rail. cover-passenger side and Left instrument panel and (010)(110) Other right side object object held (454) Unknown exterior objects below (specify): (189) Air bag compartment (011) Center instrument panel and cover-passenger side and EXTERIOR OF OTHER MOTOR below object in mouth **VEHICLE** (012) Right instrument panel and INTERIOR (190) Other air bag (specify) (501) Front bumper below (151) Seat, back support (502)Hood edge (013) Glove compartment door Belt restraint webbing/buckle (152)(195) Other air bag compartment (503)Other front of vehicle (014) Knee bolster (153)Belt restraint B-pillar or door cover (specify) (015) Windshield including one or (specify): frame attachment point more of the following: front (154) Other restraint system (504)Hood header, A (A1/A2)-pillar, component (specify): ROOF (505)Hood ornament instrument panel, mirror, or (201) Front header (506)Windshield, roof rail, A-pillar steering assembly (driver side (155)Head restraint system (202)Rear header (507) Side surface only) (160)Other occupants (specify): (203)Roof left side rail (508)Side mirrors (016) Windshield including one or (204)Roof right side rail Other side protrusions (509)more of the following: front (161)Interior loose objects (205)Roof or convertible top (specify): header, A (A1/A2)-pillar. (162)Child safety seat (specify): instrument panel, or mirror **FLOOR** (510) Rear surface (passenger side only) Other interior object (specify): (251) Floor (including toe pan) (511) Undercarriage (017) Windshield reinforced by (252)Floor or console mounted (512) Tires and wheels exterior object (specify) transmission lever, including Other exterior of other motor (513)AIR BAG console (019) Other front object (specify): vehicle (specify): _ (170) Air bag-driver side (253) Parking brake handle (171)Air bag-driver side and (254) Foot controls including (514) Unknown exterior of other evewear parking brake motor vehicle LEFT SIDE Air bag-driver side and jewelry (172)(051) Left side interior surface, (173) Air bag-driver side and object REAR OTHER VEHICLE OR OBJECT IN excluding hardware or held (301)Backlight (rear window) THE ENVIRONMENT armrests (174) Air bag-driver slde and object (302)Backlight storage rack, (551) Ground (052) Left side hardware or armrest in mouth door, etc. Other vehicle or object (053) Left A (A1/A2)-pillar (175) Air bag compartment (303)Other rear object (specify): (specify): (054) Left B-pillar cover-driver side (055) Other left pillar (specify): (176) Air bag compartment (599) Unknown vehicle or object cover-driver side and eyewear ADAPTIVE (ASSISTIVE) DRIVING Left side window glass (056)Air bag compartment **EQUIPMENT** NONCONTACT INJURY (057)Left side window frame cover-driver side and jewelry (401) Hand controls for (601) Fire in vehicle (058)Left side window sill (178) Air bag compartment braking/acceleration (602)Flying glass (059)Left side window glass cover-driver side and object (402)Steering control devices (603) Other noncontact injury including one or more of the held (attached to OEM steering Source following: frame, window sill, (179) Air bag compartment wheel) (specify): A (A1/A2)-pillar, B-pillar, or cover-driver side and object in (403) Steering knob attached to (604)Air bag exhaust gases roof side rail mouth steering wheel (060) Other left side object (697) Injured, unknown source (180) Air bag-passenger side (405) Replacement steering wheel (specify): (181) Air bag-passenger side and (i.e., reduced diameter) eyewear (406)Joy stick steering controls (182) Air bag-passenger side and Wheelchair tle-downs (407) RIGHT SIDE jewelry (408)Modification to seat belts. (101) Right side interior surface, (specify): excluding hardware or Additional or relocated armrests switches, (specify): (410) Raised roof

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)


Autopsy and Hospital Records




OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

Autopsy & Hospital Records





OFFICIAL MANAGE		
OFFICIAL INJURY	DATA - SKELETAL	INTUDICO
	DATA ONLLE I AL	

Restrained?

___ No

-xx^{Yes}

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are

Blood Alcohol Level (mg/dl)

BAL = 0

Glasgow Coma Scale Score

GCSS = 03

Units of Blood

Units = 0


Arterial Blood Gases


pH = __.__

LO3-

PCO₂ ____

нсо, ____





BEST AVAILABLE

Form Approved

O.M.B. No. 2127-0021 NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

OCCUPANT INJURY FORM

National Highway Traffic Safety Administration

1. Primary Sampling Unit Number

2. Case Number - Stratum

059610

3. Vehicle Number

4. Occupant Number

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

			-	A.I.S 9	00				Injury	Occupant		
	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Source Confidence Level	Direct/ Indirect Injury	Area Intrusion Number	ICD-9
ist	<u>5.9</u>	6.1	<u>, 9</u>	0. <u>66</u>	9.在办	10	n.3 12	627	13. 9	14.7	15. <u>0</u> 0	<u> 873 9</u>
2nd	16.9	17 <u>.8</u>	18.9	19 <u>. p. 4</u>	20 <u>42</u>	21. <u>1</u>	292	697	219	25. 7	26. <u>P P</u>	924.5
3rd	27 4	28 4	29. 9	30 <u>P</u>	31. <u>4.7</u>	32. <u>L</u>	33. <u>4</u> 34	150	35 <u>3</u>	36. 1	эт. <u>Фф</u>	922.)
4th	38	39	40	41	42	43	4445		46	47	48	
5th	49	50	51	52	53	54	5556.		57	58	559	
6th	60	61	62	63	64	65	6667.		68	69	70	
7th	71	72	73	74	75	76	7778.		79	80 1	81	
8th	82	83	84 8	35	86	87	8889.		90	91 6	92	 .
9th	93	94	95 8	06	97	98	99100.		101	102 1	03	
10th 1	104	105	106 10	071	08	109	110111.		112	113 1	14	

OCCUPANT INJURY CLASSIFICATION **Body Region Specific Anatomic** Level of Injury **Aspect** Structure Head Specific injuries are (2) (3) (4) (5) (6) (7) Face Right assigned consecutive (2) (3) Left Neck Vessels, Nerves, Organs. two-digit numbers beginning Bilateral Thorax Bones, Joints are assigned with 02. Abdomen Central consecutive two digit (5) Spine Anterior numbers beginning with 02. To the extent possible, within (6) Upper Extremity Posterior the organizational (8) Lower Extremity Superior The exceptions to this rule framework of the AIS, 00 is (9) (8) Unspecified Inferior apply to: assigned to an injury NFS as Unknown to severity or where only one Whole region Whole Area injury is given in the Type of Anatomic (02)Skin - Abrasion dictionary for that anatomic Structure (04) Skin - Contusion structure. 99 is assigned to (06) Skin - Laceration any injury NFS as to lesion Whole Area (80) Skin - Avulsion (2) (3) or severity. Vessels (10)Amputation Nerves (20) Burn Abbreviated Injury Scale (4) Organs (includes (30)Crush Muscles/ligaments) Degloving (40)Minor Injury (5) Skeletal (includes (50) Injury - NFS (2) Moderate Injury joints) Head - LOC **(90)** Trauma, other than (3) Serious Injury mechanical (4) (5) Severe Injury **(9)** Skin Critical Injury Head - LOC (6)Maximum (02) Length of LOC (untreatable) Injured, unknown (04)Level severity (06)of (80)Consciousness (10) Concussion <u>Spine</u> (02)Cervical (04)Thoracic

(06)

SOURCE OF INJURY DATA

Lumbar


INJURY SOURCE DIRECT/INDIRECT INJURY CONFIDENCE LEVEL OFFICIAL RECORDS (1) Autopsy records with or (1) Certain without hospital/medical Direct contact injury Probable (2)Indirect contact injury records Possible (3) (2) Hospital/medical records other Noncontact injury (9) Unknown than emergency room Injured, unknown source (e.g., discharge summary) (3) Emergency room records only (including associated X-rays or other lab reports) (4) Private physician, walk-in or emergency clinic **UNOFFICIAL RECORDS** (5) Lay coroner report (6) E.M.S. personnel (7) Interviewee (8), Other source (specify): (9) Police

INJURY SOURCES FRONT (102) Right side hardware or (183) Air bag-passenger side and Wall mounted head rest (used (411)(001) Windshield object held (002)behind wheel chair) Mirror Right A (A1/A2)-pillar (103)(184) Air bag-passenger side and (412) Other adaptive device (003)Sunvisor (104) Right B-pillar object in mouth (004)(specify): Steering wheel rim (105)Other right pillar (specify): (185) Air bag compartment (005)Steering wheel hub/spoke cover-passenger side (006)Steering wheel (combination (106)Right side window glass (186)Air bag compartment EXTERIOR of OCCUPANT'S of codes 004 and 005) (107)Right side window frame cover-passenger side and VEHICLE (007)Steering column, transmission (108)Right side window slll evewear (451) Hood selector lever, other Right side window glass (109)(187) Air bag compartment Outside hardware (e.g., (452)attachment including one or more of the cover-passenger side and outside mirror, antenna) (800) Cellular telephone or CB radio following: frame, window sill, jewelry (009)(453)Other exterior surface or tires Add on equipment (e.g., tape A (A1/A2)-pillar, B-pillar, or (188) Air bag compartment deck, air conditioner) (specify): roof side rail. cover-passenger side and (010)Left instrument panel and (110) Other right side object object held (454) Unknown exterior objects below (specify): (189) Air bag compartment (011) Center instrument panel and cover-passenger side and EXTERIOR OF OTHER MOTOR below object in mouth **VEHICLE** (012) Right instrument panel and INTERIOR (190)Other air bag (specify) (501) Front bumper below Seat, back support (151)(502) Hood edge (013) Glove compartment door Belt restraint webbing/buckle (152)(195) Other air bag compartment (503)Other front of vehicle (014) Knee bolster (153)Belt restraint B-pillar or door cover (specify) (015) Windshield including one or (specify): frame attachment point more of the following: front (154) Other restraint system (504)header, A (A1/A2)-pillar, Hood component (specify): ROOF (505)Hood ornament instrument panel, mirror, or (201) Front header Windshield, roof rail, A-pillar (506)steering assembly (driver side (155) Head restraint system (202)Rear header (507)Side surface only) (160) Other occupants (specify): (203)Roof left side rail (016) Windshield Including one or (508)Side mirrors Roof right side rail (204)(509)Other side protrusions more of the following: front Interior loose objects (205) Roof or convertible top header, A (A1/A2)-pillar, (specify): (162)Child safety seat (specify): Instrument panel, or mirror FLOOR (510)Rear surface (passenger side only) (163)Other interior object (specify): (251) Floor (including toe pan) (511) (017) Windshield reinforced by Undercarriage (252)Floor or console mounted (512)exterior object (specify) Tires and wheels transmission lever, including (513) Other exterior of other motor AIR BAG console vehicle (specify): (019) Other front object (specify): (170) Air bag-driver side Parking brake handle (253)(171) Air bag-driver side and (254) Foot controls including (514) Unknown exterior of other eyewear parking brake **LEFT SIDE** motor vehicle (172) Air bag-driver side and jewelry (051) Left side interior surface, (173) Air bag-driver side and object REAR OTHER VEHICLE OR OBJECT IN excluding hardware or (301) Backlight (rear window) THE ENVIRONMENT armrests (174) Air bag-driver side and object (302)Backlight storage rack. (052) Left side hardware or armrest (551) Ground in mouth door, etc. (053)(598) Other vehicle or object Left A (A1/A2)-pillar (175) Air bag compartment (303) Other rear object (specify): (054)Left B-pillar (specify): cover-driver side (055)Other left pillar (specify): (176) Air bag compartment Unknown vehicle or object (599)cover-driver side and eyewear ADAPTIVE (ASSISTIVE) DRIVING Left side window glass (056)(177) Air bag compartment EQUIPMENT (057) Left side window frame NONCONTACT INJURY cover-driver side and jewelry (401) Hand controls for (601) Fire in vehicle (058) Left side window sill (178) Air bag compartment braking/acceleration Flying glass (059) Left side window glass (602)cover-driver side and object (402)Steering control devices (603)Other noncontact Injury including one or more of the held (attached to OEM steering following: frame, window sill, source (179) Air bag compartment wheel) A (A1/A2)-pillar, B-pillar, or (specify): cover-driver slde and object in (403) Steering knob attached to (604)Air bag exhaust gases roof side rail. steering wheel (060)(697) Injured, unknown source Other left side object (180)Air bag-passenger side (405)Replacement steering wheel (specify): (181) Air bag-passenger side and (i.e., reduced diameter) evewear (406)Joy stick steering controls Air bag-passenger side and (407)Wheelchair tle-downs RIGHT SIDE jewelry (408)Modification to seat belts. (101) Right side interior surface, (specify):_ excluding hardware or (409)Additional or relocated armrests switches, (specify): (410) Raised roof

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES


Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)


Police Report



OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





	OFFICIAL IN ILIBY DATA	BEST AV	VAILA
Restrained?	OFFICIAL INJURY DATA	— SKELETAL INJURIES	
	Cata the Leasting Only is a		
Sou	cate the Location, Specific Anatomic Structure, Detail (size, depth, fracture irce of all injuries indicated by official sources (or from PAR or other unoffici vailable.)	type, head injury clinical signs and neurological deficits), and	
— Yes una	/ailable.)	lal sources if medical records and interviewee data are	
Blood Alcohol Level mg/dl)			
BAL =	(\cdot, \cdot, \cdot)		
	(60g)	d b	
lasgow Coma			
cale Score			
css =			
its of Blood			
/en			
nits =		//// * # */ \\9\\	
			•
erial Blood Gases			
d =		THE CASASS	
O ₂ =			
co,			
co,	\\\ <i>\\</i>	\\\	
		\ \\ ///	
	\\ \(\) \(\)	$\bigwedge \bigwedge \bigwedge \bigwedge$	
		(11) (\(\lambda\)	
	\\\\/\\ <i>\\\\</i>	\(\(\(\)\\\\\\	
	W. W	\\V\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
		\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	

GENERAL VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

gmnistration	CRASHWURTHINESS DATA STSTEM
Primary Sampling Unit Number	12. Speed Limit ϕ 8 9
2. Case Number - Stratum DS96 10	(000) No statutory limit Code posted or statutory speed limit in kmph
3. Vehicle Number	(999) Unknown
VEHICLE IDENTIFICATION	55 mph X 1.6093 = 49 kmph
4. Vehicle Model Year Code the last two digits of the model year (99) Unknown 5. Vehicle Make (specify):	13. Police Reported Alcohol Presence For Driver (0) No alcohol present (1) Yes alcohol present (7) Not reported (8) No driver present (9) Unknown
Applicable codes are found in your NASS Data Collection, Coding and Editing Manual. (99) Unknown 6. Vehicle Model (specify): CAND AM Applicable codes are found in your NASS Data Collection, Coding and Editing Manual. (999) Unknown	14. Alcohol Test Result For Driver Code actual value (decimal implied before first digit—0.xx) (95) Test refused (96) None given (97) AC test performed, results unknown (98) No driver present (99) Unknown Source:
7. Body Type Note: Applicable codes may be found on the back of this page.	15. Police Reported Other Drug Presence For Driver (0) No other drug(s) present (1) Yes other drug(s) present
8. Vehicle Identification Number	(7) Not reported (8) No driver present
1 6 2 N E 1 4 3 6 P M X X X X X X X X X X X X X X X X X X	(9) Unknown 16. Other Drug Specimen Test Result For Driver (0) No specimen test given (1) Drug(s) not found in specimen (2) Drug(s) found in specimen, (specify):
9. Vehicle Special Use (This Trip) (0) No special use (1) Taxi (2) Vehicle used as school bus (3) Vehicle used as other bus	 (3) Specimen test given, results unknown or not obtained (8) No driver present (9) Unknown if specimen test given
(4) Military (5) Police	17. Driver's Zip Code
(6) Ambulance (7) Fire truck or car	(00001) Driver not a resident of U.S. or territories
(8) Other (specify):	Code actual 5-digit zip code
(9) Unknown OFFICIAL RECORDS	(99998) No driver present (99999) Unknown
	a
10. Police Reported Vehicle Disposition (0) Not towed due to vehicle damage (1) Towed due to vehicle damage (9) Unknown	18. Driver's Race/Ethnic Origin (1) White (non-Hispanic) (2) Black (non-Hispanic) (3) White (Hispanic)
11. Police Reported Travel Speed Code to the nearest kmph (NOTE: 000 means less than 0.5 kmph) (160) 159.5 kmph and above (999) Unknown	(4) Black (Hispanic) (5) American Indian, Eskimo or Aleut (6) Asian or Pacific Islander (7) Other (specify): (8) No driver present
mph X 1.6093 = kmph	(9) Unknown

CDS APPLICABLE VEHICLES

Automobiles

- (01) Convertible (excludes sun-roof, t-bar)
- (O2) 2-door sedan, hardtop, coupe
- (03) 3-door/2-door hatchback
- (04) 4-door sedan, hardtop
- (05) 5-door/4-door hatchback
- (06) Station wagon (excluding van and truck based)
- (07) Hatchback, number of doors unknown
- (08) Other automobile type (specify):
- (09) Unknown automobile type

Automobile Derivatives

- (10) Auto based pickup (includes El Camino, Caballero, Ranchero, Brat, and Rabbit pickup)
- (11) Auto based panel (cargo station wagon, auto based ambulance/hearse)
- (12) Large limousine more than four side doors or stretched chassis
- (13) Three-wheel automobile or automobile derivative

Utility Vehicles (≤ 4,536 kgs GVWR)

- (14) Compact utility (Jeep CJ-2 CJ-7, Scrambler, Golden Eagle, Renegade, Laredo, Wrangler, Cherokee [84 and after], Dispatcher, Raider, Bronco II, Bronco [76 and before], Explorer, S-10 Blazer, Geo Tracker, Bravada, S-15 Jimmy, Thing, Pathfinder, Trooper, Trooper II, Rodeo, Amigo, Navajo, 4-Runner, Montero, Passport, Samurai, Sidekick, Rocky)
- (15) Large utility (includes Jeep Cherokee [83 and before], Ramcharger, Trailduster, Bronco-fullsize [78 and after], fullsize Blazer, fullsize Jimmy, Hummer, Landcruiser, Rover, Scout, Yukon)
- (16) Utility station wagon (Chevy Suburban, GMC Suburban, Travelall, Grand Wagoneer, includes suburban limousine)
- (19) Utility, unknown body type

Van Based Light Trucks (≤ 4,536 kgs GVWR)

- (20) Minivan (Town and Country, Caravan, Grand Caravan, Voyager, Grand Voyager, Mini-Ram, Vista, Aerostar, Windstar, Villager, Lumina APV, Trans Sport, Silhouette, Astro, Safari, Toyota Van, Toyota Minivan, Previa, Nissan Minivan, Quest, Mitsubishi Minivan, Expo Wagon, Vanagon/Camper.)
- (21) Large van (B150-B350, Sportsman, Royal, Maxiwagon, Ram, Tradesman, Voyager [83 and before], E150-E350, Econoline, Clubwagon, Chateau, G10-G30, Chevy Van, Beauville, Sport Van, G15-G35, Rally Van, Vandura.)
- (22) Step van or walk-in van (≤ 4,536 kgs GVWR)
- (23) Van based motorhome (≤ 4,536 kgs GVWR)
- (24) Van based school bus (\leq 4,536 kgs GVWR)
- (25) Van based other bus (≤ 4,536 kgs GVWR)
- (28) Other van type (Hi-Cube Van, Kary) (specify):
- (29) Unknown van type

Light Conventional Trucks (Pickup style cab, ≤ 4.536 kgs GVWR)

- (30) Compact pickup (D50, Colt P/U, Ram 50, Dakota, Arrow Pickup [foreign], Ranger, Courier, S-10, T-10, LUV, S-15, T-15, Sonoma, Datsun/Nissan Pickup, P'up, Mazda Pickup, Toyota Pickup, Mitsubishi Pickup)
- (31) Large Pickup (Jeep Pickup, Comanche, Ram Pickup, D100-D350, W100-W350, F100-F350, C10-C35, K10-K35, R10-R35, V10-V35, Silverado, Sierra, R100-R500, T100)
- (32) Pickup with slide-in camper
- (33) Convertible pickup
- (39) Unknown pickup style light conventional truck type

Other Light Trucks (≤ 4,536 kgs GVWR)

- (40) Cab chassis based (includes rescue vehicles, light stake, dump, and tow truck)
- (41) Truck based panel
- (42) Light truck based motorhome (chassis mounted)
- (45) Other light conventional truck type
- (48) Unknown light truck type
- (49) Unknown light vehicle type (automobile, utility, van, or light truck)

OTHER VEHICLES

Buses (Excludes Van Based)

- (50) School bus (designed to carry students, not cross country or transit)
- (58) Other bus type (e.g., transit, intercity, bus based motorhome) (specify):
- (59) Unknown bus type

Medium/Heavy Trucks (> 4,536 kgs GVWR)

- (60) Step van (> 4,536 kgs GVWR)
- (61) Single unit straight truck (4,536 kgs < GVWR ≤ 8,845 kgs)
- (62) Single unit straight truck (8,845 kgs < GVWR ≤ 11,793 kgs)
- (63) Single unit straight truck (> 11,793 kgs GVWR)
- (64) Single unit straight truck, GVWR unknown
- (65) Medium/heavy truck based motorhome
- (67) Truck-tractor with no cargo trailer
- (68) Truck-tractor pulling one trailer
- (69) Truck-tractor pulling two or more trailers(70) Truck-tractor (unknown if pulling trailer)
- (78) Unknown medium/heavy truck type
- (79) Unknown truck type (light/medium/heavy)

Motored Cycles (Does Not Include All-Terrain Vehicles/Cycles)

- (80) Motorcycle
- (81) Moped (motorized bicycle)
- (82) Three-wheel motorcycle or moped
- (88) Other motored cycle (minibike, motorscooter) (specify):
- (89) Unknown motored cycle type

Other Vehicles

- (90) ATV (All-Terrain Vehicle) and ATC (All-Terrain Cycle)
- (91) Snowmobile
- (92) Farm equipment other than trucks
- (93) Construction equipment other than trucks
- (97) Other vehicle type
- (99) Unknown body type

	DDC OD A CLU ENVIDONINGENITAL DATA			
	PRECRASH ENVIRONMENTAL DATA	25	Desduse Confess Condition	1
	1.	7 23	. Roadway Surface Condition	
19.	Relation To Interchange Or Junction	1	(1) Dry	
	(0) Non-interchange area and non-junction	1	(2) Wet	
	(1) Interchange area related		(3) Snow or slush	
	(1) Iliterchange area related	1	(4) Ice	
			(5) Sand, dirt, or oil	
	Non-Interchange junctions			
	(2) Intersection related		(8) Other (specify):	
	(3) Driveway, alley access related	1	(9) Unknown	
	(4) Other junction (specify)			
	(v) Constitution (opening)	126	- Philip Assaults	ì
	(5) Unknown type of junction	20	. Light Conditions	1
	(5) Unknown type or junction		(1) Daylight	
	101 11 1		(2) Dark	
	(9) Unknown		(3) Dark, but lighted	
	•		(4) Dawn	
	ϕ		(5) Dusk	
20.	Trafficway Flow Ψ		(9) Unknown	
	(0) Not physically divided (two way traffic)	1	(3) Officiowifi	
	(1) Divided trafficway-median strip without positive	1		
	barrier barrier	١)
		27	. Atmospheric Conditions	
	(2) Divided trafficway-median strip with positive		(0) No adverse atmospheric-related driving	
	barrier		conditions	
	(3) One way traffic	l	(1) Rain	
	(9) Unknown	l	(2) Sleet/hail	
	2-	l	(3) Snow	
21.	Number Of Travel Lanes		(4) Fog	
	(1) One	l	(5) Rain and fog	
	(2) Two	ļ	(6) Sleet and fog	
	(3) Three		(7) Other (e.g., smog, smoke, blowing sand or	
	(4) Four		dust, etc.) (specify):	
	• • • •		duct stail laboury.	
	(5) Five		(9) Unknown	
	(6) Six		(9) Unknown	
	(7) Seven or more]		1
	(9) Unknown	20.	. Traffic Control Device	<u> ()</u>
			(0) No traffic control(s)	1
	Roadway Alignment 3		(1) Traffic control signal (not RR crossing)	
22.		İ		
	(1) Straight		Regulatory	
	(2) Curve right		(2) Stop sign	
	(3) Curve left		(3) Yield sign	
	(9) Unknown		(4) School zone sign	
		1		
	į		(5) Other regulatory sign (specify):	
23.	Roadway Profile			
	(1) Level		(6) Warning sign (not RR crossing)	
	(2) Uphill grade (>2%)		(7) Unknown sign	
	(3) Hill crest		(8) Miscellaneous/other controls including RR	
	(4) Downhill grade (>2%)		controls (specify):	
	(5) Sag		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
			(9) Unknown	
	(9) Unknown		(6) 5	
	^			
24	Roadway Surface Type	20	Troffic Control Davin 5	1
		29.	Traffic Control Device Functioning	Ψ_
	(1) Concrete		(0) No traffic control device	•
	(2) Bituminous (asphalt)		(1) Traffic control device not functioning	
	(3) Brick or block		(specify):	
	(4) Slag, gravel, or stone			
	(5) Dirt		(2) Traffic control device functioning properly	
	(8) Other (specify):		(9) Unknown	
	(9) Unknown			

	PRECRASH DRIVER RELATED DATA	THIS VEHICLE TRAVELLING
30	Driver's Distraction/Inattention To Driving	(10) Over the lane line on left side of travel lane
JU.	(Prior To Recognition Of Critical Event)	(11) Over the lane line on right side of travel lane (12) Off the edge of the road on the left side
	(00) No driver present	(12) Off the edge of the road on the right side
	(01) Attentive or not distracted	(14) End departure
	(02) Looked but did not see	(15) Turning left at intersection
	Distractions	(16) Turning right at intersection
	(03) By other occupant(s), (specify):	(17) Crossing over (passing through) intersection
	(05) by other occupant(s), (specify).	(18) This vehicle decelerating
	(04) By moving object in vehicle (specify):	(19) Unknown travel direction
	(o.) By morning object in termore (opening).	(vo) omalom data anodasii
	(05) While talking or listening to cellular phone (spe	cify OTHER MOTOR VEHICLE IN LANE
	location and type of phone):	(50) Other vehicle stopped
		(51) Traveling in same direction with lower steady
	(06) While dialing cellular phone (specify location a	nd speed
	type of phone):	(52) Traveling in same direction while decelerating
	(07) 100 11 - 11 - 12 - 12 - 13 - 14 - 14	(53) Traveling in same direction with higher speed
	(07) While adjusting climate controls	(54) Traveling in opposite direction
	(08) While adjusting radio, cassette, CD (specify):	(55) In crossover
	(09) While using other device/controls integral to	—— (56) Backing
	vehicle (specify):	(59) Unknown travel direction of other motor vehicle in
	(10) While using or reaching for device/object brou	ant lane
	into vehicle (specify):	
	(11) Sleepy or fell asleep	OTHER MOTOR VEHICLE ENCROACHING INTO
	(12) Distracted by outside person, object, or event	LANE
	(specify):	(60) From adjacent lane (same direction)—over left
	(13) Eating or drinking	lane line
	(14) Smoking related	(61) From adjacent lane (same direction)—over right
	(97) Distracted/inattentive, details unknown	lane line
	(98) Other, distraction (specify):	(62) From opposite direction—over left lane line
	(00) II-l	(63) From opposite direction—over right lane line
	(99) Unknown	(64) From parking lane
31.	. Pre-Event Movement (Prior to	(65) From crossing street, turning into same direction
	Recognition of Critical Event)	(66) From crossing street, across path
	(00) No driver present	(67) From crossing street, turning into opposite
	(01) Golng straight	direction
	(02) Decelerating in traffic lane	(68) From crossing street, intended path not known
	(03) Accelerating in traffic lane (04) Starting in traffic lane	(70) From driveway, turning into same direction
	(05) Stopped in traffic lane	(71) From driveway, across path
	(06) Passing or overtaking another vehicle	(72) From driveway, turning into opposite direction
	(07) Disabled or parked in travel lane	(73) From driveway, intended path not known
	(08) Leaving a parking position	(74) From entrance to limited access highway
	(09) Entering a parking position	(78) Encroachment by other vehicle—details unknown
	(10) Turning right	DEDESTRIAN DEDALOYOURT OR OTHER
	(11) Turning left	PEDESTRIAN, PEDALCYCLIST, OR OTHER NONMOTORIST
	(12) Making a U-turn	(80) Pedestrian in roadway
	(13) Backing up (other than for parking position)	(81) Pedestrian approaching roadway
	(14) Negotiating a curve	(82) Pedestrian—unknown location
	(15) Changing lanes	(83) Pedalcyclist or other nonmotorist in roadway
	(16) Merging	(05) Fedalcyclist of other floriffictorist in foadway
	(17) Successful avoidance maneuver to a previous	(specify):
	critical event	(84) Pedalcyclist or other nonmotorist approaching
	(97) Other (specify):(99) Unknown	roadway, (specify):
	` '	(85) Pedalcyclist or other nonmotorist—unknown
32.	. Critical Precrash Event	location
	THIS VEHICLE LOSS OF CONTROL DUE TO:	(specify):
	(01) Blow out or flat tire	
	(02) Stalled engine	OBJECT OR ANIMAL
	(03) Disabling vehicle fallure (e.g., wheel fell off)	(87) Animal In roadway
	(specify):	(88) Animal approaching readures
	(04) Non-disabling vehicle problem (e.g., hood flew	up) (89) Animal—unknown location
	(specify):	(90) Object in roadway
	(specify):	(91) Object approaching roadway
	(06) Traveling too fast for conditions	— (92) Object—unknown location
	(08) Other cause of control loss (specify):	(98) Other critical precrash event (specify):
	(09) Unknown cause of control loss	(99) Unknown

Category	Configur- ation	ACCIDENT TYPES (includes intent)
	A. Right Roadside Departure	DRIVE OFF CONTROL/ TRACTION LOSS WITH VEH. PED. ANIM. 01 02 03 CTT 04 05 AVOID COLLISION SPECIFICS SPECIFICS UNKNOWN
I Single driver	B. Left Roadside Departure	DRIVE OFF CONTROL/ AVOID COLLISION SPECIFICS SPECIFICS OTHER UNKNOWN
	C. Forward Impact	PARKED VEHICLE STA. OBJECT PEDESTRIAN/ ANIMAL END DEPARTURE SPECIFICS UNKNOWN
cway	D. Rear-End	20 22 24 26 25 28 30 (EACH• 32) (EACH• 33) STOPPED SLOWER 25,26,27 DECEL 29,30,31 20 30 (EACH• 32) (EACH• 33) SPECIFICS SPECIFICS UNKNOWN
II Same Trafficway Same Directlon	E. Forward Impact	34 35 36 37 38 40 (EACH• 42) (EACH• 43) CONTROL/ TRACTION LOSS CONTROL/ TRACTION LOSS WITH VEHICLE WITH OBJECT (EACH• 42) (EACH• 43) SPECIFICS SPECIFICS UNKNOWN
	F. Sideswipe/ Angie	46 45 45 47 (EACH• 48) (EACH• 49) SPECIFICS OTHER SPECIFICS UNKNOWN
ay ction	G. Head-On	(EACH • 52) (EACH • 53) LATERAL MOVE SPECIFICS OTHER SPECIFICS UNKNOWN
Same Trafficway Opposite Direction	H. Forward Impact	54 55 57 58 60 (EACH- 62) (EACH- 63) CONTROL/ TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LOSS TRACTION LO
=	i. Sideswipe/ Angie	65 (EACH• 66) (EACH• 67) SPECIFICS OTHER SPECIFICS UNKNOWN
N Change Trafficway Vehicle Turing	J. Turn Across Path	68 71 70 73 72 (EACH• 74) (EACH• 75) SPECIFICS SPECIFICS OTHER UNKNOWN
	K. Turn into Path	77 79 78 80 81 82 (EACH• 84) (EACH• 85) TURN INTO SAME DIRECTION TURN INTO OPPOSITE DIRECTION OTHER UNKNOWN
v Intersecting Paths (Vehice Damage)	L. Straight Paths	89 (EACH• 90) (EACH• 91) SPECIFICS OTHER SPECIFICS UNKNOWN
VI. Miscel- laneous	M. Backing Etc.	92 93 OTHER VEHICLE OR OBJECT 98 Other Accident Type 99 Unknown Accident Type 99 No impact

Source:

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

(00) No rollover	(57) Fence
(01-30) — Vehicle Number	(58) Wall
	(59) Building
Noncollision	(60) Ditch or culvert
(31) Turn-over — fall-over	(61) Ground
(32) No rollover impact initiation (end-over-end)	(62) Fire hydrant
(34) Jackknife	(63) Curb
(***	(64) Bridge
Collision With Fixed Object	(68) Other fixed object (specify):
(41) Tree (≤ 10 cm in diameter)	(00) 0000 more 00,000 (0) 0000,77
(42) Tree (> 10 cm in diameter)	(69) Unknown fixed object
(43) Shrubbery or bush	(00)
(44) Embankment	Collision with Nonfixed Object
	(70) Passenger car, light truck, van, or other
(45) Breakaway pole or post (any diameter)	vehicle not in-transport
, -, -, -, -, -, -, -, -, -, -, -, -, -,	(71) Medium/heavy truck or bus not in-transport
Nonbreakaway Pole or Post	(76) Animal
(50) Pole or post (≤ 10 cm in diameter)	(77) Train
(51) Pole or post (> 10 cm but ≤ 30 cm in	(78) Trailer, disconnected in transport
diameter)	(79) Object fell from vehicle in-transport
(52) Pole or post (> 30 cm in diameter)	(88) Other nonfixed object (specify):
(53) Pole or post (diameter unknown)	(out of the manufact of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control
(see a post parameter annual see,	(89) Unknown nonfixed object
(54) Concrete traffic barrier	(oc) chance object
(55) Impact attenuator	(98) Other event (specify):
(56) Other traffic barrier (includes guardrail)	(ac) acide at an appearing to
(specify):	(99) Unknown event or object
	(00) C. Milettii Otolik ol objook

National Accident Sampling System-Crashworthiness Da	ta System: General Vehicle Form BEST AVAILABLE Page 6
OVERRIDE/UNDERRIDE (THIS VEHICLE)	ACCIDENT RECONSTRUCTION PROGRAMS HIGHEST DELTA V
51. Front Override/Underride (this Vehicle)	50 Pair (- Taral / Par Harry Patra / 10 2)
52. Rear Override/Underride (this Vehicle) (0) No override/underride, or not an end-to-end impact between two CDS applicable vehicles, and no medium/heavy truck or bus underride	58. Basis for Total (Resultant) Delta V (highest) (00) No vehicle inspection
Override (see specific CDC) [Between 2 CDS applicable vehicles (Bodytype, GV07 = 1-49)] (1) 1st CDC (2) 2nd CDC (3) Other not automated CDC (specify):	Delta V Calculated (01) Reconstruction program-damage only routine (02) Reconstruction program-damage and trajectory routine (03) Missing vehicle algorithm
Underride (see specific CDC) [Between 2 CDS applicable vehicles (Bodytype, GV07 = 1-49)] (4) 1st CDC (5) 2nd CDC (6) Other not automated CDC (specify):	Delta V Not Calculated (04) At least one vehicle (which may be this vehicle) is beyond the scope of an acceptable reconstruction program, regardless of collision conditions.
(7) Medium/heavy truck or bus override (of any configuration)(9) Unknown	All vehicles within scope (CDC applicable) of reconstruction program but one of the collision conditions is beyond the scope of the
HEADING ANGLE AT IMPACT FOR HIGHEST DELTA V	reconstruction program or other acceptable reconstruction technique, regardless of adequacy of damage data.
Values: (000)-(359) Code actual value (996) Non-horizontal impact (997) Noncollision (998) Impact with object (999) Unknown	(05) Rollover (06) Other non-horizontal forces (07) Sideswipe type damage (08) Severe override (09) Yielding object
53. Heading Angle For This Vehicle 2 1 0	(10) Overlapping damage
54. Heading Angle For Other Vehicle ϕ 9	(11) All vehicle and collision conditions are within scope of one of the acceptable reconstruction
RECONSTRUCTION DATA	programs, but there is insufficient data
55.Towed Trailing Unit (0) No towed unit (1) Yes—towed trailing unit (9) Unknown	available, (specify):
56. Documentation of Trajectory Data for This Vehicle (0) No (1) Yes	(98) Other, (specify):
57. Post Collision Condition of Tree or Pole (For Highest Delta V) (0) Not collision (for highest delta V) with tree or pole (1) Not damaged (2) Cracked/sheared (3) Tilted < 45 degrees (4) Tilted ≥ 45 degrees (5) Uprooted tree (6) Separated pole from base (7) Pole replaced (8) Other (specify):	

(9) Unknown

COMPUTER GENERA	ATED CRASH SEVERITY
Highes 59. Total Delta V	Highest 63. Impact Speed 998
Nearest kmph (highest) Nearest kmph (secondary)	Nearest kmph (highest) Nearest kmph (secondary) (NOTE: 000 means
(NOTE: 000 means less than 0.5 kmph) (160) 159.5 kmph and above (999) Unknown Highes	less than 0.5 kmph) (160) 159.5 kmph and above (998) Trajectory algorithm not run (999) Unknown
60. Longitudinal Component of Delta V + 4 3 5	DELTA V CONFIDENCE LEVEL
Nearest kmph (highest) Nearest kmph (secondary) (NOTE:000 means greater than -0.5 kmph and less than +0.5 kmph) (±160) ±159.5 kmph and above (999) Unknown	64. Confidence In Reconstruction Program Results (For Highest Delta V) (0) No reconstruction (1) Collision fits model — results appear reasonable (2) Collision fits model — results appear high (3) Collision fits model — results appear low (4) Borderline reconstruction — results appear reasonable
Highes 61. Lateral Component of Delta V + /	OTHER SPEED ESTIMATE
-39.7 Nearest kmph (highest)	Highest 65. Barrier Equivalent Speed
Nearest kmph (secondary) (NOTE:000 means greater than -0.5 kmph and less than +0.5 kmph) (±160) ±159.5 kmph and above (999) Unknown Highest 62. Energy Absorption Nearest 100 joules (highest) Nearest 100 joules (secondary) (NOTE: 0000 means less than 50 joules) (9997) 999,650 joules or more (9999) Unknown	Nearest kmph (highest) Nearest kmph (secondary) (NOTE: 000 means less than 0.5 kmph) (160) 159.5 kmph and above

National Accident Sampling System-Crashworthiness Data System: General Vehicle Form BEST AVAILABLE Page 8 ESTIMATED DELTA V **INSPECTION TYPE** 66. Estimated Highest Delta V (Researcher 67. Type of Vehicle Inspection Determined) (0) No inspection (0) Reconstruction Delta V coded (1) Vehicle fully repaired-no damage evident (2) Partial inspection (specify): Estimated Delta V (1) Less than 10 kmph (3) Complete inspection (2) \geq 10 kmph but < 25 kmph (3) \geq 25 kmph but < 40 kmph (4) \geq 40 kmph but < 55 kmph **DELTA V EVENT NUMBER** (5) \geq 55 kmph Other estimates of damage severity 68. Delta V Event Number (6) Minor Code the accident event sequence (7) Moderate number that resulted in the Delta V that (8) Severe has been coded above for this vehicle (99) Unknown (9) Unknown *** IF THE CDS APPLICABLE VEHICLE WAS NOT INSPECTED (I.E., GV67 = 0), *** DO NOT COMPLETE THE EXTERIOR AND INTERIOR VEHICLE FORMS

*** IF GV07 DOES NOT EQUAL 01-49, DO NOT COMPLETE *** THE EXTERIOR VEHICLE, INTERIOR VEHICLE, OCCUPANT ASSESSMENT, AND OCCUPANT INJURY FORMS.

OCCUPANT ASSESSMENT FORM

Form Approved O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM CRASHWORTHINESS DATA SYSTEM

A. D. L. C. Library Brown box	OCCUPANT'S SEATING
1. Primary Sampling Unit Number	10. Occupant's Seat Position
2. Case Number - Stratum DS 96 1 \$\Phi\$	Front Seat
3. Vehicle Number <u> </u>	(11) Left side (12) Middle
4. Commont Number	(13) Right side
4. Occupant Number	(14) Other (specify):
OCCUPANT'S CHARACTERISTICS	(15) On or in the lap of another occupant
5. Occupant's Age Code actual age at time of accident. (00) Less than one year old (specify by month): (97) 97 years and older (99) Unknown	Second Seat (21) Left side (22) Middle (23) Right side (24) Other (specify): (25) On or in the lap of another occupant
6. Occupant's Sex (1) Male (2) Female-not reported pregnant (3) Female-pregnant-1st trimester(1st-3rd month) (4) Female-pregnant-2nd trimester(4th-6th month) (5) Female-pregnant-3rd trimester(7th-9th month) (6) Female-pregnant-term unknown (9) Unknown	Third Seat (31) Left side (32) Middle (33) Right side (34) Other (specify): (35) On or in the lap of another occupant Fourth Seat (41) Left side (42) Middle (43) Right side (44) Other (specify):
7. Occupant's Height Code actual height to the nearest centimeter. (999) Unknown 7 3 inches X 2.54 = centimeters	(45) On or in the lap of another occupant (97) In or on unenclosed area (98) Other seat (specify): (99) Unknown
8. Occupant's Weight Code actual weight to the nearest kilogram. (999) Unknown L	11. Occupant's Posture (0) Normal posture Abnormal posture (1) Kneeling or standing on seat (2) Lying on or across seat (3) Kneeling, standing or sitting in front of seat (4) Sitting sideways or turned to talk with another occupant or to look out a rear window (5) Sitting on a console (6) Lying back in a reclined seat position (7) Bracing with feet or hands on a surface in front of seat (8) Other abnormal posture (specify): (9) Unknown
S Form 4334 (1/96) This report is sutherized by P.I. 99 562 T	BEST AVAILABLE

	EJECTION/ENTRAPMENT							
	Ejection (0) No ejection (1) Complete ejection (2) Partial ejection (3) Ejection, unknown degree (9) Unknown	Φ	15. Medium Status (Immediately Prior To Impact) (0) No ejection (1) Open (2) Closed (3) Integral structure (9) Unknown					
13.	Ejection Area (0) No ejection (1) Windshield (2) Left front (3) Right front (4) Left rear (5) Right rear (6) Rear (7) Roof (8) Other area (e.g., back of pickup, etc.) (specify): (9) Unknown	<u></u>	16. Entrapment (0) Not entrapped/exit not inhibited (1) Entrapped/pinned - mechanically restrained (2) Could not exit vehicle due to jammed doors, fire, etc. (specify): (9) Unknown 17. Occupant Mobility (0) Occupant fatal before removed from vehicle (1) Removed from vehicle while unconscious or not oriented to time or place					
14.	Ejection Medium (0) No ejection (1) Door/hatch/tailgate (2) Nonfixed roof structure (3) Fixed glazing (4) Nonfixed glazing (specify): (5) Integral structure (8) Other medium (specify): (9) Unknown	φ.	(2) Removed from vehicle due to perceived serious injuries (3) Exited vehicle with some assistance (4) Exited vehicle under own power (5) Occupant fully ejected (8) Removed from vehicle for other reasons (specify): (9) Unknown					

	BELT SYSTE	VI FUNCTION	
18.	Manual (Active) Belt System Availability (0) None available (1) Belt removed/destroyed (2) Shoulder belt (3) Lap belt (4) Lap and shoulder belt (5) Belt available—type unknown	Manual Shoulder Belt Upper Anchorage Adjustment (0) No manual shoulder belt (1) No upper anchorage adjustment for manual shoulder belt Adjustable shoulder Belt Upper Anchorage	4
	Integral Belt Partially Destroyed (6) Shoulder belt (lap belt destroyed/removed) (7) Lap belt (shoulder belt destroyed/removed) (8) Other belt (specify): (9) Unknown	 (2) In full up position (3) In mid position (4) In full down position (5) Position unknown (9) Unknown if position has adjustable upper anchorage adjustment 23. Automatic (Passive) Belt System Availability/ 	2
19.	Manual (Active) Belt System Use (00) None used, not available, or belt removed/destroyed (01) Inoperative (specify):	Function (0) Not equipped/not available (1) 2 point automatic belts (2) 3 point automatic belts (3) Automatic belts - type unknown Non-functional	
	(02) Shoulder belt (03) Lap belt (04) Lap and shoulder belt (05) Belt used—type unknown (08) Other belt used (specify):	(4) Automatic belts destroyed or rendered inoperative (9) Unknown 24. Automatic (Passive) Belt System Use (0) Not equipped/not available/destroyed or	<u>i</u>
	 (12) Shoulder belt used with child safety seat (13) Lap belt used with child safety seat (14) Lap and shoulder belt used with child safety seat (15) Belt used with child safety seat—type unknown 	rendered inoperative (1) Automatic belt in use (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): (3) Automatic belt use unknown	
20.	(18) Other belt used with child safety seat (specify): (99) Unknown if belt used Proper Use of Manual (Active) Belts (0) None used or not available	(9) Unknown 25. Automatic (Passive) Belt System Type (0) Not equipped/not available (1) Non-motorized system (2) Motorized system	1_
	 (1) Belt used properly (2) Belt used properly with child safety seat Belt Used Improperly (3) Shoulder belt worn under arm (4) Shoulder belt worn behind back or seat (5) Belt worn around more than one person (6) Lap belt worn on abdomen (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): (8) Other improper use of manual belt system (specify): (9) Unknown 	(9) Unknown 26. Proper Use of Automatic (Passive) Belt System (0) Not equipped/not available/not used (1) Automatic belt used properly (2) Automatic belt used properly with child safety seat Automatic Belt Used Improperly (3) Automatic shoulder belt worn under arm (4) Automatic shoulder belt worn behind back (5) Automatic belt worn around more than one person (6) Lap portion of automatic belt worn on abdomen (7) Automatic lap and shoulder belt or	
21.	Manual (Active) Belt Failure Modes During Accident (0) No manual belt used or not available (1) No manual belt failure(s) (2) Torn webbing (stretched webbing not included) (3) Broken buckle or latchplate (4) Upper anchorage separated (5) Other anchorage separated (specify): (6) Broken retractor (7) Combination of above (specify): (8) Other manual belt failure (specify): (9) Unknown	automatic shoulder belt used improperly with child safety seat (specify): (8) Other improper use of automatic belt system (specify): (9) Unknown 27. Automatic (Passive) Belt Failure Modes During Accident (0) Not equipped/not available/not in use (1) No automatic belt failure(s) (2) Torn webbing (stretched webbing not include (3) Broken buckle or latchplate (4) Upper anchorage separated (5) Other anchorage separated (specify): (6) Broken retractor (7) Combination of above (specify): (8) Other automatic belt failure (specify):	1
		(9) Unknown	

POLICE REPORTED RESTRAINT USE	AIR BAG SYSTEM FUNCTION
28. Police Reported Belt Use (0) None used (1) Police did not indicate belt use (2) Shoulder belt (3) Lap belt (4) Lap and shoulder belt (5) Belt used, type not specified (6) Child safety seat (7) Automatic belt (8) Other type belt, (specify):	30. Frontal Air Bag System Availability/Function (This Occupant Position) (0) Not equipped/not available (1) Air bag Non-functional (2) Air bag disconnected (specify): (3) Air bag not reinstalled (9) Unknown 31. Frontal Air Bag System Deployment (This Occupant Position) (0) Not equipped/not available
29. Police Reported Air Bag Availability/Function (0) No air bag available (1) Police did not indicate air bag availability/function (2) Deployed (3) Not deployed (4) Unknown if deployed (9) Police indicated "unknown"	 (1) Deployed during accident (as a result of impact) (2) Deployed inadvertently just prior to accident (3) Deployed, details unknown (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical) (5) Unknown if deployed (7) Nondeployed (9) Unknown 32. Other Than First Seat Frontal Air Bag
Check the Primary Source Used In Determining Belt Use. [] Vehicle inspection Official injury data [] Driver/occupant interview Other (specify):	Availability/Function (This Occupant Position) (0) Not equipped/not available (1) Air bag Non-functional (2) Air bag disconnected (specify): (3) Air bag not reinstalled (9) Unknown Specify type of "other" air bag present:
	 33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) (0) Not equipped with an "other" air bag (1) Deployed during accident (as a result of impact) (2) Deployed inadvertently just prior to accident (3) Deployed, details unknown (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical) (5) Unknown if deployed (7) Nondeployed (9) Unknown
	34. Are There Indications of Air Bag System Failure? (This Occupant Position) (0) Not equipped/not available (1) No (2) Yes (specify): (9) Unknown

FIRST SEAT FRONTAL AIR	BAG SYSTEM EVALUATION
35. Had Vehicle Been in Previous Accident(s)? (0) Not equipped/not available (1) No previous accidents Yes (2) Previous accident(s) without deployment(s) (3) One previous accident with deployment (4) More than one previous accident with at least one deployment (8) Previous accidents, unknown deployment status (9) Unknown	40. Longitudinal Component of Delta V For Air Bag Deployment Impact (_000) Not equipped/not available Code the value of the delta V for the impact that initiated the air bag deployment (_996) Deployment, unknown longitudinal Delta V (_997) Not deployed (_998) Unknown if deployed (_999) Unknown
36. Type of Air Bag (0) Not equipped/not available (1) Original manufacturer installed system (2) Retrofitted air bag (3) Replacement air bag (8) Unknown type of air bag (9) Unknown	41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? (0) Not equipped/not available (1) No (2) Yes (3) Deployed, unknown if flap(s) opened at designated tear points (7) Not deployed (8) Unknown if deployed
37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? (0) Not equipped/not available (1) No prior maintenance (2) Yes, prior maintenance (specify): (9) Unknown	(9) Unknown 42. Were Air Bag Module Cover Flap(s) Damaged? (0) Not equipped/not available (1) No (2) Yes (specify): (3) Deployed, unknown if air bag module cover flap(s) damaged (7) Not deployed
38. Air Bag Deployment Accident Event Sequence Number (00) Not equipped/not available Code the accident event sequence number that initiated the air bag deployment (96) Deployed, unknown event (97) Not deployed (98) Unknown if deployed (99) Unknown	(8) Unknown if deployed (9) Unknown 43. Was There Damage To The Air Bag? (00) Not equipped/not available (01) Not damaged Yes - Air Bag Damage (02) Ruptured (03) Cut (04) Torn
39. CDC For Air Bag Deployment Impact (0) Not equipped/not available (1) Highest delta V (2) Second highest delta V (3) Other non-coded delta V (specify): (6) Deployed, unknown event (7) Not deployed (8) Unknown if deployed (9) Unknown	(05) Holed (06) Burned (07) Abraded (88) Other damage (specify): (95) Damaged, details unknown (96) Deployed, unknown if damaged (97) Not deployed (98) Unknown if deployed (99) Unknown

	FIRST SEAT FRONTAL AIR BAG SYSTEM		HEAD RESTRAINT AND SEAT EVALUATION
44.	Source of Air Bag Damage (00) Not equipped/not available (01) Not damaged (02) Object worn by occupant, (specify): (03) Object carried by occupant, (specify): (04) Adaptive/assistive controls, (specify): (05) Fire in vehicle (06) Thermal burns (07) Rescue or emergency efforts (08) Other damage source (specify): (95) Damaged, unknown source	- - -	49. Head Restraint Type/Damage by Occupant at This Occupant Position (0) No head restraints (1) Integral—no damage (2) Integral—damaged during accident (3) Adjustable—no damage (4) Adjustable—damaged during accident (5) Add-on—no damage (6) Add-on—damaged during accident (8) Other (specify): (9) Unknown 50. Seat Type (this Occupant Position) (00) Occupant not seated or no seat
45.	(96) Deployed, unknown if damaged (97) Not deployed (98) Unknown if deployed (99) Unknown Was The Air Bag Tethered? (0) Not equipped/not available (1) No (2) Yes (specify number of tether straps):	ф.	(01) Bucket (02) Bucket with folding back (03) Bench (04) Bench with separate back cushions (05) Bench with folding back(s) (06) Split bench with separate back cushions (07) Split bench with folding back(s) (08) Pedestal (i.e., column supported) (09) Box mounted seat (i.e., van type) (10) Other seat type (specify):
46.	(3) Deployed, unknown if tethered (7) Not deployed (8) Unknown if deployed (9) Unknown Did The Air Bag Have Vent Ports? (0) Not equipped/not available (1) No (2) Yes (specify number of vent ports):	ф	(99) Unknown 51. Seat Orientation (this Occupant Position) (0) Occupant not seated or no seat (1) Forward facing seat (2) Rear facing seat (3) Side facing seat (inward) (4) Side facing seat (outward) (8) Other (specify):
47 .	(3) Deployed, unknown if vent ports present (7) Not deployed (8) Unknown if deployed (9) Unknown Was the Air Bag in this Occupant's Position Contacted by Another Occupant? (0) Not equipped/not available (1) No (2) Yes (specify):	ф	(9) Unknown 52. Seat Track Adjusted Position Prior To Impact (0) Occupant not seated or no seat (1) Non-adjustable seat track Adjustable Seat Track (2) Seat at forward most track position (3) Seat between forward most and middle track positions
48.	 (3) Deployed, unknown if other occupant conta air bag (7) Not deployed (8) Unknown if deployed (9) Unknown Was This Occupant Wearing Eye-wear? (0) Not air bag equipped/air bag not available (1) No (2) Eyeglasses/sunglasses (3) Contact lenses (4) Deployed, unknown if eyewear worn (7) Not deployed 	ect to	 (4) Seat at middle track position (5) Seat between middle and rear most track positions (6) Seat at rear most track position (9) Unknown
	(7) Not deployed(8) Unknown if deployed(9) Unknown		

53. Seat Back Incline Prior and Post Impact

99

- (00) Occupant not seated or no seat
- (01) Not adjustable

Upright prior to impact

- (11) Moved to completely rearward position
- (12) Moved to rearward midrange position
- (13) Moved to slightly rearward position
- (14) Retained pre-impact position
- (15) Moved to slightly forward position
- (16) Moved to forward midrange position
- (17) Moved to completely forward position

Slightly reclined prior to impact


- (21) Moved to completely rearward position
- (22) Moved to rearward midrange position
- (23) Retained pre-impact position
- (24) Moved to upright position
- (25) Moved to slightly forward position
- (26) Moved to forward midrange position
- (27) Moved to completely forward position


Completely reclined prior to impact


- (31) Retained pre-impact position
- (32) Moved to rearward midrange position
- (33) Moved to slightly rearward position
- (34) Moved to upright position
- (35) Moved to slightly forward position
- (36) Moved to forward midrange position
- (37) Moved to completely forward position
- (99) Unknown
- 54. Seat Performance (this Occupant Position)



- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify):____
- (4) Seat track/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion, (specify):_____
- (7) Combination of above (specify):
- (8) Other (specify):
- (9) Unknown







	CHILD S	AFET	Y SEAT
55.	Child Safety Seat Make/Model (000) No child safety seat	_ 58	3. Child Safety Seat Harness Usage
	Applicable codes are found in your NASS CDS Data Collection, Coding and Editing (950) Built-in child safety seat (997) Other make/model (specify):	59	9. Child Safety Seat Shield Usage
	(998) Unknown make/model	60). Child Safety Seat Tether Usage ϕ
	(999) Unknown if child safety seat used		Note: Options below applicable to Variables OA58-OA60.
56.	Type of Child Safety Seat (0) No child safety seat	-	(00) No child safety seat
	(1) Infant seat(2) Toddler seat(3) Convertible seat(4) Booster seat - with shield		Not Designed With Harness/Shield/Tether (01) After market harness/shield/tether added, not used (02) After market harness/shield/tether used
	 (5) Booster seat - without shield (7) Other type child safety seat (specify): (8) Unknown child safety seat type 		 (O3) Child safety seat used, but no after market harness/shield/tether added (O9) Unknown if harness/shield/tether added or used
57.	(9) Unknown if child safety seat used Child Safety Seat Orientation (00) No child safety seat	_	Designed With Harness/Shield/Tether (11) Harness/shield/tether not used (12) Harness/shield/tether used (19) Unknown if harness/shield/tether used
	Designed for Rear Facing for This Age/Weight (01) Rear facing (02) Forward facing		Unknown If Designed With Harness/Shield/Tether (21) Harness/shield/tether not used (22) Harness/shield/tether used (29) Unknown if harness/shield/tether used
	(08) Other orientation (specify): (09) Unknown orientation		(99) Unknown if child safety seat used
	Designed For Forward Facing for This Age/Weight (11) Rear facing (12) Forward facing (18) Other orientation (specify): (19) Unknown orientation Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight (21) Rear facing (22) Forward facing (28) Other orientation (specify): (29) Unknown orientation		
	(99) Unknown if child safety seat used		
		- 1	

occupant Assessment Form	rayo
INJURY CONSEQUENCES	
61. Injury Severity (Police Rating) (0) O - No injury (1) C - Possible injury (2) B - Nonincapacitating injury (3) A - Incapacitating injury (4) K - Killed (5) U - Injury, severity unknown (6) Died prior to accident (9) Unknown	63. Type Of Medical Facility (for Initial Treatment) (0) Not treated at a medical facility (1) Trauma center (2) Hospital (3) Medical clinic (4) Physician's office (5) Treatment later at medical facility (8) Other (specify): (9) Unknown
62. Treatment - Mortality (0) No treatment (1) Fatal (2) Fatal - ruled disease (specify): Nonfatal (3) Hospitalization (4) Transported and released (5) Treatment at scene - nontransported (6) Treatment later (7) Treatment - other (specify): (8) Transported to a medical facility-unknown if treated (9) Unknown	(00) Not Hospitalized Code the number of days (up through 60) that the occupant stayed in hospital.
	(99) Unknown
	SPONSE INFORMATION
(9) Unknown Air VEHIC	CLE (01) Fire department (02) Rescue squad (03) Police department (04) Trauma unit (05) Disaster unit
EMS NotificationTime (9999) Unknown L B 3 ROAD VEHICLE L B 3 AIR VEHICLE L B 3 ROAD VEHICLE L B 3 ROAD VEHICLE L B 3 ROAD VEHICLE L B 3 ROAD VEHICLE L B 3 ROAD VEHICLE L B 3 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE L B 5 ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEHICLE ROAD VEH	(07) Hospital
EMS Departure Time To Treatment Facility G G G G G G G G G G G G G	(03) Resuscitation (04) CPR (05) Emergency cardiac care

EMS Arrival Time At Treatment Facility (9999) Unknown

EMS arrived, provided

treatment, but did not

EMS arrived, but was

transport

not used

Unknown

Treatment Facility

(9997)

(9998)

(9999)

STOP WORK HERE VARIABLES 66-74 TO BE CODED BY THE ZONE CENTER

(06)

(07)

(80)

(98)

(99)

Life support system monitoring (blood pressure,

pulse rate, respiration, EKG)

Combination of above, specify: _

Emergency burn care

Other, specify: _

Unknown

TO BE CODED BY THE ZONE CENTER

4		INJURY CONSEQUENCES		TRAUMA DATA	
67. 1st Medically Reported Cause of Death 68. 2nd Medically Reported Cause of Death Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death (00) Not fatal or no additional causes (96) Mode of death given but specific injuries are not linked to cause of death. (specify): (97) Other result (includes fatal ruled disease) (specify): (99) Unknown 70. Number of Recorded Injuries for This Occupant Code the actual number of injuries recorded for this occupant. (00) No recorded injuries (97) Injured, details unknown (98) Unknown if injury data (3) Driver/occupant interview (8) Other (specify): (99) Unknown if blood given (2) Yes - blood not given (2) Yes - blood not given (2) Yes - blood given (3) Yes - blood given (4) Yes - blood not given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood given (5) Yes - blood for tyen (5) Yes - blood for given (5) Yes - blood fiven (5) Yes - blood fiven (5) Yes - blood fiven (5) Unknown if blood given (6) Not enuits: (9) Unknown if plood gases (ABG) - HCO ₃ (00) Not injured, details unknown (97) Injured, details unknown (98) Unknown if plood gases (ABG) - HCO ₃ (00) Not injured, details unknown (99) Unknown if plood gases (ABG) - HCO ₃ (00) Not injured, details unknown (97) Injured, details unknown (99) Unknown if plood gases (ABG) - HCO ₃ (00) Not injured, details unknown (97) Injured, details unknown (99) Unknown if	66.	Time to Death Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day 31, 2 days = 32, n days = 30 + n up through 30 days = 60) Not fatal Fatal - ruled disease		(at Medical Facility) (00) Not injured (01) Injured - not treated at medical facility (02) No GCS Score at medical facility (03-15) Code the actual value of the initial GCS Score recorded at medical facility. (97) Injured, details unknown	
Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death (00) Not fatal or no additional causes (96) Mode of death given but specific injuries are not linked to cause of death. (specify): (97) Other result (includes fatal ruled disease) (specify): (99) Unknown 70. Number of Recorded Injuries for This Occupant Code the actual number of injuries recorded for this occupant. (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00) No recorded injuries (00)	68.	2nd Medically Reported Cause of Death	ф ф	(1) No - blood not given(2) Yes - blood given(specify units):	_
disease) (specify): (99) Unknown 70. Number of Recorded Injuries for This Occupant Code the actual number of injuries recorded for this occupant. (00) No recorded injuries (97) Injured, details unknown BELT USE DETERMINATION 74. Primary Source of Belt Use Determination (0) Not equipped/not available/destroyed or rendered inoperative (1) Vehicle inspection (2) Official injury data (3) Driver/occupant interview (8) Other (specify): (9) Unknown if belt used		Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death (00) Not fatal or no additional causes (96) Mode of death given but specific injuries are not linked to cause of death. (specify):	7	 (00) Not injured (01) Injured, ABGs not measured or reported (02-50) Code the actual value of the HCO₃ (96) ABGs reported , HCO₃ unknown (97) Injured, details unknown 	k.
70. Number of Recorded Injuries for This Occupant Code the actual number of injuries recorded for this occupant. (00) No recorded injuries (97) Injured, details unknown 74. Primary Source of Belt Use Determination (0) Not equipped/not available/destroyed or rendered inoperative (1) Vehicle inspection (2) Official injury data (3) Driver/occupant interview (8) Other (specify): (9) Unknown if belt used				BELT USE DETERMINATION	
	70	Number of Recorded Injuries for This OccupantCode the actual number of injuries recorded for this occupant. (00) No recorded injuries (97) Injured, details unknown	ф <u>3</u>	74. Primary Source of Belt Use Determination (0) Not equipped/not available/destroyed or rendered inoperative (1) Vehicle inspection (2) Official injury data (3) Driver/occupant interview (8) Other (specify):	

General Information

DSI96AB10

Vehicle 1 Vehicle 2 Year: 1992 1993 Make: Pontiac Mercury Model: Sable Grand Am Body Style: 4S **4S** CDC: 11FDEW2 **MISSING** Right Damaged Side:

PDOF: 340° 40° Heading Angle: 90° 210°

Vehicle Information

<u>Vehicle 1</u>	<u>Vehicle 2</u>
269.9 cm	262.6 cm
488.2 cm	474.7 cm
180.8 cm	174.2 cm
1554.0 kg	1310.0 kg
228.1 cm	228.1 cm
146.5 cm	142.4 cm
71.5 sqrt(N)	63.3 sqrt(N)
9.8 sqrt(N)/cm	7.5 sqrt(N)/cm
3	3
3	3
	269.9 cm 488.2 cm 180.8 cm 1554.0 kg 228.1 cm 146.5 cm 71.5 sqrt(N) 9.8 sqrt(N)/cm

Vehicle 1: Used d0 and d1 values estimated from the vehicle size (modified for offset impact).

Vehicle 2: Used d0 and d1 values estimated from the vehicle size.

DSI96AB10

WinSMASH 1.2.1

Damage Information

	Vehicle 1	Vehicle 2
	Offset Impact	
Damage Length:	145.0 cm	ROLDMISS
Damage Offset:	0.0 cm	
Field L - D:	-14.0 cm	0.0 cm
C1:	23.6 cm	
C2:	26.1 cm	
C3:	25.2 cm	
C4:	21.9 cm	
C5:	9.0 cm	
C6:	0.0 cm	

Page 2

Summary of Results Using Damage

Vehicle 1

Speed Change

(Damage)

Total: 39.0 km/h

Longitudinal: -36.6 km/h

Latitudinal: 13.3 km/h

PDOF: 340°

Energy Dissipated: 52,119 Joules

Barrier Equivalent Speed: 27.2 km/h

Moment Arm of Principle Force: 61.0 cm (CW)

Change in Angular Velocity: 1.8 deg/seconds

Used d0 and d1 values estimated from the vehicle size (modified for offset impact).

Vehicle 2

Speed Change

(ROLDMISS)

Total: 46.2 km/h

Longitudinal: -35.4 km/h

Latitudinal: -29.7 km/h

PDOF· 40°

Energy Dissipated: 186,284 Joules

Barrier Equivalent Speed: 54.9 km/h

Moment Arm of Principle Force: 66.7 cm (CW)

Change in Angular Velocity: 2.4 deg/seconds


Used d0 and d1 values estimated from the vehicle size.

DSI96AB10

WinSMASH 1.2.1

RAF	FIC COLLISION REP	ORY					ESI AVAILABLE	7494	1 00 20 -	د
PECIAL CO	NAMES NAMES	PELONY CITY		****	3.1	1,000	A PISTING PLOCAL IN	IN M HAMBER		
	an much service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service and a service									
	M. M. M. M. M. M. M. M. M. M. M. M. M. M	HE & RUN COLUTY		REPOR	THE SHIPPET	•	AAY			
			- 	·		. BAY YEAR	Ymes (see)	100000		
	CULTIMON COCHE JED ON			andarrent.		1 196	1813	MOC.	OFFICER L	
20	mritel biguntion					MY OF WEEK	TOW AWAY	1900	ev:	
OCATION					SA	WTFS		1		
9	AT INTERNSCIPON WITH	97					STATE HAY NEL			
-	⊠on: 7117/1=17	DP					Dies (S)		[]Hora	
PARTY	DEVENT DORGE MANAGE	<u> </u>	STATE CL	AAA SAPETT			OBEL/COLOR	ED E		176
1				= G	193 6	PONTIAC	GRAND AM			
DRIVER	MAR (MART, MODEL, LAST)		1			208	المسم ا	i i	×	
							many on a fire and		وران الومها المستعدد الأمراهية الماراهية والمعالد	
ANTAL -	TYREST ADDRESS			A	Ounding Hype	į.	Special es immen	•	:	
PARKED	COTY / STATE / 200				OWNER'S ASSESS	-	The same	<u></u>		4
VEHICLE			- 1-	Action -		<u>k</u>	Sharing and the			1
<u>Q</u>	BET NUR EVED MEMORY	Thigh	PRIDORATE, VE	RACE	DE PORTION OF	ALICAL ON ONDERS	or Klome	IN TORVE	A PHOTHER	\dashv
	M BLN BLU (60)	140	7	S W						×
OTHER	HONA Priord	BUENESS PHONE			-MOR WECKWAC	А. РЕГЕСТВ:	HOME APPA		REPERTO MARASTIVE	П
		(ABACITE ABE	OHRY DESC	MOS ABIŞCYS BYNVOL		SHADE IN DAMAGED AREA	7
	CANADA	****	PARILLE CONTRACTOR	- Mari	1		MK			
		and the second second	Mare.		- T		OO. MAJOR	TOTAL.	· •	\mathbf{I}
	BUR OF CONSTRUCT OF SHAPE	55			744 D]
PARTY	STATE OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY	The same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the sa	STATE CL	and Swally	WELL VEAR	BARS / 800	DEL/COLDA	LCOM	ATS ABBOUGH BO	=
2			1 1	コエ	1921 M	ercury !	SABLE 40	R		
DAVER	HAME (PROT. MODULE LAST)			-	1	10			- ·	
Ø							UE			4
PEDER	STREET ASPRES		Mari Fa	•	Owners war	Ľ	DAME AD DRIVER	`		
PARKED	CITY / STATE / BP		Amelia	 	OTHERT ADDRESS	· K	3 SAME AS DRIVER			\dashv
America			A STATE OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PAR		_	L	3			1
MCY.	THOUSE AND MODERT	WESHT NO. 1	HENNY YEA		DISPOSE TION OF Y	ENCLE ON ORDERS	or: Klornes	· Post	- DOWNER	7
	M BRO HZ43/0	220	2			-				
DIMER	resset Protect -	Supplies Nicola			PROG MECHAGO	AL PEPBOTE:	NOME APPAR	 🔯	REFER TO HARANTY	_]
-	INSURANCE CARRIER	- Leas	Partie		Albecra A	TYPE 1	NOE VENCLE DAMAGE	·	MADE IN DAMAGES ANSA	
							04 X 1000	TOTAL /		
	ONKNOWAN	1 aprais	(AC)		ICC ()				,	
	The second second	55	i		28				ليسب	4
PARTY	DINVER'S LICENSE NUMBER		STATE CLA	M 200.20	VEH YEAR	MAKE / WO	OBL / COLOR	ncom	ATT PRODUCTS BY	T
3			$\perp X$	\mathcal{L}	1					.]
DRIVER	HAME (MIST, MIDDLE , LANY)	Married .	(T)			-A 12				1
71012	STREET ADDRESS	lie (1)	10		Devisors made		AME S DIEVER			\dashv
1700			-							
PARKED	CHY/OTATE/DP	HAVE			OWNER'S COM		AND D PRIVAR			٦
Ö	1 1	MENTON A	·							_
MCV- CLIEF	BEE HAIR E HENOHT		MONTE VE	, me	DIMONICO	THE CONTROL		DOMAR	OUNER	i
Q		ग । ।			777	THE WAY			-	H
OTHER	()	()			PROFITE TO SEC	AL SEPTEME	MONA AFAI		REPER TO NARRATIVE	4
	INDURANCE CARRIER	Pouc	NUMBER		VEIOCLS Y	775	HOL HOME [Lescon		
						10.	100. Human	TOTAL		1
i	MAL OF ON STREET DR HEGHWAY	OPE 20	bes		*** D					1
KEPARER			DISPATCE	H NOTIFED	LEMERSH HW	18		DAVE	neviewED	7
	The second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second secon		1	16	al			1	0/	1

		96		<u> </u>		<u> </u>	-	<u></u>	· X		BE	ST AV	AILABLE	
MULHER	PASSENGER	AGE	DEX			"X") אמטנאו	·	INJURED	WAS ("X"	ONE)	PARTY	BVAT	BAPTITY	
				PATAL	INJURY	OTHER VIEWELS	COMPLAINT OF PAIN	DAVER PARK	PED. MCYCU	T DTHEA	Nunga	POB,	sour,	Pito
TAME (A O.D	ADDATES	17	W			ם ע					Z Tilli Pincar	3	GAY.	2
	LY) TRANSPORT	YED 94:					TAXEN TO:				TILIPRO		The second second	
SENCHIBE IN	JURUSS		AIR								-			
		RITIC	AL	CONOIT	חסט נ	NITH TRA	OT AMU	CHEST	N QUA	ECK.				
 -				· · · · · · · · · · · · · · · · · · ·									·	
		1.5	T -		-	-		1 - 1-	1	<u></u>	ACTIM OF W	-	_	10
# 1W8 / 0.0.E	Abbass	68	100		N N						2		9/_	
MINUED ON	TRANSPORT	ED AY:			****		TAXEN TO:				-			
ESCRIPE PA	NAIRE			12	·							~		
·	 :	CU	TS	ON BA	rk on	MGAD A	M ARM	COMPLA	AINT OF	PAIN	1 12	CHE	TCZ	
0	·												· 	
					T					<u>~</u>	спи ор ио	LENT OR	ME NOTIFIE	0
AME (D.C.)	ADDRES	121	M					N D			ELEPHONE		<u>G</u>	0
TOHED ONL	TANIBROATE	EO UY:				.75	TAKEN TO:						· ·	
DOME HA	1		A				X							
	<u>6</u> A	1 24	مه	BANK	OF A	HEAD BI	ZVISES OF	U LEL A	ND CHO	37.				
						·		i i						
					-		γ	·		□ we	THE OF VIOL	EMT CNI	ME NOTIFIED	
AME / D.Q.A.	ADDATA	44	M							إما	ALE PHONE			
	TRANSPORTE	0 841		52			YAKEN TO:						A water and	
ESCRIBE WIL										A. A.		,		
			····				·							
	-					····								
-					·		2			U vic	THE OF YOU	ENT ONL	41 NOTIFIED	-
38 AME / D.O.S. /														
		IA N			· · · · · · · · · · · · · · · · · · ·						ELEPHONE			
	n Tambronte	IU = T:				·····	TAKEN TOI						,	
HOCAIDE MUI	/AIG	····			~~~~~									
										□ we	um of Mol	ENT CAI	4E NOTINES	
]"					D									
AME / D, O, D,				·			11			7	ELEPHONE			
	TRANSPORTE	ID BY:					YAKEN TO:							
IOCADE MJV	init)													
			-	-										
										□ w	ma of viol	DIT CRI	-	
M B. WINY CE	AMIL .		1	r.i	D, NUMBER	w0,	DAY YE	AR REVIEWERS NA	W.F		W.		BAY	



HALIADO	PPLEME	NIAL			BEST AVAILABLE	Page 5 OF
OF INCIDENT/OCCUP	MENCE	TIME (2400)	NCIC NUMBER	OFFICER I.D. NUMBER	NUMBER	
	96	1813				A STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STA
E	-X. ONE		TYPE SUPPLEMENTAL PATAPE	Fatal	Hit and run update	
larrative	Collision	n report	BA update		Other:	•
Supplemental	Other:		Hazardous materials	C School bus	REPORTING DISTRICT/BEAT	CITATION NUMBER
COUNTY/JUDICIAL DI	STRICT		west fall factors (- By a particular and the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second seco		
				7	STATE HICHWAY RELATED	
TIONBUDIECY		TALL STATE OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE		·	☐ Yes	Ø No
A series			may in better market with the said			•
I	FACT	75				
	A. S	CENE			8	
		ROAD	DESCRIPTION			CCENE
					AT THE	SCENE
			ACCIDENT	IS A TI	NO LANE, T	YAW OW
		OF THE			·	
		ASPHALT	ROADWAY,	RURAL		
		SLIGHT	CURVE AN		DIVIDED	<u>3 Y</u> _
					JES.	
		DOUBLE	The same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the sa			THAT
			ST. WEST	15 A	DIRT ROAD	
		0.00	ORTH FORM	NG A	T' WITH	المال المكان والمستحدد المام وعارا أواد
		RUNS N			IN T/G USE	ED AS
			TOH	A FACTOR	18 115	CX
		REFEREN				
			JCE ONLY			
		KEFEKER	SCE ONLY			
			FIC CONTRO),5 No	NE.	
				No.	NE	
				NO.	ne	
		Z. TRAF	EFIC CONTRO			
	a	Z. TRAF	EFIC CONTRO			OLAMPE)
	В	Z. TRAF	EFIC CONTRO		AND DONE BY RO	OLAMPE)
	В	Z. TRAF	EMENTS (ALL	APPROXIMATE	AND DONE BY RO	
	8	AOT	EMENTS (ALL	AMPROXIMATE	AND DONE BY RO	OKAMPE)
	В	AOT	EMENTS (ALL	AMPROXIMATE	AND DONE BY RO	SE
	В	AOT	EMENTS (ALL	AMPROXIMATE	AND DONE BY RO	SE
·	8	AOI	EMENTS (ALL VAS 218 FEE MD 7'7" NORT	AMPOXIMATE ET EAST TH OF SCL	AND DONE BY RO	OF
	В	AOI	EMENTS (ALL VAS 218 FEE MD 7'7" NORT	AMPOXIMATE ET EAST TH OF SCL	AND DONE BY RO	ÉAST
	В	AOT Y	EMENTS (ALL WAS 218 FEE ND 7'7" NORTH	AMPOXIMATE ET EAST TH OF SCL	AND DONE BY RO	OF
).	8	AOI Y	EMENTS (ALL WAS 218 FEE AND 7'7" NORT OR P-1 WA	AMPOXIMATE ET EAST TH OF SCL	AND DONE BY RO	ÉAST
).).). 1.	8	AOI Y	EMENTS (ALL WAS 218 FEE AND 7'7" NORTH	AMPROXIMATE ET EAST TH OF SCL S' RIF	AND DONE BY RO	ÉAST NORTH
).	6	AOI Y	EMENTS (ALL WAS 218 FEE AND 7'7" NORTH	AMPROXIMATE ET EAST TH OF SCL S' RIF	AND DONE BY RO	ÉAST NORTH
).). 1. 2. 3.	8	AOI Y	EMENTS (ALL WAS 218 FEE MP 7'7" NORT OR P-1 WA FECL OF SCL OF L/F TIRE	AMPROXIMATE ET EAST TH OF SCL S' R/F 226' E	AND DONE BY RO	ÉAST NORTH
).). 1. 2. 3. 4.	В	AOI Y	EMENTS (ALL WAS 218 FEE AND 7'7" NORTH	AMPROXIMATE ET EAST TH OF SCL S' R/F 226' E	AND DONE BY RO	ÉAST NORTH
3. 2. 3. 4.	8	AOI Y	EMENTS (ALL WAS 218 FEE MP 7'7" NORT OR P-1 WA FECL OF SCL OF L/F TIRE	AMPROXIMATE ET EAST TH OF SCL S' RIF 226' E 140" N.	AND DONE BY ROOF OF ECL OF AND 19'7" OF ECL OF	ÉAST NORTH
3. 3. 3. 3. 4. 25. 26.	8	AOI Y	EMENTS (ALL WAS 218 FEE MD 7'7" NORTH OR P-1 WA FELL OF SCL OF L/F TIRE MEST AND 33	AMPROXIMATE ET EAST TH OF SCL S' RIF 226' E 5' 10" N.	AND DONE BY ROOF OF ECL OF AND 19'7" OF ECL OF	ÉAST NORTH
3. 3. 9. 0. 1. 22. 23. 24.	6	AOT Y	EMENTS (ALL WAS 218 FEE MD 7'7" NORTH OR P-1 WA FELL OF SCL OF L/F TIRE L/R TIRE	AMPROXIMATE ET EAST TH OF SCL S' RIF 226' E 140" N. WAS 23	AND DONE BY ROOF OF ECL OF OF ECL OF OF SCL OF I'BE OF ECL	ÉAST NORTH
3	8	AOT Y	EMENTS (ALL WAS 218 FEE MD 7'7" NORT OR P-1 WA FECL OF L/F TIRE L/R TIRE V AND 19'9"	AMPROXIMATE TEAST TH OF SCL S' RIF 226' E 5' 10" N. WAS 23 N OF SC	AND DONE BY RO OF ECL OF TIRE 222' 11" AND 19'7" OF ECL OF OF SCL OF	ÉAST NORTH S
3. 3. 3. 3. 3. 4. 3. 4. 25. 26. 27.	8	AOT Y	EMENTS (ALL WAS 218 FEE MD 7'7" NORT OR P-1 WA FECL OF L/F TIRE L/R TIRE V AND 19'9"	AMPROXIMATE TEAST TH OF SCL S' RIF 226' E 5' 10" N. WAS 23 N OF SC	AND DONE BY RO OF ECL OF TIRE 222' 11" AND 19'7" OF ECL OF OF SCL OF	ÉAST NORTH S
3. 3. 3. 3. 3. 4. 25. 26. 27. 28. 29.		AOI V	EMENTS (ALL WAS 218 FEE MD 7'7" NORT OR P-1 WA FELL OF SCL OF L/F TIRE WEST AND 13 L/R TIRE W AND 19'9" R/R TIRE	APPROXIMATE ET EAST TH OF SCL S' RIF 226' E S'NO" N. WAS 23 N OF SC WAS 230	AND DONE BY ROOF OF ECL OF OF ECL OF OF SCL OF L'BE OF ECL OF SCL OF ECL EAST NORTH S	
3. 2. 3. 4. 2. 2. 2. 2. 2. 2. 2. 3.		AOI V	EMENTS (ALL WAS 218 FEE MD 7'7" NORT OR P-1 WA FECL OF L/F TIRE L/R TIRE V AND 19'9" R/K TIRE	AMPROXIMATE ET EAST TH OF SCL S' RIF 226' E 140" N. WAS 23 N OF SC WAS 230	AND DONE BY RO OF ECL OF TIRE 222' 11" AND 19'7" OF ECL OF OF SCL OF	ÉAST NORTH S

OF INCIDENTACCURRENCE C G -X* ONE Namative	TIME (2400)	TYPE SUPPLEMENTAL (X. APPL		NUMBER Hit and run update	
Variative Collision P	-	TYPE SUPPLEMENTAL CX. MPL			••
e -x-one Collision r Supplemental Other:	-				
iamative Collision F	report	CA modele		SIRDOU OUT NAMEDIAL	
Supplemental Other:			Fatel	Other:	
ODDIALITATION The second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second sec		Hazardous materiais	School bus	REPORTING DISTRICT/BEAT	CITATION NUMBER
DOUNTYJODICIAE DISTANCE				AEFONTING DIOTING	
				STATE HIGHWAY RELATED	
		-			No
TION SUBJECT				Yos	LJ NO
	05.45.175	CONTINUEC)		
MEASO	REMERIS				
		0 0 0	105 1 1/5	TIRE WAS	226 8"
	1	R P-Z Y		AND 7'2" 5	. OF SCL
	E, OF E	CL OF	5T W 1	714	AS 2181
	DF X				11'3"
	E OF	ECL OF	ST	X	1 9
	S. OF	SCL OF		RD.	
			221' E	OF ECL O	F
	-154-15	AND 161		CL OF	
	ST WI		RE WAS	2291 5	OF ECL
	4			211 S OF	SCL
	OF	ST W.			
	OF		20,		
				111	231 8"
	POR E	OR THE P-1	RIF TI		
		ECL OF	ST	W AND 4	1'9"
		NCL OF			
	N. OF	N C C			
<u> </u>			= .2 \(\). \(\)	BUMPER	WAS
0		=OR P-1	FRONT		ST W
0.	28011	O" E. OF		OF '	· · ·
		1' S OF	: SCL	OF THE	NIS ALLEP GENERAL
1.					
2	POR	FOR P-1	REAR	BUMPER	WAS
3.		OF EC	and the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of th		W. ANT
4.			LOF		RD.
25	5'4"	N. OF NO			
26				WERE 227	I F OF
27	GOUGE	MARKS IN		AND 9'9"	NOF
28.	ECLO	F S	TWEST	GOUGE WA	
29.	SCLO	F	an improve the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second s	GOUGE WA	2 4
	LONG				
	L UN 12				
30.	<u> </u>	DATE	EVIEWER'S NAME		DATE

NARRATIVE/SUPPLEMENTAL

E OF INCIDENTACCU					BEST AVAILABLE	Page 70F
	MENCE	TIME (2400)	NCIC NUMBER	OFFICER LO WOOR	NUMBER	
	96	1813	TYPE SUPPLEMENTAL FX. AFF	1 240(6)		
ONE	-X- ONE			Fatal	Hit and run updato	
Narrativo	Collision	n report	BA update Hazardous materials		Other:	
Supplemental	Other:		(_J Mazaroous materials		REPORTING DISTRICT/BEAT	CITATION NUMBER
ACCOUNTY JUDICIAL D	1517101			•		
ATIONSUBJECT					STATE HIGHWAY RELATED	
					Yos	□ No
	0.1.16.1	ICAL EVID	ENCE			
ــــــــــــــــــــــــــــــــــــــ						
	1. SK	CIDMARKS	: NONE			
	2. D	EBRIS	AS LI	STED_IN	MEASURE	MENTS
			2.1. 7.2.0	A NAME OF THE PERSON P	ER WAS	2N)
<u> </u>			P-I FROM	Name of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last of the last o	ALL CHAIL OF	ani O
					AY SHOULDE	
			P-1 REAR	BUMPER	WAS ON -	ME
					P-I RF WHE	EEL
L						
			MAS ON H	. SHOULVER	COP KDAVE	<u>× 1</u>

	77	STATE	MENTS.			
<u> </u>			20.07.54	E0E	TRANSPORT	ED .
·		BOTH	MRITES	- XX	W WODING	1
i <u>.</u>		TO 409	>PITAL PIC	TOK TO	MY ARRIVA	<u> </u>
		W-1	SAID HE	WAS.	WORKING_	11
)			. 1	AF 7/6	HE SA	_
		HE FIE	LO N/W	OF TIC		W
	T P	HE FIE	LO N/W	OF T/C	B LANE	_
S	P	HE FIE	LO N/W	THE W/		W
	P	HE FIE HE F/	LO N/W S FROM 3 LANE	THE W/	B LANE	W OTU
3.	P	HE FIE HE F/	LO N/W S FROM 3 LANE 5 HITI	THE WA	B LANE AW THE	W INTO WAS
)	P	HE FIE -1 CROS HE F/I VEHICLE ON THE	LO N/W S FROM 3 LANE 5 HITI WILONG	THE W/ AND S HE SA SIDE O	B LANE AW THE ID P-1 F THE R	WAS OAD
3. 3.	P 	HE FIE -1 CROS HE F/I VEHICLE ON THE	LO N/W S FROM 3 LANE 5 HITI	THE W/ AND S HE SA SIDE O	B LANE AW THE ID P-1 F THE R	WAS OAD
).).	P 	HE FIE -1 CROS HE E/I VEHICLE ON THE	LO N/W S FROM 3 LANE 5 HITI WILONG	THE W/ AND S HE SA SIDE O	B LANE AW THE ID P-1 F THE R	WAS OAD
5. 3. 9. 9.	P 	HE FIE -1 CROS HE E/I VEHICLE ON THE	LO N/W S FROM 3 LANE 5 HITI WILONG	THE W/ AND S HE SA SIDE O	B LANE AW THE ID P-1 F THE R	WAS OAD
5. 7. 9. 9. 9. 1.	P 	HE FIE -1 CROS HE E/I VEHICLE ON THE	LO N/W S FROM 3 LANE 5 HITI WILONG	THE W/ AND S HE SA SIDE O	B LANE AW THE ID P-1 F THE R	WAS OAD
5. 7. 3. 9. 9. 1. 2.	P 	HE FIE -1 CROS HE E/I VEHICLE DN THE AND WA	LO N/W S FROM 3 LANE 5 HITI WILONG	THE W/ AND S HE SA SIDE O	B LANE AW THE ID P-1 F THE R	WAS OAD
5. 3. 9. 9. 1. 2. 3.	P T	HE FIE -1 CROS HE E/I VEHICLE DN THE AND WA	LD N/W S FROM 3 LANE S HIT! WIZONG AS THE O	THE W/ AND S HE SA SIDE O	B LANE AW THE ID P-1 F THE R F THE A	WAS OAD
5. 3. 9. 9. 1. 2. 3. 4.	P T	HE FIE -1 CROS HE F/I VEHICLE AND WA OPINION A. SUM	LO N/W S FROM 3 LANE S HIT! WIZONG AS THE O	THE W/ AND S HE SA SIDE O CAUSE O CONCLU P-1 WAS	B LANE AW THE ID P-1 F THE R F THE A	WAS OAD
5. 3. 9. 9. 1. 2. 3. 4.	P T	HE FIE -1 CROS HE E/I VEHICLE DN THE AND WA	LO N/W S FROM 3 LANE S HITT WILDONG AS THE MARY:	THE W/ AND S HE SA SIDE OF CAUSE OF CONCLU P-1 WAS ROA	B LANE AW THE ID P-1 F THE R F THE A SIONIS DRIVING DIN HEAVY	WAS OAD CCIDENT
5. 7. 9. 9. 1. 2. 3. 4. 5.	P T	HE FIE -1 CROS HE F/I VEHICLE AND WA OPINION A. SUM	LO N/W FROM LANE WILONG S THE MARY: TRACTION	THE W/ AND S HE SA SIDE O CAUSE O CONCLU P-I WAS ROA AND ENT	B LANE AW THE ID P-1 F THE R F THE A SIONIS DRIVING DIN HEAVY ERED THE	WAS OAD CCIDENT W/B RAIN E/B
5	P T	HE FIE -1 CROS HE E/I VEHICLE AND WA OPINION ON ON	LO N/W FROM LANE WILONG S THE MARY: TRACTION	THE W/ AND S HE SA SIDE O CAUSE O CONCLU P-I WAS ROA AND ENT	B LANE AW THE ID P-1 F THE R F THE A SIONIS DRIVING DIN HEAVY ERED THE THENUHIT	WAS OAD CCIDENT W/B. RAIN E/B
5. 7. 9. 9. 1. 2. 3. 4. 5. 66.	P T	HE FIE -1 CROS HE E/I VEHICLE AND WA OPINION ON LOST LANE	LO N/W S FROM 3 LANE S HITT WILONG AS THE MARY: TRACTION TRACTION	THE W/ AND S HE SA SIDE O AUSE O CONCLU P-1 WAS ROA AND ENT	B LANE AW THE ID P-1 F THE R F THE A SIONIS DRIVING DIN HEAVY ERED THE THENUHIT	WAS OAD CCIDENT W/B. RAIN E/B
5	P T	HE FIE -I CROS HE F/I VEHICLE ON THE AND WI OPINION ON LOST ON ON ON ON ON ON ON ON ON O	LO N/W S FROM 3 LANE S HITT WIZONG AS THE MARY: TRACTION WHICH CA	THE W/ AND S HE SA SIDE O CAUSE O CON CLU P-I WAS ROA AND ENT HICLES	B LANE AW THE ID P-1 F THE R F THE A SIONIS DRIVING DIN HEAVY ERED THE THENUHIT	WAS OAD CCIDEN W/B RAIN E/B HEA AND
5	P T	HE FIE -1 CROS HE E/I VEHICLE AND WA OPINION ON LOST LANE	LO N/W S FROM 3 LANE S HITT WIZONG AS THE MARY: TRACTION WHICH CA	THE W/ AND S HE SA SIDE O AUSE O CONCLU P-1 WAS ROA AND ENT	B LANE AW THE ID P-1 F THE R F THE A SIONIS DRIVING DIN HEAVY ERED THE THENUHIT	WAS OAD CCIDEN W/B RAIN E/B HEA AND
5	P T	HE FIE -I CROS HE F/I VEHICLE ON THE AND WI OPINION ON LOST ON ON ON ON ON ON ON ON ON O	LO N/W S FROM 3 LANE S HITT WILONG AS THE MARY: TRACTION TRACTION WHICH CA TO GO SO	THE W/ AND S HE SA SIDE O CAUSE O CON CLU P-I WAS ROA AND ENT HICLES	B LANE AW THE ID P-1 F THE R F THE A SIONIS DRIVING DIN HEAVY ERED THE THENUHIT	WAS OAD CCIDEN W/B RAIN E/B HEA AND

RRATIVE/SUPPLEMENTAL BEST AVAILABLE NUMBER OFFICER LD. NUMBER NCIC HUMBER THIS (2400) TE OF INCIDENTACCUARENCE 1013 96 TYPE BUPPLEMENTAL (X APPLICABLE) TO ONE ONE Hit and run update - Falsi BA update Collision report evterned [Other: School bus Hazardous materials Other:] Supplemental CITATION NUMBER REPORTING DISTRICT/SEAT Y/DOUNTY/JUDICIAL DISTRICT STATE HIGHWAY RELATED CATIONSUBJECT □ No Yes CAUSE B THE CAUSE OF THE ACCIDENT WAS ASSOCIATED VIOLATION OF UNSAFE SPEED FOR CONDITIONS FACTOR RECOMMENDATIONS -NONE TY **?2**. 25. 26. 27. 28. 29. 30. DATE

Use previous editions until depleted.

DATE

REVIEWER'S NAME

31. PREPARED'S NAME AND LD NUMBER

Because of the fatality, the retention on this report is now "0" and the stat code is changed to "470".

Due to the death of P-2 Passenger the facts of the case will be presented to County District Attorney for consideration of a charge of Vehicular Manslaughter against P-1

32 33 34

35

27

28 29


30

31

96

	7	ASSIST ONLY	L OF .	ه	ATE		12	و جريد لڪ	TA S		PROP	.vez L	- D/8		ليا	ليبا	با
		INCIDENT LOC.	MAER		STREET NAME	170				<u>F</u>	1	<u>.</u>					EMT
į	5	TEMMENT OF CONT P		A COM	THEE! NAME		ER AS	OENT .	APT &	OULA C		CENT I	TEA	1	A = 1	CERT I	
	,					_	en Arek	5 pg	T, _			SIMA				EN.	17
1		NAME First	the the second	T. F.		SEO NO							218		ALS:	- 44	e/HEL
1		ADDRESS	(.ac)	7				٠.			-	PROV.	CIF		CLE	- C	IF
Î		AGE 7 DOB	. 18	A San	City		~~.	State	Zip		- 1	JNIT .					i
I N		OF ALL ALLA ON ALL AFRA IN		•			TEL		Go			HSP.	183	8/1	83	3 115	138
Č		Danies'		. □ ETOH	Mid i M Fami	'od. 1566 Ílv Violena	evere Se/Na	Approx	Inquiry Re	_Kg (×.	VRRVL		31	2146		SE
			Lucto		ucto	_		tont ensec			_	EFT	r r	7.	<u> </u>		e :
		ramate	Full	arr				In-A			+	T HOS.		100		1	
	I	Good chest	0	218				k Mas		<u>ح</u>	-+	VAIL	011	+		LM	5
O	ľ	CPR STORTED	200	Mesay		U		e mus	<u> </u>	Spi	ساها	HANSPO	17 7	717	7/1		
A.	İ	MASO	ALTUR	- 7		PE	<u> </u>	tocos-	1 Dorted	<u>u</u>	_ار	Amo		Fire	nogen	D PY	di. t. Ven
N	r	DEF Duty P.F.	74 · · · · ·			OFTO	arro	10000-	160 24	NEW TENT		LAMB & EC. HOS	Medic 🗌	Police	(10		
S	ŀ	and the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second s		Scen		Flag 1 de Same	114. E.	- (A)	20 mil	H-160		Most A		EDAP	T (ny) ⊒ Req :	by of
		Mouth to Man		MINS	prio		E	DIATE	ival	TBC] Trauma] PCCC		PeriNa Divers	atai [3 Othe	ا معم
	H	Jo Obvious Trau	ima -	FF BO	Matin	e.C.D	ex	posure (vanitu	<u>(2)</u>	ַבְּ	NCONTRO	OLLABLE I	NFIEL	D		 -
-	Ľ,	Frank Eying	Rook in	PUSY						Ī		Airway		Other	AIGIRC	Arest	
Н Х	k	Unavailable Diabetes Ho Sig. Hist. Heart Dis	Pos Pre	egnancy	Mo.			HYperten	sion			ONTACT	Ĩ		Ī		
	Ì		BEHaviors			Seizu gn Body (Other" Head	Pain			DB stetric					
c			Cardiac Ai		Ext. Bloc	eding		☐ Loca	Neuro S				a ☐ New	mod	☐ SE		reath
0 2	9	(Suspected)	Chest Pair DYsmy/Pr						ea/Vomiti			DD/POiso	ning		☐ \$Y	ncope	
ρ	ì	Apnea Episode	FEver			Sepleed			Drowning /Back Pai			Respirato OTher	ry Arrest		☐ We	ak/Dizz	ιλ
A	ł,	No Accessed in	72.24] BUMES	hock			inc. Veh &	Seat Bell	ZA	_	- Acts		WO IL X	50		
7	F	DOMENTE CO	Heed	٥٥	Abdomen	- Z		Pass. Sp		on		∷L) Wi Diosw	th Bluck in	2	Ja 15 Bearc	F) 0	MOI
S		Red Chest DD	Facial/Dent		Diffuse	Tend 1	E] EJected	rom Vehic	de		∴ 🔲 YR		Ö	dezmat	encox Exposu	en.
	^	ESTREET CO	Neck J		Genital/But Extremitie			☐ EXINCATIO Ped/Bike vs.	n Require	d		Д STab	original original	÷⊡⊤	Dome	Bun	•
	7	Apest	Bec Mac	Zav 🔻 :	☐ FRact	res N		fotorcycle/k	Roped		3.1	3. L b	dictional		Mork Re	hated	
L .1			Back Oriente		Amoute			Vx.Veh.				OThe	Care now.	. B	Mino	m	
₽ H Y		1 D == 1444 (MA) (Disorie	nted	PEF			Li Normai Tidal Volum	☐ Clea		□N		Appoi			ı	
S	7		□ NorMai	for pt.	P Ping		A	Wheeze:	5	· - 🗆	Raiss	Ś	☐ Jaund	beoit	p. Neill	•	
C	ξ	N Responds to Pain	C Eye _ C Motor	' \	E Fixe			R H onchi Une qual		_	☐ Ba	siLar	2 Cyan	otic			
A	Ų	N Non-Purposefully	8		1	: .	7	P) ~~~	9		Strick		Pale	•		old Diaphor	ÁS:A
- V	4	No Response		OPENING		Y	C'	PK.	ssent		QVL		Other			reprior	BUC
i.	•		B/P 740		155 OF	MOSA		EK		-	WE	DEPAR FORUG	DOSE			COUTE	11N
A	7			1	}		ORU	FIND	1	B	58				2		
	_	11210131 010	1 1		0 5/	2 1	GS	STI	111	119	00	- NSX	2 of	en i	2	NV	Ŧ
25	1	1903 130	18			71	1	1 5			1	1				1	
0		EKG TIME	PERB	DOSE	TM# R	OUTE THE	T 5	1									
έ	T	TEN 1901	OFFAI	IMS	2		Ĝ	5 1							\rightarrow		× .
	_	(Indicate Team Member # in		1 1		24		B/V/M		L -				+			
	Ē	Attempt #1 #2	#3		Voro Airwa		8 1	1	Y.M. #.	于一		SHock P		MS	D DR	-	
ļ L	7	Were Cords Visualized?	Y DN	Esop	hageal Ain	way		Mouth to A	fouth .	X		Anti-Sho		SE	□ SPI		
d in it	U	☐ \$\$ after ET/EOA☐ Patient Resisted Intubati	on (Blows/Thr			THoracost Witnessed	omy "			Vagai Ma	eneuvers	MUSCULO.	☐ Tra		plint
A P	A	☐ Vomitus/Secretions in Ai ☐ Solid Foreign Body in Ai	rway	SUCT	Removal			PR: 🖵 Citiz	zen 💢 M			CHemstr	ip	- 01	Spi Imn	nal Nobiliza	ition
¥	I	Blood in Airway	Tube S		Restoration	on of Puls		ChildBirt	h to CPI	Rofuse	<u>s: </u>	Treatme	n	Ransp			
	20	☐ Anatomical Abnormality Success? ☐ Y ☐ N	Size		No Treatm			REstrain	ts*	-	_		إلماس	riel iop	~ (
	Ī			<u>بل</u> ے ہا	DNR	PRC	OVID	OTher_				swed by:	on Maquired in	Comment	Section or	m soace pr	Ī.
						1.11	~ * 1W	- T									

COUNTY MEDICAL REPORT - FUNEINOIS SOIEINGE	J_141_11	
Date	APPROXI- MATE INTERVAL BETWEEN ONSET AND DEATH	
(A) Multiple Injuried DUE TO, OR AS A CONSEQUENCE OF (B) Blust Fore Tauma DUE TO, OR AS A CONSEQUENCE OF	Jayo	REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST Description REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION REQUEST DESCRIPTION
DUE TO, OR AS A CONSEQUENCE OF (D)		☐ Criminalistics
Other conditions contributing but not related to the immediate cause of death:		☐ HISTOPATH CUT: ☐ AUTOPSY ☐ LAB☐ MICROBIOLOGY: ☐ NEUROPATHOLOGY
If other than natural causes HOW DID INJURY OCCUR? WAS OPERATION PERFORMED FOR ANY CONDITION STATED ABOVE? TYPE SURGERY ORGAN PROCUREMENT PERTINENT COMMENTS: DEVIDENCE RECOVERED AT AUTOPSY Item Description:	90	TOXICOLOGICAL SPECIMENS COLLECTED YES, by BLOOD: HEART BILE BRAIN LIVER SPLEEN URINE KIDNEY STOMACH VITREOUS CONTENTS NO BLOOD EMBALMED > 24 HR. IN HOSPITAL NOT INDICATED OTHER REASON TOXICOLOGICAL ANALYSES ORDERED SCREEN: C H T S ALCOHOL ONLY CARBON MONOXIDE NO TOXICOLOGY REQUESTED OTHER (SPECIFY DRUG AND TISSUE)
RESIDENT , M.C. YMEDICAL EXAMINER DEATH CERTIFICATE ISSUED	, M.D.	STORAGE JARS (No) Typing Blood Taken by HEART OTHER PRIOR EXAMINATION REVIEW BY DME BODY TAG MED. RECORD CLOTHING AT SCENE PHOTO (NO) SPECIAL X-RAY (NO) PROCESSING TAG FLUORO
DATE ISSUED ISSUED BY		WHITE - FILE COPY CANARY - FORENSIC LAB COPY
PENDING DATE ISSUED ISSUED BY		PINK - INVESTIGATION COPY GOLDENROD - MEDICAL EXAMINER COPY



51

EXAMINATION PROTOCOL

FOLLOW FORM EXACTLY AS PRINTED CIRCLE OR CHECK ONE OR THOSE THAT APPLY REMEMBER THE FORM IS PRINTED ON BOTH SIDES



page 1 of 2
The body is identified by toe tags. Diagram(s) & form(s) used
The body is identified by our object.
The body
The clothing can be described as
Rigor has presumably been <u>altered abolished</u> as has livor. Rigor mortis is present. Divor mortis is
Appears: Asian Black Caucasian Hispanic Indian
Sex: Male Female. Appears the stated age of: years
The body weighs approximately Cachectic. mildly/moderately/extremely obese. poorly nourished. Thin.
approx
Embalmed:NoYes Decomposed Mutilated
Irides: Blue BrownGrey Hazel
Sclera:Normal Icteric Congested with/without Petechial Hemorrhage
Conjunctival Petechial Hemorrhage:NoYes
Head Hair: Black Blond Brown Gray Red White
Long ShortCurly Straight Tightly Curled Wavy
Balding is: Absent Present Located: temple/frontal/occipital
Mustache: Absent Present Beard: Absent Present
Teeth: Absent Present Comment:
Dentures:Absent Present Comment:
Scars:None Present Comment:
(includes needle track scars)

Tattoos: Absent Present Comment:
Deformities:Absent Present Comment:
There is no deformity or abnormal mobility of the extremities except for
The oral and nasal passages are unobstructed/ebstructed by
Resuscitative marks are are present over the precordium. The chest has no are
mildy increased anterior-posterior diameter.
The abdomen is distended. Oflat. Inot unusual. Opese. Oscaphoid. The genitalia are those of an adult male.
Examination of the back & buttocks reveals
Examination of the skin reveals
IF A TRAUMA CASE STATE: Injury date: Hospital Date(s):
TRAUMA COMMENTS: Ryly - Form 18-
TRAUMA COMMENTS: Rylu- Form 17- HMCY! Encyclosof - Alus To Chansoculos Traum - (Man Pan
Photographs
X-Rays
GSR
Indicate other form number(s) attached
OPINION (please print) Delath is attached to
Maure Head thy cy and Chul Trawn (pulmer Chul Trawn)
of A Tours of wilmen
On the Coop
(m) w / · · ·
DEPUTY MEDICAL EXAMINER Date
DELOIT UNDITUM DUVITHER

*		1 960			/ \	\ C.	ASE RE	PORT		1996		BEST AVAILAB R <mark>tment of c</mark>	
	-		APPARENT MO	DE						1000	DEPA	CASE NO.	OHONE
1 .	4.	•	STATE HOSE					CLOSELY WATC		MESTIC VIOLENCE			
1							NT RELATED			NG RELATED		4€	b
I			SPECIAL CIRCL	JMSTANCES	* TA T	Vehicle	/Vehicle(Passenge	r)			CRYPT	·,
l	-				* No (Charges		-				```e'	
LAST, FIR	ST MIC	DLE	<u> </u>			AKA:					□ JOHN		
1											☐ JANE		
ADDRESS											UND #		
ADDRESS	•						CITY				len'	STATE Z	IP
SEX	107	CE PEARS	DOB TOTAL	AGE	T'HGT "	WGT	EYES	HAIR	TEETH	IPVIEW	CONDITION	☐ EMBALI	450
M	AP	C	89	7	54	57	Blue	Blond	Own	YES NO	Fair	U EMBALI	MED
BEARD D Y OX		CARS (DI	ESCRIBE)	MARK	S	TATTO	OS (DESCRIBE)	AMP	UTATIONS	PIERCIN	lGS	DEFORMIT	IES
MUSTACI	HE												
UNSHAV	EN				None	noted				Θ.			
- X	<u>~ 1</u>	C market and a second										· · · · · · · · · · · · · · · · · · ·	
Ì													
S													
ID BY:	VISITÀ	/SEE BE	LOW) LAPD	DOINTS C	DOJ PRIN	170			-				•
- E	FAMIL'	L (SEE BE Y @ HOSP	TAL LASD	PRINTS	CAL ID PE	RINTS					•		
LA#	00.0		MAIN#	niivis		CII #		FBI #		MILITARY #		PO)B
								,				, ,	,,,
NAME (PRI	NT)				SIGNATU	IRE		RE	LATIONSHIP	PHO	ONE	DATE	TIME
					x								
PLACE OF	DEATH	PLACE FO	DUND		I HAVE PE		EEN THE DECEAS S OR LOCATION	ED OR A PHOTO	GRAPH AND C	ONFIRM THE IDENT			
				. a		A DO A LOS	on coon lor			CITY		ZIP	
													. 1
PLACE OF I				1	ORK DAT	96 L	OCATION OR AD	DRESS				ZIP	
• Veh	icle	RF	passenger		YES 18				21-11-		- It was	Mary Mary	3
600	FN	D TIM	E	FOUNDAY	NO 1 11M	E -	-					The stand	
	ç		1000	PRON BY	\	are bestalling.	· ·	alogically and	*	4		1.0	
OTHER AGE	NCY &	INV. OFFI	CER			PHONE			REPORT NO	D	NOTIFIED BY		NON
TD441077					PH				•				
TRANSPOR	IED BY	:	dilik dikelendika kana ana						TO: FSC AVRO	X	DATE	TIME .	
			- Andrea - Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of the Company of	and the second second second second	- 7 and	and the second of the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second s	and the second second second second	more and the second	SCVRC			96-@ 12	10
DOINTO .	YES		CI 071 1110		YES NO		RPT YES X						
PRINTS MED. EV.		XI XI	CLOTHING INVEST. PHO	OTO #	Ö Ö		C SEAL PA SE	NOT SEALI	ED MORTU	ARY	····		W-515
PHYS. EV.		OX.	EVIDENCE L		אם ם۔ אם ם		ND: VE0 □	NO 1971		HOSP. RPT.	YES 💆 NO		
SUICIDE		CX.		/-	_ •		10	ио 🔀		HOSP. CHART			- 1
NOTE			GSR NO	N/A		RCF	PT. NO	W. (1980)		PF NO			
Rid	ing	as th	ne right i	front p	assen	ger in a	a car dri	ven by h	is gran	dfather wh	en thev	collide	d
head	d on	with	another	vehicl	e at a	an esti	mated 60+	mph. De	cedents	seatbelt/	shoulde	r harnas	s I
in p	plac	e, ai	.rbag dep.	loyed.	Recove	ered fro	om the ba	ck seat.	Bystan	der CPR fo	r 15 mi	nutes be	-
feri	e pa ∽~	ramed	lics at so	cene. N	o vita	als for	rescue.	Taken to				trans	-
			death. De	ay idte: ecedent	event	juries (aescribec	as pulm	onary c	ontusions,	anoxic	encepha	10-
mult	., :ipl	e don	ations	-ccaeiic	CACIIC	-darry :	3 accumed	. Seen a	c ule	WICHOUT	crauma	showing	
			SOURCES:	1)		E	1 2)Hospi	tal PF	3) DATE			I	
,					FSC in	vestiga			DATE	96 1		PATE , ,	
									1		0,07752	• / /	1

DATE:

96

CARDIOPULMONARY RESUSCITATION, TRAUMATIC AND FULL ARREST NOTE

HISTORY OF PRESENT ILLNESS: is a 7-year-old patient who comes to the Emergency Room via paramedics and air squad in traumatic full arrest. He was involved in a motor vehicle accident at approximately 1830 hours. Apparently, a high speed, head on collision. Both cars were in the 50 to 60 miles per hour range. Paramedics arrived with no blood pressure or pulse with air bag and seat belt injuries to the chest and abdomen. They started mask suit airway control with an oral airway and hyperventilated and also started IV full fluids. He was given epinephrine 1 mg times two. The patient converted to a sinus tachycardia with a palpable blood pressure. But this only lasted for approximately 15 minutes and then on arrival to the Emergency Department, he was in full cardiac arrest.

There is no other past medical history available at this time, but later the father gave no history that there is underlying medical problems.

PHYSICAL EXAMINATION: GENERAL APPEARANCE: On arrival in the Emergency Room the patient has basically trauma to the upper chest and right clavicle as well as a slightly distended abdomen. LUNGS: Lung sounds though with the ambu bag are clear bilaterally. HEART: Heart sounds are not present due to the patient's flat line on cardiac monitor. EXTREMITIES: The patient's extremities were in the ambu bag initially and were not examined. The patient was in the mask suit initially. The paramedics though described that they had no obvious trauma to these extremities prior to the mass suit.

COURSE IN THE EMERGENCY ROOM: The patient was attached to the cardiac monitor and was in flat line. He was immediately continued on external cardiopulmonary resuscitation which was in progress on arrival and was immediately intubated with a #6 tube without complications. There was a lot of vomitus in the airway and there was a potential aspiration.

Page 1 of 3

EMERGENCY ROOM

The patient had bilateral IV's already established and was given additional epimephrine, Atropine and Bicarbonate. He slowly returned with a sinus rhythm which showed quite a bit of ectopy and nasogastric tube also was put down almost simultaneously.

The ectopy immediately stopped and remained in sinus tachycardia and his blood pressure initially was momentarily up to the 160 range but then quickly dropped back down to 90 and that is where it seemed to stabilize after approximately a liter and a half of fluid.

Initially, we called the Trauma Team.

pediatrics. But by the time that these people called back and actually

was in the Emergency Department, the patient's father came and told us he was a patient. At that time,

recommended calling a doctor.

and were called. They immediately returned the call and they would be available to follow up.

The CBC came back with a hemoglobin of 13, hematocrit of 40, and white blood cell count of 10,000. Initial blood gases after intubation showed the pH of 7.04, PCO2 48, PO2 22, indicating marked lactic acidosis with adequate oxygenation. The electrolytes showed a slightly low bicarbonate at 17, glucose was 308, BUN 13, creatinine 0.6.

The patient continued on fluids and was able to be stable enough to go for a CT scan of the chest and abdomen. The CT scan was only up for a short time because of the electrical storm that was available and we had very limited time for the CT scan. The patient's CT scan of the great vessels and cardiac silhouette all appeared good. There was no evidence of cardiac tamponade. The patient had some excess fluid in the abdomen but the spleen and liver, pancreas and kidneys all appeared to be intact.

at the time of dictation, was here evaluating the patient as well as

The patient remained and started to drop his blood pressure at this time and as soon as the father's CT scan of the abdomen and chest was done, a CT scan of the child's head will be done.

Page 2 of 3

EMERGENCY ROOM

ELECTROCARDIOGRAM INTERPRETATION:

FINDINGS: Electrocardiogram was done and this showed premature ventricular contractions with sinus tachycardia but no ischemic changes.

PLAN: The patient will be admitted to Intensive Care Unit under the care of with _____as pediatric consultation.

ADMISSION DIAGNOSIS:

- 1. Status post traumatic full arrest.
- 2. Cardiac contusion.
- 3. Cardiac arrhythmias with ventricular fibrillation in the field.
- 4. Fixed and dilated pupils more than likely related to cardiac arrest.

M

D: 96 T: 96 JOB #:

Page 3 of 3

DATE OF ADMISSION:

96

DATE OF TRANSFER:

96

FINAL DIAGNOSIS:

CHIEF COMPLAINT:

Cardiopulmonary full arrest, auto-

versus-auto.

HISTORY OF

PRESENT ILLNESS:

was a previously healthy 71/2-year-old white male who was a passenger in his grandfather's
automobile while they were traveling on the highway, traveling
approximately 55-65 mph. They were involved in a head-on
collision.

was wearing a seat belt and the air bag
deployed his chest.

The child was found in full arrest and was given cardiopulmonary resuscitation for approximately 15 minutes out in the field by an off-duty paramedic. The paramedic continued CPR until the paramedics arrived and then continued CPR en route to Hospital. The child arrived at the emergency room nonresponsive, pupils fixed and dilated. The child was immediately intubated with a 6.0 endotracheal tube and given epinephrine times one and bicarbonate was given. The child was also to be given atropine and did convert into a sinus rhythm.

LABORATORY DATA: Hemoglobin 13, hematocrit 40, white count 10 with normal platelets. The electrolytes were normal with an elevated glucose of 300. Urinalysis was positive for 3+ blood.

Neurologic:

The patient has been unresponsive, pupils fixed and dilated. The head CT scan with leftover contrast from the abdominal CT revealed no midline shift, no evidence of dilated ventricles, cerebral edema or evidence of mid brain herniation.

The patient was given Mannitol 0.25 gm/kg times one, Decadron 1 mg/kg/dose and from neurology was consulted. No seizure activity or posturing was noted.

Respiratory:

Page 1 of 3

TRANSFERRED

The patient_was_intubated with an endotracheal tube of 6.0, cuffed with a 50 cc air lead. Tidal volume 250 cc. The I-time 1.3, respiratory rate 60, PEEP 3. The oxygen saturation is in the mid 70's to low 80's on 100% oxygen.

The last gas was pH 7.27, pCO2 30, pO2 must have been a mixed venous because the pO2 was 48. The oxygen saturation was 78%. Will continue to monitor respiratory status.

<u>Cardiovascular:</u>

No heart rate on admission. The pulse has been 100-160. Blood pressure initially 80-90/50, dipping down to 40/30. Dopamine drip started. It has been hovering at 8 0-85/50. Also received normal saline bolus of 100 cc times two. A dopamine drip was started at 5 mcg/kg/min which has been bumped up to 15 mcg/kg/min. Dobutana salve 6 5mcg/kg/min a will 1 1 + 75 mcg/g/m is

The cardiovascular condition is continually being monitored. Will add dobutamine if necessary.

<u>Gastrointestinal:</u>

Abdominal CT was negative. There was no evidence of liver, spleen or gross kidney trauma. There is blood in the urine. The patient has an nitroglycerin to intermittent suction with small amounts of coffee ground emesis. The patient is NPO.

prom surgery evaluated the patient and there was no evidence of a surgical abdomen. There is an ileus secondary to the trauma. Continue the management as directed. Would consider putting the patient on Zantac Cimetidine and (H2 blockers)

Renal:

The patient had a Foley catheter with good urinary output which responded to about an 80-100 cc urine output after the Mannitol.

<u>Hematologic:</u>

The patient appears to be stable. Hemoglobin of 13% on admission is now 11%. No evidence of active bleeding. Will repeat another hematocrit and arterial blood gases. Consider PT, PTT.

Page 2 of 3

TRANSFERRED

Infectious Disease:

The patient is hypothermic at 91-92°F. Has been placed on blankets and some external thermal measures. Also was given Rocephin 1 gm intravenously.

IMPRESSION

AND PLAN: This is a previously healthy 7-1/2-year-old male who suffered most likely severe brain anoxia who is now unresponsive. The pupils are fixed and dilated. Head CT scan is negative as noted.

The family is aware of his grave condition and have agreed to transport the patient to the pediatric intensive care unit at the so that he can undergo further studies to document whether there is brain activity on the electroencephalogram and have pediatric neurology evaluation.

PD:	
D:	96
T: /	96
JOB #	:1

CC:

Page 3 of 3

TRANSFERRED

Date of Consultation:

96

CONSULTANT:

REQUESTED BY:

REASON FOR

CONSULTATION: I was asked to see this patient in consultation by the emergency room doctor and also by the , and I responded as soon as I could. I finished my surgery upstairs and then came down and evaluated the patient in the emergency room. There is only minimal history available, but I understand that the patient was involved as a passenger in a car involved in a head on collision with each car going approximately 55-60 miles an hour. The patient was apparently wearing a seat belt and the air bag did inflate.

There was someone near the scene of the accident. I have been told that this was an off duty paramedic or fireman who gave the patient approximately eight minutes of mouth-to-mouth resuscitation and then the paramedics arrived and the patient apparently had suffered a full arrest in the field. The patient had fixed and dilated pupils and had repeated ventricular fibrillation. The patient, eventually was brought to the emergency room where he was evaluated by

The patient was noted to be fixed and dilated on physical examination and he was immediately intubated because he was quite hypoxic and also had evidence of a low pH of 7.0.

The patient was also noted to have been vomiting just prior to coming in and there was vomit and emesis present in the mouth and this was cleared. The patient never had good vital signs. Initially his blood pressure was approximately 50 and when I saw the patient the blood pressure was 64/30. The patient has never responded to any stimuli and the pupils have been fixed and dilated ever since his admission here. I understand that the patient immediately went to CAT scan department after he was felt to be as stable as he could be. CAT scan of the chest showed no contusions, but no evidence of any hemopneumothorax. The heart was not showing any evidence of any contusion or any pericardial tamponade. There were infiltrates in both lung fields. The CAT scan of the abdomen showed some fluid and dilated loops of small

Page 1 of 3

intestine, but there was no evidence of gross free air and there was no evidence of any rupture of his spleen or liver. We understand that his grandfather was also involved in the accident and he is a patient here in the hospital as well. The child was examined.

PHYSICAL

EXAMINATION: The child was lying in a flat position or supine position. He is intubated. Head: There is no evidence of head trauma. There is a large amount of vomitus around the mouth still. Pupils are completely fixed and dilated and I myself do not see any gross of papilledema. Nose: Septum is in the midline. The ears are clear. Neck: Supported by means of a collar. C-spine precautions were taken, but I understand that there was no evidence of fractures. Chest is symmetrical. He has decreased air entry and he has some crackles in both lung field. There is no evidence of any subcutaneous air. Heart rate is actually fairly slow at the present time being in the 60s to 64. Shows no evidence of trauma with multiple abrasions or contusions primarily over the right lower quadrant. His abdomen is distended of course. The child was unable to respond. There is no guarding, no rebound or rigidity. Bowel sounds are absent. Genitalia: Normal male. The testicles are in the scrotum. A Foley catheter is draining urine which is grossly clear. Rectal: Examination is non-localizing. Extremities: The lower. extremities are in a MAST suit, but he does have some perfusion. Neurologic: The patient is totally comatose. There is no response to pain or painful stimuli whatsoever. He does not move any extremities.

IMPRESSION:

- 1. Multiple trauma.
- 2. Severe anoxic event to the brain.
- 3. Possible herniation of brain stem.
- 4. Bilateral pulmonary contusions and probable bilateral aspiration pneumonia.
- 5. Possible intra-abdominal injury, but no evidence of any fracture of spleen or liver.

DISCUSSION: I would recommend an immediate neurosurgical or neurological consult on this patient to evaluate the brain status. The patient, in fact, may have evidence of brain death. In my opinion there is no need for an emergency abdominal exploration because there is no evidence of any serious bleeding

Page 2 of 3

and no evidence of any free air or any grossly traumatized intestine. Also the patient does not need any chest tubes, that part needs to be treated medically. I will stay around and will follow the patient with you and I will certainly make recommendations after evaluation and discussion with neurologist.

Thank you for asking me to see this patient in consultation.

GB:

D: 96 T: 96

JOB #:

cc:

Page 3 of 3

DATE OF ADMISSION:

96

DATE OF DISCHARGE/DEATH:

96

PRINCIPAL DIAGNOSIS: Status post motor vehicle accident.

SECONDARY DIAGNOSIS: Brain death.

COMPLICATIONS: Expiration.

PRINCIPAL PROCEDURE: Ventilatory support.

SECONDARY PROCEDURES:

- 1. Femoral arterial cannulation.
- 2. Femoral venous cannulation.
- 3. Internal jugular cannulation.
- 4. EEG.
- 5. Intravenous fluids.
- 6. Cardiorespiratory support.

CONDITION ON DISCHARGE: Expiration.

The patient was a 7-year-old male who was status post motor vehicle accident and was transferred to from

The patient was traveling in an automobile with his grandfather in the passenger seat and restrained when he was struck by a head-on collision at approximately 6:30 p.m. on 96. On arrival, EMS noted the patient was in the back seat and in full arrest. CPR was performed for 15 minutes. The patient was transferred to

In the ER, the patient was intubated, CPR was initiated. The patient received epinephrine, bicarbonate, atropine. Initial pH was 7.01, initial hemoglobin and hematocrit were 13 and 44. A head CT, C-spine and abdominal CT scans were all negative. Chest x-ray did note a right pulmonary contusion in the upper lobe that progressed to diffuse infiltrates throughout on follow-up films. Urinalysis showed 3- blood. The patient was noted to have good urine output. The patient had a Glasgow Coma Scale of 3. His pupils were fixed and dilated. He was started on mannitol, Decadron, Rocephin x 1, dopamine at 10 mcg/kg/min was initiated. During transport, the dopamine was increased to 20 mcg/kg/min to maintain blood pressure. The patient was also started on dobutamine during transport.

Page 1 of 3

His current medications on arrival were Rocephin, Decadron, mannitol, dopamine and dobutamine. He was noted to have no known drug allergies. He had no complications during pregnancy or delivery. Normal birth weight and normal development. His immunizations were noted to be up to date. His past history was significant for a history of wheezing episcdes x 3. He also was noted to have a head injury at 5 years of age. No other significant past medical history was noted.

On arrival, patient's vital signs were a blood pressure 101/35, pulse 170, temperature 34, respiratory rate of 30, and a weight of 25 kg. The patient was intubated and unconscious. His pupils were fixed and dilated at 6 mm bilaterally. His breath sounds were equal bilaterally. There were rales over bilateral fields. There was noted to be contusions in the seat belt position over his chest. His abdomen was soft, nondistended. There were no bowel sounds noted and no hepatosplenomegaly. Neuromuscular exam was difficult to examine due to paralysis. His extremities were noted to be cold. There were decreased peripheral pulses bilaterally. There was no movement to pain stimulation and no spontaneous movements.

Upon arrival, femoral arterial and femoral venous lines were started as well as an internal jugurar line. The patient was maintained on dopamine and dobutamine, and an epinephrine drip was initiated. The patient was adjusted for adequate ventilatory support, and cardiac support. A repeat head CT was performed which showed blood in bilateral lateral ventricles, in the subarachnoid space and in the subdural space. There was also marked cerebral edema with effacement of the suprasellar cistern and fourth ventricles. There was also multiple small cerebral parenchymal hemorrhages.

On 96, a ventriculostomy drain was placed by Neurosurgery. The patient's hospital course by systems was as follows:

PROBLEM \$1: SUPPORT: Upon admission, the patient received several IV boluses due to decreased peripheral pulses and decreased blood pressure which subsequently stabilized his blood pressure. Throughout his hospital course, he was noted to have increasing urine output which was actually inappropriate and was thought for a period of time to have diabetes insipidus. He was started on DDAVP. His urine output normalized, and the DDAVP was discontinued. His electrolytes were maintained with the appropriate boluses.

Page 2 of 3

PROBLEM #2: CARDIOVASCULAR: The patient was initially started on dopamine, dobutamine, and epinephrine drips. All three drips were blowly weaned until patient maintained blood pressure on his own.

PROBLEM #3: RESPIRATORY: The patient was transferred to intubated and required minimum ventilatory support to maintain oxygen saturations, was stable on minimal ventilatory setting throughout his hospital course.

PROBLEM #4: NEUROLOGY: Due to initial cerebral edema and ventricular hemorrhage as well as hydrocephalus, a ventriculostomy drain was placed 96, also, the ventriculostomy drain was noted to fail secondary to blood clots. A revision was attempted but was unsuccessful. In addition, the patient's neurological exam remained to show very minimal neurological activity from the beginning. The pupils were fixed and dilated. The patient never had any withdrawal to pain, 96, an EEG was never showed any spontaneous movements. On performed which showed no brain activity. In addition, a nuclear medicine cerebral scan showed no blood flow which was consistent with At this time, parents requested second opinion from prior to discontinuing life support. The parents brain death. and Social Work were consulted at this time, and after further consultation with several neurologists, the parents agreed to 96, the parents discontinue life support due to brain death. On was contacted. did agree to organ donation, and

On 96, care was taken by and patient was declared dead on 96.

D: 96 T: 96



Page 3 of 3

CC:

DATE OF CONSULTATION:

TYPE OF CONSULTATION: Inpatient Neurology Consultation

REASON FOR CONSULTATION: The patient is status post MVA and nonresponsive, to evaluate for brain death.

The patient is a seven-year-old white male with no significant past medical history, was with his grandfather yesterday and had a head-on collision MVA at about 60 mile per hour in single-lane highway. The patient was in the front passenger seat with his seatbelt on and airbags opened up. According to the parents, the car was totally destroyed. Grandfather suffered several fractures but did not lose his consciousness.

In the field, the patient was found pulseless, and bystander initiated CPR. At the patient was still pulseless, and CPR was continued, and the patient was intubated. His pH at that time was 7.01. CT of the head, spine and abdomen were all negative. Chest x-rays showed bilateral pulmonary contusion in the upper lobe, which later progressed to diffuse infiltrate. Pupils were fixed and dilated, nonresponsive. Glasgow score of 3 was given to the patient because of +3 blood in his urine. The patient was treated with Miochol, Decadron, Rocephindopamine and dobutamine.

FAMILY HISTORY: Diabetes and asthma.

SOCIAL HISTORY: The patient's development for his age was normal.

No known allergies.

Currently, he is on epinephrine IV, dopamine IV, and Decadron has been discontinued.

VITAL SIGNS: Weight 25 kg, temperature 35.6, pulse 164, blood pressure 76/33. GENERAL: The patient has no spontaneous movements and is intubated. Mental examination shows no response to pain or verbal stimuli, no spontaneous movement. EYES: Pupils are dilated between 6 and 7 mm bilaterally and nonreactive. FUNDUS: Within normal. Disks are sharp. Doll's eye was negative. Corneal reflex was negative. Cold

Page 1 of 2

caloric test with 60 cc of cold water at 30 degrees head-up was done on both sides of the ears without any nystagmus. EXTREMITIES: No spontaneous movement. Flaccid extremities. No response to pain. No reflex. BABINSKI'S: No response. HEENT: HEAD: Nontraumatic. NECK: soft and supple. Tympanic membranes bilaterally were red, unlikely to be blood. CARDIOVASCULAR: Tachycardia without any murmur. LUNGS: Clear to auscultation bilaterally without any wheezing. ABDOMEN: Bowel sounds present. Soft, no distention. There is a presence of belt contusion.

LABS: ABG: 7.24, pCO2 32, pO2 107. Saturation at 97%.

ASSESSMENT AND PLAN: The patient is a seven-year-old white male status post MVA, pulseless and in respiratory arrest at the field. Physical examination shows no response. Pupils are fixed and dilated at 6-7 mm and nonreactive. Cold caloric test shows no response. Doll's eye was negative. Corneal reflex was negative. CT scan of the head and abdomen were negative. Chest x-ray shows bilateral contusion.

On clinical examination, the patient no brain stem activity. We recommend an EEG to be done on this patient to evaluate for cerebral silence

This case was discussed with

D: 96 (3:13p)

T: 96

DATE OF OPERATION:

96

SURGEON(S):

PREOPERATIVE DIAGNOSIS: Rule out increased intracranial pressure secondary to obstructive hydrocephalus, secondary to massive brain edema.

POSTOPERATIVE DIAGNOSIS: Obstructive hydrocephalus.

OPERATION PERFORMED: Ventriculostomy.

ANESTHESIA: Local anesthesia with standby.

DETAILS OF OPERATION: The patient was brought to the operating room and placed on the operating table in the supine position. The patient's neurologic examination had previously been determined to be consistent with cerebral death. He had made some minimal spontaneous nonpurposeful movements which prompted consideration for intracranial pressure monitoring.

The patient was given a complete haircut. The head was then positioned on a jelly doughnut. The cranium was shaved, prepped with a povidene-iodine solution and draped in the usual fashion. A line of intended incision was outlined, which was just anterior to the coronal suture, approximately 2.5 to 3 cm right of the midline. Approximately 1.5 cc of 0.5% Xylocaine plus epinephrine was infiltrated in the scalp, after which a small incision was made. A twist drill hole was made and a Becker-type ventricular catheter was introduced into the right frontal horn on the first pass. The blood returned slightly blood tinged under a significant amount of pressure. The pressure was then measured with the manometer and was found to be greater than 350 mm of water pressure.

At this point, the ventricular catheter was tunneled beneath the scalp and the subgaleal space and brought out through a separate stab wound. The catheter was secured to the scalp, after which a dry sterile dressing was applied and secured with tape. A full head dressing was then applied to the wound. The patient was then transferred to the Pediatric Intensive Care Unit where he was to be connected to the cerebrospinal fluid collection system. The patient's condition remained unchanged throughout the procedure. The estimated blood loss was less

Page 1 of 2

BEST AVAILABLE

1996

than 5 cc. The sponge and needle counts were reported correct at the end of the procedure.

D: 96 (6:33P)

T: 96

Page 2 of 2

OPERATIVE REPORT